

Technical Service Bulletin



PSS 01 3.0TFSI Bank 2 engine misfires - Q8/Q7 (DCBD engine)

01 23 47 2054182/6 March 9, 2023. Supersedes Technical Service Bulletin Group 01 number 21-03 dated April 7, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8	2019 – 2022	All	Not Applicable
Q7	2020 – 2022		

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised released dates
5	4/7/2021	Revised title Revised header (Added MY21-22) Revised <i>Production Solution</i> (Updated estimate)
4	09/03/2020	Revised <i>Production Solution</i> (Updated estimate) Revised <i>Service</i> (Adjusted Steps and updated with software release)

This PSS only applies if all of the following conditions are met, see Figure 1 for an example:

- MIL on, MIL flashing, or misfires reported by customer.
- Misfire DTCs are stored for more than one cylinder on Bank 2.
- DTC ambient conditions show misfires occurring at or near the same timestamp.
- DTC ambient conditions show misfires occur while engine operating condition is “Leerlauf” (idle in German).
- DTC ambient conditions show misfires occur when the vehicle is at or near 0 km/h speed.
- The vehicle is NOT currently misfiring when examined in the workshop.

If all of the above criteria are not met, this PSS does not apply and the vehicle should be diagnosed using the normal GFF process.



```

DTC memory entry
Number: P030500: Cyl.5 Misfire
Error type 2: Detected
Symptom: passive/sporadic
Status: 10595
01100000

Standard ambient conditions:
Date: 12/2/18
Time: 2:42:42 PM
Mileage (DTC): 1771
Priority: 2
Frequency counter: 2
Elimination counter / driving cycle: 255

Expanded ambient conditions:
Engine speed 626.5 1/min
Normed load value 7.8431373 %
Vehicle speed 0 km/h
Coolant temperature 101 °C
Intake air temperature 23 °C
Ambient air pressure 970 mbar
Voltage terminal 30 13.1 V
20 96 27 10 7A 03 11 BD 0E 77
Dynamic environmental data 3E FC 05 12 16 03 1F 15 14 04
1B 60 00 02 10 10 01 6A
Unlearning counter according OBD 39
Engine status COENG_RUNNING
Param_TestProgrCoEngStCOMPUVERBUBYTE3
Engine oil temperature 97.16 °C
Engine operating condition Leerlauf
Param_TestProgrChann67 5
Relative load value 18.726562 %
Current system status SYNC_DRIVE
Param_TestProgrExeConState02UBYTE 4
Virtual_SlgXSet_TiOff_tStrtEnd_Off 2 s
Engine torque 36.2 Nm

DTC memory entry
Number: P030600: Cyl.6 Misfire
Error type 2: Detected
Symptom: passive/sporadic
Status: 10596
01100000

Standard ambient conditions:
Date: 12/2/18
Time: 2:42:42 PM
Mileage (DTC): 1771
Priority: 2
Frequency counter: 2
Elimination counter / driving cycle: 255

Expanded ambient conditions:
Engine speed 626.5 1/min
Normed load value 7.8431373 %
Vehicle speed 0 km/h
Coolant temperature 101 °C
Intake air temperature 23 °C
    
```

Figure 1. Example of applicable DTC.

Technical Background

Software calibration causing misfire under certain running conditions using winter blend fuel (higher vapor pressure). This condition would occur mostly during winter months.

Production Solution



Improved software in development pending 3rd quarter of 2023 release.

Service

1. If the customer's vehicle condition matches the condition listed in this PSS TSB, clear the DTCs and test drive the vehicle.
2. If no faults return after the test drive, explain to the customer that a solution is forthcoming in the 3rd quarter of 2023 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Access Audi (under *Related Links >> Service*).

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (**2054182**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.