

Published date: 02/28/2023

Preliminary Information

PIT5873G After A Remote Start When The Start Button Is Pressed The Engine May Stall or Will Not Restart / Ignition May Appear To Be Stuck On / Engine May Stay Running With Ignition Off / Service Column Lock Message / DTC P0E32 and P0E37/ Dead Battery

Proactive

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	11411511115510115.
Cadillac	Escalade Models	2022 - 2023	All	All	All	All
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 =A or D)	2022	All	All	All	All
Chevrolet	Silverado 1500	2023	All	All	All	All
Chevrolet	Suburban	2022 - 2023	All	All	All	All
Chevrolet	Tahoe	2022 - 2023	All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H or U)	2022	All	All	All	All
GMC	Sierra 1500	2023	All	All	All	All
GMC	Yukon Models	2022 - 2023	All	All	All	All

Involved Region or Country	North America, Uzbekistan, Middle East, Russia, Israel, Palestine, Bolivia, Chile, Colombia, Ecuador, Peru, Japan, Kazakhstan, Korea, Thailand
	Some customers may comment after using the remote vehicle start, either from the fob or app, they experienced any of the following issues:
	- When they enter the vehicle and press the start button the engine stalls
Canadition	- If they try to restart the engine, it will not crank
Condition	- If the remote start times out they are unable to restart the engine with the start button
	- When trying to turn engine off the engine stays running
	- Unable to turn the ignition off
	- Service Steering Column Lock Message, if equipped
	- Dead Battery
Cause	The cause of this concern is a BCM messaging issue.

Correction:

To correct this concern reprogram the BCM with the latest cals available in TLC/SPS following SI "K9 Body Control Module: Programming and Setup".

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage

Labor Operation	Description	Labor Time		
*2889288	K9 - Body Control Module Reprogramming with SPS for Remote Start Errors	0.5 Hr.		
Add	ONLY Use As Needed - Charge and Test Battery	0.2 Hr.		
*This is a unique Labor Operation for Bulletin use only.				

Additional SI Keywords

no RVS shut

Version History

Version	8
	12/08/2021 - Created on.
	03/01/2022 - Updates to the Condition, Correction and Warranty sections.
	03/23/2022 - Update to the correction and warranty sections
	06/06/2022 - Update to the Involved Region or Country
Modified	01/13/2023 - Update to title, models, condition, correction, and warranty
	sections
	02/10/2023 - Update to the Correction and warranty sections
	02/15/2023 - Update to the Correction and Warranty sections
	02/27/2023 - Update to the Correction section

















GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.