

Service Bulletin

Bulletin No.: 22-NA-140

Date: March, 2023

INFORMATION

Subject: Information On Rear Suspension Sag When Loaded with Equipment

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	mansinission.
Chevrolet	Tahoe	2021	2022				

Involved Region or Country	North America		
Additional Options (RPOs)	5W4: SALES PACKAGE-SPECIAL SERVICE, MUNICIPAL		
Condition	Some customers may comment on the rear suspension sagging.		
Cause	This condition may be caused by heavy equipment loaded the in cargo area overloading the suspension enough to sag at a point where the truck is lower in the rear.		
	Important: This is a customer pay repair.		
Information	A higher rate spring is available to provide more capacity for vehicles that are heavily loaded. Replace the right and left rear coil springs as deemed necessary.		

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Service Procedure

Refer to Coil Spring Replacement in SI.

Parts Information

Causa Part	Description	Part Number	Qty
Х	SPRING, RR COIL	84660652	2

Warranty Information

Important: Caution must be used to make sure the truck is not overloaded per the GVWR ratings label.

This is a customer pay repair.

Version	1
Modified	Released March 08, 2023