



Service Bulletin

Bulletin No.: 96-T-35D

Date: March, 2023

TECHNICAL

Subject: Odor from A/C at Vehicle Start-Up (Remove Debris from Evaporator Case, Disinfect Evaporator or Apply Cooling Coil Coating, and Install Delayed Blower Motor Control Module)

Models: 1996 Saturns and 1997 Saturns equipped with A/C built before and including the following vehicles:

This bulletin is being revised to update the Correction. This bulletin supersedes bulletin 96-T-35C, which should be discarded.

Model	Options	VIN No
Sedan/Coupe	Manual Trans. w/ABS	VZ270301
—	All Others	VZ271219
Wagon	Manual Trans. w/o ABS	VZ267540
—	Manual Trans. w/ABS	VZ270131
—	Automatic Trans.	VZ276754

Condition:

A musty odor from A/C system, most noticeable at vehicle start-up.

Cause:

An unpleasant (musty) odor from A/C outlets at vehicle start-up can be the result of microbial growth on the evaporator core. This bacteria feeds on the organic matter and moisture that is present on the evaporator core.

Correction:

Remove any debris from evaporator case; clean evaporator with disinfectant or apply cooling coil coating, and install delayed blower motor control module according to the following procedures.

Important: Before installing delayed blower motor control module, the following information **must be explained to the customer**.

- The delayed blower motor control module will not affect normal A/C or blower motor operation. However, the delayed blower motor control module will activate the blower motor on high speed for approximately five minutes. If the A/C compressor clutch has been continuously engaged for four minutes or more. The delayed blower motor control module will wait approximately fifty minutes after the ignition is turned Off before activating the blower motor. The blower run time reduces the amount of condensate on the evaporator core that may contribute to undesirable odors. The blower motor will be turned On with NO driver input if the conditions as stated above are met. The air rush sound created by the blower is noticeable from outside of the vehicle.
- The parasitic current draw of the delayed blower motor control module, combined with the blower motor load, will lower the state of charge of the vehicle's battery, and may negatively impact battery life depending on the driving habits of the customer.

A/C Evaporator Disinfecting/Cooling Coil Coating Application:

Depending on part availability, use A/C system disinfectant kit or cooling coil coating when performing this procedure.

Before starting procedures, obtain the following equipment and supplies:

- A/C System Disinfectant Kit P/N 21030784 or P/N 10953503 for Canada or Cooling Coil Coating P/N 12346390
- Cleaning gun, OTC Tool SA9216NE


Caution: When using Disinfectant Kit P/N 21030784, ordinary safety glasses are not sufficient.

- If using Disinfectant Kit P/N 21030784 or P/N 10953503 for Canada; safety goggles or face shield
- If using Disinfectant Kit P/N 21030784 or P/N 10953503 for Canada, National Institute of Occupational Safety and Health (NIOSH) approved acid gas/organic vapor respirator with chlorine dioxide cartridges 3M® P/N 5103–small, 5203–medium, 5303–large, which are to be used with a pre-filter P/N 5010 and retainer P/N 501, or equivalents
- If using Cooling Coil Coating P/N 12346390, safety glasses
- Rubber gloves
- Pedestal fan
- Plug P/N 21121827

1. Dry evaporator by:


- Adjusting temperature to full hot
- Turning RECIRC On
- Making sure A/C button is Off
- Close all doors and windows
- Start engine and allow to reach operating temperature.
- Allow blower motor to operate on HI blower for 5 minutes, once engine reaches operating temperature

2. Raise vehicle on a hoist.



880679


3. Check the HVAC module drain for blockage. If necessary, clear drain hole with a soft blunt tool such as the eraser end of a pencil.
4. Lower vehicle from hoist.



880462

5. To reduce the risk of debris from entering the HVAC module, check for gaps between cowl panel foam and windshield, at base of windshield. Repair gaps by repositioning panels or by removing cowl panels and installing additional foam to panel. Use Kent Industries P/N 40115 Adhesive Back Shim Stock or equivalent 5/16 x 3/8 inch foam.
6. Place a drain pan directly below the HVAC drain to collect disinfectant or cooling coil coating and rinse water runoff.

7. Open all doors and windows in the vehicle and position pedestal fan so that it provides cross ventilation through the vehicle during the cleaning/coating procedure.



859699


8. Cover interior of vehicle to protect it from spray.
 9. Disconnect blower motor and connector.
 10. Remove blower motor mounting screws and remove blower motor assembly.

Notice: Use care when removing debris from front of evaporator so no damage is done to the fins.

11. Check the HVAC module for debris through the blower motor opening. Remove any debris from evaporator face.
 12. Install blower motor and connect electrical connector.

Tighten

Tighten the blower motor mounting screws to 1.7 N•m (15 lb in).



880601

13. Using a 15/32 inch drill bit, attach a drill stop or depth gauge, or masking tape to allow for a 4 mm (5/32 in) depth.
 14. Locate the center of the triangle shaped portion of the plenum which slopes upward and to the right, next to the left-most blower motor fastener.

Notice: Running the drill bit in more than 4 mm (5/32 in) can damage the evaporator.

Important: Depending on part availability, two different products may be available for use on A/C evaporators. Select the appropriate procedure to follow based on the product you will be using:

- If using the disinfectant Kit P/N 21030784 or P/N 10953503 for Canada, continue to the "Evaporator Disinfecting Using Disinfectant Kit P/N 21030784 or P/N 10953503 for Canada" procedure in this bulletin.
- If using the Cooling Coil Coating P/N 12346390, continue to the "Applying Cooling Coil Coating (P/N 12346390) to Evaporator" procedure in this bulletin.

15. Drill a 15/32 inch hole. Be careful not to let the drill bit penetrate beyond a 4 mm (5/32 in) depth.


Evaporator Disinfecting Using Disinfecting Kit P/N 21030784; P/N 10953503 for Canada

Perform this procedure only if you are using A/C System Disinfectant Kit P/N 21030784 or P/N 10953503 for Canada.

Caution: This procedure should only be performed on a cold vehicle. It has been demonstrated that irritating vapors will be formed in the engine compartment if the disinfectant coming out of the drain outlet contacts hot engine components. Disinfectant can cause substantial, but temporary eye injury. Do not get disinfectant in eyes or on clothing. Wash thoroughly with soap and water after handling.


First Aid: If disinfectant gets into eyes, hold eyelids open and flush with a steady, gentle stream of water for 15 minutes. Obtain medical attention if irritation persists.

1. Allow vehicle to cool down before performing disinfectant procedure.
2. Put on rubber gloves, safety goggles and NIOSH approved acid gas/organic vapor respirator.
3. Pour the small bottle of the two part A/C System Disinfectant Kit P/N 21030784 or P/N 10953503 for Canada into the large bottle. Put the cap back on the large bottle and invert bottle once or twice to mix the contents.
4. Using clean gun, OTC Tool SA9216NE or equivalent siphon-type parts cleaning spray gun capable of delivering 2 ounces per minute of liquid with shop air at 552–620 kPa (80–90 psi), insert siphon hose into container of disinfectant. Take care to place the bottle in a secure upright position to avoid spilling contents.




880615

5. Insert nozzle tip of spray gun through the drilled hole and orient so spray pattern will be parallel to the evaporator face.



880608

6. With the blower motor on HI and engine Off, spray the entire contents of the disinfectant mix. Rotate the nozzle tip up and down while spraying disinfectant to allow for an even distribution and to ensure full coverage of the evaporator.
7. Turn blower motor Off.
8. Allow evaporator core to soak for at least 5 minutes.
9. With blower motor on HI, thoroughly rinse the evaporator core, using the above procedure with 1 quart of clean water to remove any disinfectant.



880618

10. Install hole plug P/N 21121827.
11. Properly dispose of disinfectant and rinse water runoff collected in drain pan into a sanitary drain.
12. Remove protective covering from interior of vehicle.

Important: Before enabling afterblow function, refer to “Customer Information” on page 2 of this bulletin and review operation of afterblow function with customer.

13. If the delayed blower motor control module is to be installed, proceed to “Delayed Blower Motor Control Module Installation” in this bulletin.


Applying Cooling Coil Coating P/N 12346390 to Evaporator

Perform this procedure only if you are using Cooling Coil Coating P/N 12346390.

Caution: Cooling coil coating can cause temporary eye injury. Do not get cooling coil coating in eyes or on clothing. Wash thoroughly with soap and water after handling.


First Aid: If cooling coil coating gets into eyes, hold eyelids open and flush with a steady stream of water for 15 minutes. Obtain medical attention if irritation persists.

1. Allow vehicle to cool down before performing cooling coil coating procedure
2. Put on rubber gloves and safety glasses.
3. Using cleaning gun, OTC Tool SA9216NE or equivalent siphon-type parts cleaning spray gun capable of delivering 2 ounces per minute of liquid with shop air at 552–620 kPa (80–90 psi), insert siphon hose into container of cooling coil coating. Take care to place the bottle in a secure upright position to avoid spilling contents.
4. Regulate shop air to 276–414 kPa (40–60 psi).




880618

5. Insert nozzle tip of spray gun through the drilled hole and orient so spray pattern will be parallel to the evaporator face.



880608

6. Apply cooling coil coating using short bursts and rotating the nozzle tip up and down. This will allow for an even distribution and to ensure full coverage of the evaporator.
7. Allow evaporator core to soak for 30 minutes.
8. Dry evaporator by:
 - Adjusting temperature to full hot
 - Turning RECIRC On
 - Making sure A/C button is Off
 - Open windows 1/2 inch and close doors
 - Start engine and allow to reach operating temperature
 - Allow blower motor to operate on HI blower for 5 minutes once engine reaches operating temperature.



880618

9. Install hole plug P/N 21121827.

10. Properly dispose of cooling coil coating runoff collected in drain pan into a sanitary drain.
11. Remove protective covering from interior of vehicle.

Important: Before enabling afterblow function, refer to “Customer Information” on page 2 of this bulletin and review operation of afterblow function with customer.

12. If the delayed blower motor control module is to be installed, proceed to “Delayed Blower Motor Control Module Installation” in this bulletin.


Delayed Blower Motor Control Module Installation

Important: Before proceeding with the installation of the delayed blower motor control module, make sure the customer is fully aware of its function and operation.

The following parts are required to install the delayed motor control module:

Part Description	P/N
Delayed Blower Motor Control Module Kit	21031158
Ring Terminal	12112245
Relay Kit	12167634

Important: On SL Sedans and SC1 Coupes, check the underhood junction block (UHJB) for a 30A power convenience (PWR CONVCE) fuse. If there is **no** 30A power convenience fuse, the underhood junction block **must be replaced with a new underhood junction block P/N 21023711 for 1996 vehicles or P/N 21021982 for 1997 vehicles**. If there is a 30A power convenience fuse, the underhood junction block does not need to be replaced.




878795

Caution: When performing service on or around SIR components or SIR wiring, follow the cautions and procedures in the appropriate year SIR service manual to temporarily disable the SIR system. Failure to follow


the disable procedures could result in possible air bag deployment, personal injury or otherwise unneeded SIR system repairs.

1. Disable the SIR system. Refer to “Disabling the SIR System” in the 1996 or 1997 “SIR Service Manual,” depending on model year of vehicle.
2. Record radio preset stations and disconnect negative battery cable.
3. Remove right and left console extension assemblies.



877980


4. Remove HVAC module lower trim panel.



878069


5. From passenger side of vehicle, wipe clean top center surface of heater duct.
6. Remove hook side of hook and loop retainer that is attached to delayed blower motor control module.

7. Peel backing off of hook side of hook and loop retainer and apply to top center of heater duct between two structure ribs. Press firmly to seat.
8. Install edge clip on electrical connector of delayed blower motor control module.
9. Using electrical tape, solid wrap delayed blower motor control module pigtail harness from electrical connector edge to delayed blower motor control module.




878066

10. From drivers side of vehicle:
 - 10.1. Insert delayed blower motor control module, with pigtail harness end first and hook and loop retainer down, into cavity above forward end of heater duct.
 - 10.2. Slide delayed blower motor control module in until rear edge is flush with heater duct edge on drivers side of vehicle.
 - 10.3. Press down on blower motor control module to engage hook and loop retainer. Delayed blower motor control module should fit securely if engagement of hook and loop retainer has been achieved.



878072


11. From passenger's side of vehicle:
 - 11.1. Route delayed blower motor control module pigtail harness between forward edge of heater duct and carpet.
 - 11.2. Attach delayed blower motor control module pigtail harness to the lower forward edge of the heater duct. Place clip as far forward as possible.



878106

12. Using black electrical tape, solid wrap 381 mm (15 in) of the delayed blower motor control module jumper harness, starting at electrical connector end.
13. Connect delayed blower motor control module jumper harness with delayed blower motor control module pigtail at heater duct.

14. Route delayed blower motor control module jumper harness under front heater duct, forward of rear heater duct, if equipped, to the I/P wiring harness on the drivers side of the vehicle.



880594

Notice: To prevent any possibility of a short circuit, replace any tape that is pushed back or removed from any wiring harness that is moved.

15. Disconnect black I/P harness connector and pull into drivers side footwell.


Important: For information on splicing wires, refer to "Wire Splicing" instructions in this bulletin.

16. Make the following splices. Refer to electrical wiring schematics on the following pages:
- 16.1. At terminal A4 of instrument panel junction block (IPJB) black 68-way connector, splice ORN wire from delayed blower motor control module into ORN wire, circuit 340L-battery feed, from 68-way connector.
 - 16.2. At terminal E10 of black 68-way connector, splice RED wire from delayed blower motor control module into BRN wire, circuit 641A-ignition from 68-way connector.


Important: High-blower relay kit is not included with delayed blower motor control module.

17. Install high-blower relay kit P/N 12167634 as follows:
- 17.1. At terminal D4 of IPJB black 68-way connector, locate PPL wire, circuit 65-blower motor, and cut wire 51 mm (2 in) from 68-way connector.
 - 17.2. Splice PPL wire from high-blower relay to length of PPL wire, circuit 65, that goes to I/P harness.
 - 17.3. Splice ORN wire from high-blower relay to length of PPL wire, circuit 65, that goes to IPJB 68-way connector.

- 17.4. At terminal A10 of IPJB black 68-way connector, splice RED wire from high-blower relay into RED wire, circuit 302-power convenience feed, from 68-way connector.
- 17.5. Splice ORN/BLK wire from high-blower relay to BLK/ORN wire from delayed blower motor control module.



18. Attach ring terminal lead wire kit P/N 12112245 to BLK/WHT wire from delayed blower motor control module and BLK/WHT wire from high-blower relay. Crimp both BLK/WHT wires together before attaching ring terminal lead kit.




878070

19. Attach ring terminal on the BLK/WHT wires from delayed blower motor control module and high-blower relay to ground location at H-brace. Make sure that new ring terminal is on top of existing ring terminal.


Tighten

Tighten the ring terminal-to-ground to 2.2 N•m (20 lb in).




878111

20. Position high-blower relay rearward in car so as to prevent any rattles, and tape to harness.
21. Disconnect PCM Lt. Blue 32-way connector.



882472

22. Using a 1.5 m (5 ft) length of .50 mm² (20 gauge) wire:
- 22.1. At terminal J1D01 of PCM Lt. Blue 32-way connector, splice one end wire to GRA wire, circuit 729-A/C relay control.
 - 22.2. Route wire to the IPJB as follows; Using electrical tape, spot tape wire to harnesses approximately every 51–76 mm (2–3 in):
 - Tape wire to PCM branch of I/P harness.
 - Follow harness up to I/P splice packs, forward of PCM.
 - From top of I/P, route wire along I/P harness, following the main branch across, forward of beam, and then down to IPJB. Route wire to the left of cruise control connector.
 - 22.3. Splice wire to WHT wire from delayed blower motor control module.
23. The BLU and TAN/ORN wires from the delayed blower motor control module are unused. Tape ends of BLU and TAN/ORN wires and tape back to jumper harness of delayed blower motor control module. The delayed blower motor control module GRN wire is used for testing.
24. Attach top half of “Notice” label provided in kit to blower motor cover. Attach bottom half of “Notice” label to inside of right side console extension assembly.
25. Connect black I/P harness connector. For SL Sedans and SCI Coupes **without** a 30A power convenience (PWR CONVCE) fuse, perform the following procedures to replace the underhood junction block (UHJB). For all other vehicles, proceed to step 46.




862790

26. Remove the battery hold-down retaining nut and screw, and lift off bracket assembly.

Caution: Do not tip battery over a 45 degree angle or acid could spill.

27. Lift the battery out of the vehicle, and place in a safe location.



865424

28. Remove air cleaner resonator retainer.
29. Remove air cleaner resonator.
30. Remove air cleaner assembly bolts and rotate upper half of air cleaner assembly toward rear of engine compartment.
31. Remove top cover from UHJB.
32. Remove battery positive cable bolt from UHJB and remove battery positive cable.
33. Remove bolts from UHJB.

34. Roll UHJB over and remove UHJB shield to gain access to UHJB connectors.
35. Remove connectors from UHJB.
36. Position new UHJB, P/N 21023711 for 1996 vehicles or P/N 21021982 for 1997 vehicles, inside engine compartment.
37. Install electrical connectors to UHJB.
38. Install shield to bottom of UHJB.
39. Position UHJB with the top facing up and install UHJB bolts.

Tighten

Tighten the UHJB mounting bolts to 9 N•m (81 lb in).

40. Position battery positive cable to UHJB and install bolt.

Tighten

Tighten the positive battery cable-to UHJB bolt to 4 N•m (44 lb in).

41. Install UHJB top cover.
42. Rotate air cleaner assembly back into position and install air cleaner assembly bolts.

Tighten


Tighten the air cleaner assembly bolts to 10 N•m (89 lb in).

43. Install air cleaner resonator and push in air cleaner resonator retainer.
44. Make sure battery tray is clean.
45. Install battery into the battery tray. Make sure that the battery terminals do not short against any metal during installation.
46. Connect negative battery cable.

Tighten

Tighten the battery cable to 17 N•m (13 lb ft).


47. Proceed to "Testing the Delayed Blower Motor Control Module" and verify operation. After operation is verified, proceed to next step.



877980

Important: Do not install parts that have been removed, except for black I/P harness and gray body harness connectors, until correct operation of the delayed blower motor control module has been verified.

48. Install HVAC module lower trim panel.



878795

49. Install right and left console extension assemblies.
50. Enable the SIR system. Refer to "Enabling the SIR System" in the 1996 or 1997 "SIR Service Manual," depending on vehicle year.
51. Set radio station presets.
52. Clear any SIR diagnostic trouble codes that may have set during delayed blower motor control module testing. Refer to the 1996 or 1997 "SIR Service Manual," depending on vehicle year.

Wire Splicing

With the wiring used in the Saturn vehicles, it is recommended that approved Packard Electric Crimp and Seal Splice Sleeves, or equivalent, be used.

Before you begin, determine proper sleeve for gauge of wire, then do the following:

	Salmon	Blue	Yellow
Wire Size	0.35, 0.50, 0.80	1.0, 2.0	3.0, 5.0
Gauge	22, 20, 18	16, 14	12, 10
Packard P/N*	12089189	12089190	12089191
Special Tool P/N**	217670	217671	217672


*Order through Packard at 1-800-PACKARD (1800-722-5273).

**Order through Saturn Special Tool Catalog. Included with Terminal Repair Kit SA9138Z.

Important: When using the salmon splice sleeve with 0.35 mm² (22 gauge) wire, remove 19 mm (3/4 in) of insulation. Bend the stripped portion in half to double

the thickness of the wire going into the splice sleeve. Twist the stripped, doubled wire and insert into the splice sleeve.


1. Remove insulation from both ends, recommended strip length is 9.5 mm (3/8 in). Caution must be used to prevent cutting the wire strands. Locate new splice a minimum of 40 mm (1 1/2 in) from an outlet or other splice.
2. Position stripped ends in sleeve until wires hit stop.



862507

Important: When splicing three wire ends into one splice sleeve, insert one cut wire end from vehicle harness and new splice wire end into one side of the splice sleeve until wires hit stop. Hand crimp using approved crimping tool. Insert remaining cut wire end from vehicle harness into other side of splice sleeve and crimp.

3. Hand crimp sleeve using the approved crimping tool. Gently tug on wires to make sure they are secure before applying heat to them.




862382

Caution: Do not use a match or open flame to apply heat to splice sleeve.

4. Apply heat using Ultratorch®, or equivalent, heating splice sleeve to 175°C (347°F). Heat until glue flows around edges of splice sleeve.
5. Check for continuity in the wire.

Testing the Delayed Blower Motor Control Module

A full functional check of the delayed blower motor control module is required to assure that all electrical connections are connected properly and it is functioning as designed.



878114

1. Locate the GRN wire at cavity H of the delayed blower motor control module and insert a Metri-pack 280 series male test adapter into cavity H until contact is made with GRN wire terminal in the delayed blower motor control module pigtail connector.

Important: Do not disconnect the jumper harness connector from the delayed blower motor control module pigtail connector or system test will not function.

2. Start engine and turn On A/C and verify that compressor clutch engages. With clutch engaged, apply battery voltage to the test adapter installed in step 1 above.

After 30 seconds, turn the ignition Off with voltage still applied to the test adapter. Approximately 10 seconds after the ignition is turned Off, the blower motor will run for one second if the delayed blower motor control module is wired correctly.

3. Disconnect voltage to the test adapter and remove adapter from connector.
4. If the delayed blower motor control runs for one second, go back to installation procedures and install parts removed from vehicle. If the delayed blower motor control module does not run for one second, go back to installation procedures and check all wiring connections. Refer to "Delayed Blower Motor Control Module Diagnosis" in this bulletin if functional check is not passed.

Delayed Blower Motor Control Module Diagnosis

Vehicle Running, High Blower Setting Does not Operate	
Cause	Solution
The high-blower relay is not properly installed.	Verify that ORN wire of high-blower relay is connected to PPL wire (circuit 65) coming from IPJB. Verify that PPL wire of high-blower relay is connected to PPL wire (circuit 65) connected to wire going to blower motor wire.

Blower Does Not Operate After Specified Delay Time (Make Sure That All Wires to Module Are Properly Connected. Use a Voltmeter to Check That the Proper Signal Is Applied to Each Wire.)	
Cause	Solution
(Test Mode Only) GRN test wire from delayed blower motor control module is not properly connected to vehicle battery source.	Connect jumper GRN test wire (pin H) to the vehicle's battery (not ignition).
Proper signal not received from A/C compressor.	Make sure A/C compressor is connected electrically. Secondly, use a voltmeter to verify that A/C is turned On.
A/C compressor was not in operation long enough to trigger delayed blower motor control module.	Start engine and turn On A/C. Make sure A/C compressor clutch is continuously engage for at least four minutes to trigger delayed blower motor control module. For test mode, run A/C for 30 seconds before turning Off engine.

Parts Requirements:

21031158	Module Kit — Delayed Blower Motor Control
12112245	Terminal — Ring
12167634	Kit — Relay
21023711	Block — Underhood Junction (1996 Vehicles)
21021982	Block — Underhood Junction (1997) Vehicles)
21030784	Kit — A/C Disinfectant P/N 10953503 for Canada
12346390	Coating — A/C EVAP Organic Growth Prev
21121827	Plug

Claim Information:

To receive credit for this repair during the warranty coverage period, submit a claim through the Saturn Dealer System as follows:

Case Type	Description	Labor Operation Code	Time
VW	Disinfect A/C System	T9555	1.3 hrs
VW	Disinfect A/C System and Install Delayed Motor Control Module.	T9709	3.5 hrs
Add:	To replace underhood junction block	—	0.6 hrs

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION