Technical Service Bulletin



91 Parking aid not working, DTC B107A16 (sym 233474)

90 23 15 2069678/1 March 15, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8 e quattro	2021		
A7 e quattro	2021 – 2022		
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron quattro, e-tron Sportback quattro, Q7, SQ7, Q8, SQ8, and RS Q8	2021 – 2023	All	Not Applicable
e-tron S quattro, e-tron GT, and RS e-tron GT	2022 – 2023		

Condition

Customer states:

The acoustic and optical parking aid does not work.

Workshop findings:

The following DTC may be stored in the driver assist systems control unit –J1121- (address word 00A5).

DTC B107A16 Voltage supply for parking aid sensor, voltage too low (symptom 233474).

Technical Background

A software related misdiagnosis may cause the DTC to enter erroneously.

Production Solution

Not Applicable

Service

Please erase the vehicle's DTCs.

Page 1 of 2

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



No repair is available at this time.

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. Instruct the customer that this condition is normal.

Workaround

- If the vehicle's driver assist control module -J1121- (address word 00A5) is older than SW 0381, please perform the software update in TSB 2069244.
- If the vehicle is already at SW 0381 or newer, the symptoms of this DTC should resolve themselves after an ignition cycle.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All part and service references provided in this TSB (2069678) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.