


Technical Service Bulletin



90 Audi drive select mode shown in instrument cluster does not match MMI display

90 23 20 2069778/1 March 23, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS 3	2023	All	Without Virtual Cockpit

Condition

Customer states:

- The Audi drive select mode shown on the MMI display differs from what is shown in the instrument cluster. For example, the Audi drive select mode "auto" is shown on the MMI display but "comfort" is shown in the instrument cluster.
- The Audi drive select mode shown on the MMI display is correct.

Technical Background

Software issue in the instrument cluster.

Production Solution

Optimized instrument cluster software 0318 is being introduced gradually in series production.

Service



Always use DoIP when flashing a control module via ODIS in supported vehicles.

To Activate DoIP, select *Administration>>General>>GFF Process>>DoIP communication>>Only allow DoIP communication*


This setting will automatically reset when the diagnostic session is ended.

You can tell if DoIP is active by observing a red LED on the VAS 6154(A)

This TSB Replaces Pending Service Solution (PSS) 2068655/1: *PSS 90 Instrument Cluster: Different drive select mode shown on the cluster compared to the MMI.*

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions.*
2. Update the instrument cluster (diagnostic address 0017) to software version 0318 with SVM code 17A046.
3. Start the update on the workshop tester by selecting "flash" and entering the specified SVM code. Follow the instructions on the tester

Technical Service Bulletin



Model	Software Part Number	Old Software Version	New Software Version	SVM Code Input
A3	8Y0 920 790 D	308, 310 314, 316	318	17A046

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 Up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9025		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 100 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2069778/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)

Additional Information

Technical Service Bulletin



All part and service references provided in this TSB (**2069778**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©**2023 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.