

WPA1 Workshop campaign - Reworking screw connections on brake lines

WPA1 Workshop campaign - Reworking screw connections on brake lines

ID Number	WPA1
Models	911 (992) 718 Boxster (982) 718 Cayman (982)
Model Years	2022 - 2023
VIN List	Attached
Number of Affected VINs	151
Issue Description	<p>On the affected vehicles, the brake line screw connection on the front and rear axles may not have been fully tightened to the prescribed final tightening torque.</p> <p>In this case, leakage in the brake system over the service life cannot be ruled out. The vehicles showed no leakage during factory testing. The brake system remains fully functional and the legally required minimum deceleration is maintained even in the event of a failure.</p> <p>For this reason, the screw connections of the brake lines on the front and rear axle must be checked and tightened to the specified final tightening torque or the brake lines replaced, depending on the test result.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting (3/17/23), the repair is immediately available.</p> <p>Parts can be ordered via PPL as needed.</p> <p>Please note that the expected replacement rate of the brake lines is 1% of vehicles.</p>

TI Number

No. 4-23

Required parts

No parts and materials are required for testing and reworking the screw connections.

The brake lines only have to be replaced in 1% of cases.

The required parts and materials for replacing the brake lines are listed in the Technical Information.

Warranty processing

Please note that each vehicle is assigned to precisely two campaign scopes.

For warranty processing, see Technical Information.

- Scopes 1 - 2: Checking and reworking screw connections on the brake lines
- Scopes 3 - 11: Replacing brake lines

Damage Code	WPA1 66 000
Repair Code	1/2
Labor time	85 - 190 TU

Please enter the campaign carried out in the warranty and maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [VIN_List_Report_WPA1_2023-03-17_V2.xlsx](#)