

# **QUALITY ACTION**

# CAMPAIGN BULLETIN HVAC Pipe Inspection

Reference: PC963

Date: March 30, 2023

#### Attention: Dealer Principal, Sales, Service & Parts Managers

Affected Models/Years:	Affected Population:		SERVICE COMM Activation date:	Stop Sale In Effect:
2023 Murano (Z52)	NA	483	March 30, 2023	YES

#### \*\*\*\*\*Dealer Announcement\*\*\*\*\*

Nissan is conducting a dealer inventory Quality Action to inspect the HVAC pipe, and if necessary replace the high-pressure flexible hose on specific MY2023 Nissan Murano vehicles identified in Service Comm and National Service History – Open Campaigns.

Due to a supplier issue that has since been corrected, the HVAC high-pressure flexible hose may not meet specification. This issue can potentially lead to a refrigerant leak and reduced cooling performance.

Affected vehicles **are subject** to stop sale and are either currently in dealer inventory or assigned and in transit to the dealer.

#### \*\*\*\*\*What Dealers Should Do\*\*\*\*\*

#### PLEASE FOLLOW THE ATTACHED INSPECTION INSTRUCTIONS:

- Verify if vehicles are affected by this quality action using Service Comm or DBS National Service History - Open Campaigns I.D. <u>PC963</u>
  - New vehicles in dealer inventory can also be identified using DBS (Sales-> Vehicle Inventory, and filter by Open Campaign).
    - Refer to NPSB 15-460 for additional information
  - Please continue to check newly arriving inventory for campaign applicability.
- 2. Please **do not drive, loan, sell or trade** the specific vehicles in dealer inventory subject to this quality action.
- 3. Use the attached procedure to remedy any vehicles affected by this quality action prior to sale.
- 4. Once remedied, dealers should submit the applicable warranty claim for the action performed so it can be closed in Service Comm and release the vehicle for sale.

## \*\*\*\*\* Dealer Responsibility \*\*\*\*\*

It is the dealer's responsibility to check Service Comm or DBS National Service History – Open Campaign using the appropriate campaign ID for the remedy status on each affected vehicle currently in new vehicle inventory.

#### NISSAN NORTH AMERICA, INC.

Total Customer Satisfaction



# PC963 - 2023 MURANO HVAC PIPE INSPECTION

#### **Service Procedure**

1. Open hood.

- 2. Locate the A/C high-pressure flexible hose, between the A/C compressor and the A/C condenser located near the upper radiator hose.
  - Locate the high pressure A/C pipe label




Figure 1

**NOTE:** A mirror may be needed to locate the lot code.

- 3. Write down the 5 digit lot code on the A/C pipe shown in Figure 2 and Figure 3.
  - ➤ If the lot code **IS** <u>6479M</u>, continue to Step 4 for High pressure A/C line.
  - ➤ If the lot code is **NOT** <u>6479M</u>, no further action is needed, close the hood and continue to claims information on last page.



Figure 2



Figure 3

1/3 PC963

# **High-Pressure Flexible Hose Replacement**

# **ACAUTION**

- Cap or wrap the joint of the pipe with suitable material such as vinyl tape to avoid the entry of air.
- Do not reuse O-rings.
- Apply A/C oil to the O-rings of the high-pressure flexible hose for installation.
- After charging the refrigerant, check for leaks.

- 4. Replace the high-pressure flexible hose.
  - Refer to the ESM section: VENTILATION, HEATER & AIR CONDITIONER HEATER & AIR CONDITIONING SYSTEM REMOVAL AND INSTALLATION COOLER PIPE AND HOSE HIGH-PRESSURE FLEXIBLE HOSE Removal and Installation Removal and Installation

2/3 PC963

## **Parts Information**

Part Number	Description	Qty
92490-5AA0A	HOSE - FLEXIBLE, HIGH (1)	1 (If Needed)

(1) Replacement hose contains New O-rings

# **Expense Code**

# Submit a "CM" line claim using the following claims coding:

Expense Code	Description	Amount Max	
123	R1234yf A/C Refrigerant	\$104.75 (1)	
124	PAG VC100YF Refrigerant Oil (2)	\$4.81 (3)	

- (1) One (1) lb. maximum.
- (2) For new O-ring lubrication ONLY.
- (3) ½ ounce maximum.

### **Claims Information**

# Submit a "CM" line claim using the following claims coding:

Campaign ("CM") ID	Description	Op code	FRT
PC963	Inspect High-pressure flexible hose - OK	PC9630	0.2 hr
	Inspect and replace High-pressure flexible hose	PC9631	2.0 hr

3/3 PC963