



Bulletin No.: PIT5872B
Published date: 03/23/2023

Preliminary Information

PIT5872B HUMMER EV Pop/Creak Type Noise While Sitting Stationary and Turning Steering Wheel With Brakes Applied

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Condition	A popping or creaking type noise may be heard inside the cabin if the customer has the brakes applied while turning the steering left or right. This type of maneuver should be avoided.
Cause	The noise is created due to a momentary slip-stick condition between the brake pads and rotors that is normal noise heard during steering wheel rotation with the vehicle stationary and the brakes applied. The noise can be heard from the front or rear suspension areas.

Correction:

Do not replace components for this noise as it is a normal characteristic.

Please educate the customer to avoid turning the steering wheel WHILE sitting stationary AND with the brakes applied.

Version History

Version	3
Modified	12/17/2021 - Created on. 01/18/2022 - Update to change model verbiage. 03/23/2023-Update to add 2023 Model Year

