

Preliminary Information

PIT5977B Device Is Starting Message On Radio - No Audio Then Loud Audio

<u>Proactive</u>

Product Investigation Review Required

<u>Models</u>

| _ | Model: | | Model Years: | VIN: | | | | |
|--|-----------|--|------------------------|-----------|-------|---------|----------------|--|
| Brand: | | | | from | to | Engine: | Transmissions: | |
| Chevrolet | Silverado | | 2022 - 2023 | All | All | All | All | |
| Chevrolet | Suburban | | 2022 - 2023 | All | All | All | All | |
| Chevrolet | Tahoe | | 2022 - 2023 | All | All | All | All | |
| GMC | Sierra | | 2022 - 2023 | All | All | All | All | |
| GMC | Yukon | | 2022 - 2023 | All | All | All | All | |
| GMC | Yukon XL | | 2022 - 2023 | All | All | All | All | |
| GMCYukon XLInvolved Region or CountryAdditional Options (RPO)Condition | | GME, GMIO, GMNA, GMSA and Holden. IOK Condition: Condition 1: Some customers may comment that audio goes to max at start-up or during the drive cycle AND the customer is able to adjust the volume back down WITHOUT a key cycle or system reboot. Condition 2: Customer may also comment about a "Device is starting" message that comes across the radio screen. Device is starting. Device is starting. These conditions may happen at the same time. | | | | | | |
| Course | | when the audio returns it is louder than before the incident. This may be caused by a software anomaly. | | | | | | |
| Cause | | This r | nay be caused by a sof | tware ano | maly. | | | |

Correction:

Condition 1: Engineering is aware of this condition. Do not replace the Radio. Dealers are to call into TAC for further direction.

Condition 2: Please refer to 23-NA-034 for available software fix

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time | | | |
|--|---|------------|--|--|--|
| 2889238 | Verify Max Audio Condition Verify Max Audio Condition | 0.2 Hr. | | | |
| *This is a unique Labor Operation for Bulletin use only. | | | | | |

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern.

Once a solution is available, this PI will be updated with additional details allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

Version History

| Version | 2 |
|----------|---|
| | 02/01/2023 - Created on. |
| Modified | 03/13/2023 - Updated correction section. |
| | 03/31/2023 - Updated correction and Admin details |



© 2023 General Motors. All Rights Reserved.