

ABS Brake Warning Light ON

Service Category Brake
 Brake Control/Dynamic
Section Control System

Market USA

Toyota Supports
 ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2016 - 2018	Prius V	

Introduction

Some 2016 – 2018 model year Prius V vehicles may exhibit a condition where the brake, ABS, and/or TRAC warning lights are on and/or a Check VSC message displays. One or more of the following Diagnostic Trouble Codes (DTCs) C1391, C1252, C1256, and/or C1253 will be stored in the vehicle's memory to be used as verification. This condition may be caused by a small brake fluid leak inside the brake booster assembly with master cylinder. Follow the Repair Procedure in this bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
BR1942	R & R Brake Booster Assembly With Master Cylinder and Brake Booster Pump Assembly	5.0	47050-#####*	8C	99

*Warranty claim MUST be submitted with the correct 10-digit OFP. Choose the correct OFP for the vehicle being repaired by searching for the parts in the Electronic Parts Catalog using the VIN filter.

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

ABS Brake Warning Light ON

Parts Information

MODEL YEAR	PART NUMBER		PART NAME	QTY
	PREVIOUS	NEW		
2016	47050-47360	04000-23876	Brake Booster Assembly With Master Cylinder	1
2017	47050-47361	04000-25147		
2018	47050-47760	04000-25247		
2016 – 2018	47070-12020	04006-22212	Pump Assy, Brake Booster	1

Required Tools & Equipment

REQUIRED TOOLS & MATERIAL	QUANTITY
DOT 3 Brake Fluid	1 – 2 liters

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream ADVI*	ADE	TSADVUNIT	1
Techstream 2.0		TS2UNIT	
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

*Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- GTS+ software version 2022.04.004.02 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

ABS Brake Warning Light ON

Repair Procedure

1. Confirm the condition exists.
Are the brake, ABS, and/or TRAC warning lights ON and/or does a Check VSC message display?
 - **YES** — Continue to step 2.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
2. Using Techstream, check for stored DTCs. Record ANY stored DTCs.
Are ANY of the following DTCs stored: C1391, C1252, C1256, and/or C1253?
 - **YES** — Continue to step 3.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
3. Remove the brake booster assembly with master cylinder.
Refer to TIS, applicable model and model year Repair Manual:
 - [2016](#) / [2017](#) / [2018](#) Prius V:
Brake – Brake System (Other) – “Brake System (Other): Brake Booster: Removal”
4. Remove the brake booster pump assembly.
Refer to TIS, applicable model and model year Repair Manual:
 - [2016](#) / [2017](#) / [2018](#) Prius V:
Brake – Brake System (Other) – “Brake System (Other): Brake Booster Pump: Removal”
5. Install the NEW brake booster assembly with master cylinder.
Refer to TIS, applicable model and model year Repair Manual:
 - [2016](#) / [2017](#) / [2018](#) Prius V:
Brake – Brake System (Other) – “Brake System (Other): Brake Booster: Installation”
6. Install the NEW brake booster pump assembly.
Refer to TIS, applicable model and model year Repair Manual:
 - [2016](#) / [2017](#) / [2018](#) Prius V:
Brake – Brake System (Other) – “Brake System (Other): Brake Booster Pump: Installation”
7. Using Techstream, clear ANY stored DTCs and test-drive the vehicle to confirm the condition is no longer present.