TECHNICAL INSTRUCTIONS

FOR

23TD03

DATA COMMUNICATION MODULE (DCM) REPROGRAM

CERTAIN 2022-2023 MODEL YEAR GR86

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently have completed all of the following courses:

• TIC206A – Electrical Repair 1

It is the dealership's responsibility to select technicians that have completed the above courses to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART

The flow chart is for reference only. *DO NOT* use it in place of the full technical instructions. Follow ALL steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



II. IDENTIFICATION OF AFFECTED VEHICLES

1. CHECK VEHICLE FOR CAMPAIGN ELIGIBILITY

- a) Compare the vehicles VIN to the VIN listed on the Repair Order to ensure they match.
- b) Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Campaign, and that it has not already been completed.

NOTICE:

TMNA warranty will not reimburse dealers for repairs completed on vehicles that are not affected or were previously completed, even by another dealer.

III. PREPARATION

A. TOOLS & EQUIPMENT

- T-SB-0134-16
 - T-SB-0107-20

- DCA-8000 Battery Diagnostic Station
- Techstream ADVi / Techstream 2.0 / Techstream Lite

IV. BACKGROUND



V. SAFETY PRECAUTIONS



CRITICAL INFORMATION - READ THOROUGHLY

An ECU could be damaged if an error occurs in the communication while reprogramming the ECU. Confirm all work is performed as described in these instructions.







1. STABILIZE THE POWER TO THE PERSONAL COMPUTER SIDE

a) Be sure to connect the personal computer to an external AC power supply.

NOTICE:

The ECU could be damaged if the battery voltage of the personal computer drops while reprogramming.

b) Turn off the screen saver and power saving mode of the personal computer so that the power to the hard disk is kept supplied.

NOTICE:

If the screen saver or power saving mode launches while reprogramming, the communication may be disconnected, resulting in the damage of the ECU.

c) **DO NOT** block the ventilation opening for the cooling fan of the personal computer.

NOTICE:

If the ventilation opening for the cooling fan is blocked with a sheet cover or the like, the personal computer may be heated excessively, causing the operation of the personal computer to stop. Due to the stop of the operation, the communication for reprogramming signals could be stopped, resulting in the damage of the ECU.

VI. TELEMATICS SYSTEM CALIBRATION ID VERIFICATION



Failed to send data to the server.

Would you like to try again

Yes

1. CHECK FOR DTC'S

a) Using a Techstream, perform a Health Check to check for any Diagnostic Trouble Codes.

NOTICE:

This Campaign covers only the software update to the Telematics System, as detailed in these instructions. It does not cover the diagnosis or replacement of any other systems on the vehicle.

NOTICE:

Before completing Health Check, "Send Vehicle Information" window may be displayed. If displayed, then click "Yes" to send the vehicle information.

• If "Failed to send data to the server" is displayed, click "No" to close the window and proceed to the next step.

2. CHECK CURRENT CALIBRATION

No

- a) Locate the Update column for the Telematics system in the Enhanced tab for this vehicle.
- b) Determine the status of an available update; indicated by a YES or NO.

HINT:

A

If the CID's indicate 'Yes', proceed with the update procedure.

R2204050007

System Select Stored	I Data Combinatio	n Meter Live	•	Cal Update									
2023 86 FA24	Tire Pressure /	Threshol	d \	/alue [psi(gauge)] [
	Sensor 1: 32.9	90 / 27.0	67	Sensor 2: 32.6	5/ 2	27.67							
Production Date	Sensor 3: 32.9	90 / 27.0	67	Sensor 4: 32.6	5/ 2	27.67							
- 7/2022	Sensor 5: N/	A/N	/Α							Camp	aign Stati	us: <u>CLOSE</u>	D
JF1ZNBC	Health Check R	esults									PERMAN	IENT: NO	
2023_86_FA24_J	- Health Check do	es not disp	olav	live data.				ECI	I Seci	urity Key: Refe	r to Rena	ir Manual	
File Notes	- Changes in vehicle condition will not update automatically.												
Health Check Deta 1 2/2	- To update Health Check, click the Refresh button on the bottom of the Health Check screen.												
Data 7-2/2													
Duiu 2-2/2	Enhanced Gene	ric											
		[DTC Re	ated Inf	ormatio	n						
	System	Monitor Status		DTC	Curr Conf	Pend	<u>Hist</u>	<u>Test</u> Failed	RoB	Calibration	Update	Configure	
	Airbag	-	*	B1661	Х				-	9118060002	No	No	
	Air Conditioner	-		B14A1				Х	-	-		No	
			\$	B224A	Х					-			
	Cockpit Control	-	988 100	B2258	X				-			No	
	Contraction		939 - 199	B2259	X					0000040004	N		
	Combination Meter	-	900 	B1502	X					000010004	INO	No	
	meter		807	B2A04	X					2400210440	Vos		
				B2A08	X					2400210440	165		
	Telematics			B2A09	Х								
	System	-		B2A0A	Х							No	
Sort				B2A0B	Х								
Evondas				U115B	Х			Х					
TIS Search	Reverse Automatic Braking	-	쑰	B2C22	х				-	-		No	~



CRITICAL MESSAGE

It is critical that T-SB-0134-20 and T-SB-0107-20 in addition to the Technical Instructions for this LSC are followed. This TSB outlines all steps necessary to prevent reprogramming failure. Toyota will not provide reimbursement coverage for reprogramming failures if this TSB is not followed. If you have a reprogramming failure that requires skid control ECU replacement and the Technical Instructions and TSB were followed correctly, please create a case with the Technical Assistance Hotline documenting all information related to the failure. If sufficient reporting is received related to re-flash failure, there will be consideration for reimbursement.

VII. VEHICLE PREPARATION

1. VEHICLE PREPARATION

- a) Confirm the following conditions:
- Vehicle in the IG position (engine off).
- Transaxle in Park.
- Parking brake engaged.
- Turn off all electrical accessories (i.e. climate control, audio system, etc.)
- Headlight switch in the DRL OFF position.
- Windshield wiper switch in the OFF position.

2. CONNECT THE 12V BATTERY TO A POWER SUPPLY (DCA-8000)

- a) Connect the DCA-8000 or other type of a power supply (not a battery charger) to the 12 V battery.
- b) Tap the Reflash icon from the Main Menu screen of the DCA-8000.

A power supply MUST be used during reprogramming. Please ensure DCA-8000 is connected and set to power supply mode. Voltage MUST be set to 13.5V.

Critical

Critical

•

Power supply must be connected directly to the 12v battery terminals and NOT the remote jump posts under the hood (if equipped).

***ECU damage will occur if the battery voltage is not properly maintained during this re-flash procedure.

3. VERIFY TECHSTREAM SETUP

- a) Verify that the Techstream meets the following conditions:
 - The latest version of software is loaded.
 - The Techstream battery is fully charged. If not, connect the Techstream to a 120 V source.
 - The DLCIII cable is in good condition.

The Techstream's battery voltage must also be maintained during the re-flash procedure. If necessary, plug the Techstream into a 120v outlet during this procedure.

***If the Techstream communication with the vehicle fails during the re-flash procedure, the telematics transceiver will be damaged.

4. CHECK AND RECORD THE SUBSCRIPTION STATUS

a) Check and record the subscription status:
 System Select -> Telematics System -> Data List -> Subscription Status

NOTICE:

Check and record the current Subscription Status as it may change after reprogramming.

VIII. UPDATE CALIBRATION

1. CONFIRM THE ECU CALIBRATION ID

a) Confirm the current calibration ID in the Telematics System.

System Select Stored Data Combination Meter Live Cal Update

														_
2023 86 FA24	Tire Pressure /	Thresho	٥ld	Value [psi(ga	uge)]	(
	Sensor 1: 32.	90 / 27	7.67	Sensor 2:	32.65 /	27	.67							
	Sensor 3: 32.	90 / 27	7.67	Sensor 4:	32.65 /	27	.67							
Production Date	Sensor 5: N		N/A								-			
- //2022											Campa	aign Stat	us: <u>CLOS</u>	ΞD
JF1ZNBC	Health Check F	Results										PERMAI	NENT: NO	
2023_86_FA24_J	Health Check de	oe not die	nla	ulivo data					ECI	1 800		r to Dona	ir Monuol	
File Notes	- Changes in vehi	cle condi	tion	will not undate	automa	tically			ECC	5 360	unty Key. Kele			
Health Checl	- To update Healt	h Check, d	click	the Refresh bu	tton on t	he bo	ttom o	f the He	alth Che	ck scr	een.			
Data 1-2/2		· · · · ·												
Data 2-2/2														
	Enhanced Gene	eric	_											
				DTO	C Relate	d Info	rmatio	n						
	System	Monitor Status	Π	DTC		urr onf	Pend	<u>Hist</u>	<u>Test</u> Failed	RoB	Calibration	Update	Configure	^
	Airbag	-	-	B1661		Х				-	9118060002	No	No	
	Air Conditioner	-		B14A1					Х	-	-		No	
			\$	B224A		Х					-			
	Cockpit Control	-	\$	B2258		Х				- I			No	
			\$	B2259		X							1	
	Combination		\$	B1502		Х					0000010004	No	Nie	
	Meter	-	\$	B1509		Х				•			INO	
				B2A04		Х					2400210440	Yes		
				B2A08		Х							1	
	Telematics			B2A09		Х							N.	
	System	-		B2A0A		Х				· ·			INO	
Sort				B2A0B		Х								
				U115B		Х			Х					
Expand>>	Reverse													
	Automatic	-	\$	B2C22		Х				-	-		No	
TIS Search	Braking													¥

The calibration IDs to re-flash in this campaign are as shown in the table below.

Medel	<u>Curatare</u>	Telematics Calibrations									
Model	System	Current Calibration ID	NEW Calibration ID								
GR86	Telematics	2400210440	4401210400								

NOTICE:

If the telematics system has the New CID's, no update is necessary.

2. REFLASH THE TELEMATICS TRANSCEIVER

a) Click yes on the health check results screen, or follow the links on the table above to begin the reflash process.

NOTICE:

Reflash failure should be extremely rare and can be avoided by following all instructions and reprogramming best practices.

HINT:

Even if the value of "Now processing. CAL 1" shows 100% please wait about 3 minutes before changing the display.

IX. COMPLETE REPAIR



2. CONFIRM CID UPDATE

- a) On the Stored Data tab, confirm the following for the Telematics System:
 - The Calibration number has the "New CID" number.

• The C	puale colum	11 11515		0								
System Select Stored	I Data Combinatio	n Meter Liv	e	Cal Update								
2023 86 FA24	Tire Pressure /	Threshol	ld V	/alue [psi(gauge)] 📑							
Production Date - 7/2022	Sensor 1: 32.9 Sensor 3: 32.9 Sensor 5: N/	90 / 27. 90 / 27. /A / N	.67 .67 I/A	Sensor 2: 32.6 Sensor 4: 32.6	51 51 2	27.67 27.67				Camp	aign Stat	us: CLOSED
JF1ZNBC16P8751159	Health Check R	esults									PERMAN	NENT: NO
2023_86_FA24_J File Notes ⊡ Health Checl Data 1-2/2	- Health Check do - Changes in vehi - To update Healtl	es not disp cle conditi h Check, c	play ion v lick	live data. will not update auto the Refresh button	omatical on the b	ly. ottom o	f the He	ECU alth Che	J Sec ck scr	urity Key: <mark>Refe</mark> ^{een.}	r to Repa	ir Manual
Data 2-2/2	Enhanced Generic DTC Related Information											
	System	Monitor Status	ÍT	DTC	Curr Conf	Pend	<u>Hist</u>	<u>Test</u> Failed	RoB	Calibration	Update	Configure ^
	Airbag	-	83	B1661	Х				-	9118060002	No	No
	Air Conditioner	-		B14A1				Х	-	-		No
			83	B224A	Х					-		
	Cockpit Control	-	63	B2258	Х				-			No
			\$3	B2259	Х							1
	Combination		쑰	B1502	Х					0000010004	No	No
	Meter	-	쑳	B1509	Х				-			NO
				B2A04	Х					4401210400	(No)	
				B2A08	Х							
	Telematics			B2A09	Х							No
	<u>System</u>	-		B2A0A	Х							NO
Sort				B2A0B	Х							
				U115B	Х			Х				
TIS Search	Reverse Automatic Braking	-	*	B2C22	х				-	-		No

Critical

Confirm the CID's has been updated successfully to the NEW CID's by someone other than the individual who performed the repair. Refer to p.6.

3. REMOVE THE POWER SUPPLY FROM THE BATTERY

4. DISCONNECT CABLE FROM NEGATIVE BATTERY TERMINAL

Refer to TIS for instructions on MAINTENANCE / FA24 BATTERY / REMOVAL

Critical

Make sure to wait for 1 minute after disconnecting the battery negative terminal, otherwise the Subscription Status may not be updated.

5. RECONNECT CABLE TO NEGATIVE BATTERY TERMINAL

Refer to TIS for instructions on MAINTENANCE / FA24 BATTERY / INSTALLATION

6. CHECK IF TELEMATICS SUBSCRIPTION STATUS IS UPDATED AFTER REFLASHING THE TELEMATICS TRANSCEIVER

- a) Check the subscription status: System Select -> Telematics System -> Data List -> Subscription Status
 b) Confirm the Subscription Status is the same as the status which was recorded before represented before repr
- b) Confirm the Subscription Status is the same as the status which was recorded before reprogramming.



7. PUT TELEMATICS TRANSCEIVER IN SLEEP MODE

- a) Turn the ACC On.
- b) Turn the IG Off.
- c) Open/close the driver-side door and then close all doors and hood.
- d) Check the map light assembly to see the LED light indicator of telematics system is off, and then leave it for 5 minutes.

8. PRINT CUSTOMER HEALTH CHECK REPORT

a) From the Stored Data tab, select the Customer Health Check Report button (TIS will launch when button is pressed).

NHE CARL The Pressure / Threshold Value (RPajaba) Control Senser 1: SGL19 / NA Senser 2: SGL19 / NA Senser 3: SGL19 / NA Senser 4: SGL19 / NA Senser 3: SGL19 / NA NA Senser 2: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / NA Senser 4: SGL19 / SGL186 - - - Senser 6: SGL19 /											(
State	918 C-HR 7R FAF	Tire Pressure / Threshold W	alue [kPa(abs)	0							ПГ			1.1				
Private System Status DTC Catt Fast Cattor Update Basit Explore Status DTC Catt Pend Hist Fast Cattoration Update Radio CA Radia Cuited -	0-00-200001 0010_C_HR_32R	Sensor 1: 368.19 / N/A : Sensor 3: 366.47 / N/A : Sensor 5: N/A / N/A Health Check Results Enhanced	Gensor 2: 368 Gensor 4: 368	1997 NG								Custm Check	er Hea Butto	alth n	1		1	
B Experiment Interment Interment Relater Crue Relater Crue Improvement Improvement Relater Crue Improvement Improvement Improvement	Health Ch	System	Monitor	DTC	Carr	Pend	Hist	Int	Calibration	Update *	III.	0	Dano		(÷) [=	LU	
Radar Crie Radar Crie	Engine	Engine	- Inc		5.010			- and -			ш.						- 11	
Nadok Cry Addr Cry Addr Cry Adviced Absorbert Stars Stars Successful Expendition Intelligion December Stars Successful Expendition Intelligi Intelligion Intelligion Intelligion Intelligion Intelligion Inte	Transmiss	Radar Cruise2									1U 🛏						_,	1
Radio Content - - - ABSVECT INSERT - - - ABSVECT INSERT - - - Steering Angle Sensor - - - Fore Thread Drive - - - Station - - - Base Content - - - Station -	Radar Cru	Transmission	-						**********	2	\sim						_	
Fore When Bars ABS/SC/TBAC/RPB - Frace/Feb33 Yee EBBY Sheema Angle Sensor - - Frace/Feb3 Yee For Whend Drive - - - - - - Star Angle Sensor - - - - - - - Star Angle Sensor -<	AREVSC/	Radar Cruise1	+ .						**********			7 /						
Extra S Steering Angle Sensor	E Four Whe	ABS/VSC/TRAC/EPB	+						F1526F4033	Yes								
B Air Conditions B Air Conditions B Air Conditions B Air Conditions B Air Conditions B LARADA B LARADADA B LARADA B LARADA B LARADA B LARADA B LA	EMPS	Steering Angle Sensor							*********	2		/						
s St3 Abda Pro Colinia Genetiane Standay C. Front Recognition Centera LKALDA Stat Door Noter Combination Refer Al: Confidenti Combination Refer Door Noter Poor Note Poor Noter Poor No	a Air Condit	Four Wheel Drive	+						**********	2 1	/ .	/						
Proc Conting C Fund Recognition Cameras Conting C Fund Recognition	 SRS Aliba 	EMPS							**********	1	/							
Constrait Front Recognition Camera - Air Conditionation Deter - LKALDA Air Conditionation Deter Bort Bort Expand->> Door Noter Door Noter - Diff Securit -	E Pre-Collie	LKALDA							*********	1/	/							
Front Noc - Source -	E Combinat Starting C	Eront Recognition Camera					-	-	**********	11								
Sott Combisation Meter Sott Main Body Expand>* Doors Nator Tis Sevent P. Door Mater	Front Rep	Air Conditioner	+						*********									
Bait Main Body	E LANCER -	Combination Meter					_		*********									
Expand->>	Sot	Main Body		1			_	_										
To Several P.Door Motor	Familia	D Door Motor	+						//									
15 Seed P.Door Motor	Columna.	Entry& Start	+ :															
	TIS Search	P.Door Motor							/ ·									
Per Contraction of the Contracti	Statement of the local division of the	100000000000000000000000000000000000000						-										
	Sot Expand>> 715 Search	Main Body D.Door Motor Entry&Start P.Door Motor	+ + +															

- b) Log in to TIS.
- c)
- Input Vehicle Mileage and Repair Order number. Check the "Performed" campaign button for campaign 23TD03. d)
- Select the Report button. e)

	Diagnostic Report
	Vehicle Information
	Mileage: 7787
	Repair Order: 77888
Our sy any of unsure	stems show the following campaigns are outstanding. Have these campaigns been completed? (Check for SSC door label if e.)
	XXX: Performed Not Performed Report
f) Confirm Customer Health	Check Report information is correct
g) Print Customer Health Che	eck Report from TIS.
h) Sign and provide to the cu	stomer.



✓ VERIFY REPAIR QUALITY ►

- Confirm the reflash completes successfully to the NEW CID.
- Confirm there are no DTCs in the Telematics System.
- Confirm the Subscription Status is the same as the status which was recorded before reprogramming.
- If you have any questions regarding this update, please contact your area representative.

X. APPENDIX

A. CAMPAIGN DESIGNATION DECODER