

<b>REFERENCE:</b>	<b>TSB:</b> 08-064-23 <b>GROUP</b> 08 - Electrical	<b>Date:</b>	February 28, 2023	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<p>2021 (DT) RAM 1500 Pickup                  2021 (DJ) RAM 2500 Pickup                  2021 (D2) RAM 3500 Pickup                  2021 (DD) RAM 3500 Cab Chassis                  2021 (DP) RAM 4500/5500 Cab Chassis                  2021 - 2022 (WK) Jeep Grand Cherokee                  2021 - 2022 (LA) Dodge Challenger                  2021 - 2022 (LD) Dodge Charger                  2021 - 2022 (LX) Chrysler 300                  2021 - 2022 (BV) Jeep Renegade                  2021 - 2023 (JL) Jeep Wrangler                  2021 - 2023 (JT) Jeep Gladiator                  2021 - 2023 (KL) Jeep Cherokee</p> <p>This bulletin applies to JT vehicles built on or before November 23, 2022 (MDH 1123XX) equipped with one of the following radios below:                  This bulletin applies to JL vehicles built on or before December 01, 2022 (MDH 1201XX) equipped with one of the following radios below:                  This bulletin applies to KL vehicles built on or before December 06, 2022 (MDH 1206XX) equipped with one of the following radios below:                  This bulletin applies to vehicles equipped with one of the following radios:</p> <ul style="list-style-type: none"> <li>• Uconnect 4C Nav With 8.4" Display Radio (Sales Codes UAV or UCV).</li> <li>• Uconnect 4C Nav With 8.4" Display Radio (Sales Codes UAQ or UCQ).</li> <li>• Uconnect 4C With 8.4" Display Radio (Sales Codes UAS or UCS).</li> </ul>	<b>MARKET APPLICABILITY:</b>			
		<input checked="" type="checkbox"/> NA		<input type="checkbox"/> MEA	
		<input type="checkbox"/> SA		<input type="checkbox"/> IAP	
		<input type="checkbox"/> EE		<input type="checkbox"/> CH	
<b>CUSTOMER SYMPTOM:</b>	<ul style="list-style-type: none"> <li>• Mobile Wi-Fi inoperative upon start up.</li> <li>• Hotspot gives "No Internet" connection message on phone, when trying to connect to a device.</li> </ul>				
<b>CAUSE:</b>	Radio Software				

**REPAIR SUMMARY:**

This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from QR39.7 to QR40.12.

**NOTE: National launch for this FOTA update is expected to begin March 10, 2023.**

**DISCUSSION:**

Vehicles sold in the U.S. and Canada can now receive software updates "over-the-air". Updates to software will occur in a phased roll-out. The software is updated through the built-in cellular modem in the radio.

Customers will see a notification on their radio screen when new software is available for their radio (Fig. 1). The owner will have the option to update the radio or schedule the update for later. **There is not an option to decline the update indefinitely, the update must be performed.**



Fig. 1

## Software Acceptance Screen

**NOTE:** If selecting “Schedule Update” the screen below will be displayed. The customer can select the exact time they want the update to begin (Fig. 2).



Fig. 2

## Schedule Update Screen

1. The vehicles transmission needs to be in the “Park” position, or have the vehicle in “Neutral” with parking brake engaged if equipped with a manual transmission. The ignition needs to be in the off position.

- Whether the customer selects “Update Now”, or “Schedule Update” (Fig. 2) and sets a time, they can shut off the vehicle and leave. The update will be completed automatically (Fig. 3) .

**NOTE: This step may take several minutes to complete.**




Fig. 3  
Update In Progress Screen

- Upon completion of update, the radio will display a confirmation message (Fig. 4) .



Fig. 4  
Update Confirmation Screen

**POLICY:**  
Information Only

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*