


Accord CAN Gateway Errors DTC U1803-88 and Code TT06

AFFECTED VEHICLES


Year	Model	Trim Level
2023	Accord	ALL
2023	Accord Hybrid	ALL

INTRODUCTION

Some customers are experience the following errors. The errors have no effect on the drivability or operation of the vehicle. In all trims the message **System update is not available. See your dealer** may appear in the gauge. When i-HDS is used to perform an All DTC Scan, the DTC U1803-88 will be returned.



In the Hybrid trims the audio unit may also display Code TT06



CAUSE

A software issue is causing an internal Ethernet error in the CAN Gateway Unit.

TEMPORARY COUNTERMEASURE

Service Information currently states to replace units. **For complaints matching the failure mode it is not necessary to replace the audio unit or the CAN Gateway Unit.**

To clear the code perform an All DTC Clear, then restart the OTA System using HDS: **System Selection Menu > CAN Gateway > Adjustment > Restart the OTA System.**

NOTE:

- Even after the code is cleared it is possible for it to return.
- **An OTA software update is in development to address the issue.**