


Exhaust Drone at Takeoff or Under Light Acceleration

Service

Category Engine/Hybrid System

Section Intake/Exhaust Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2016 - 2022	RX350	

SUPERSESSION NOTICE

The information contained in this bulletin supersedes Service Bulletin No. L-SB-0003-18.

• Applicability has been updated to include 2020 – 2022 model year RX 350 vehicles.

Service Bulletin No. L-SB-0003-18 is obsolete and any printed versions should be discarded.

Introduction

Some 2016 – 2022 model year RX 350 vehicles may exhibit a droning noise from the exhaust system at takeoff or under light acceleration. Countermeasure parts are available to reduce the droning noise. Follow the Repair Procedure in this bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG1708	R & R Exhaust Center Pipe Assembly	0.5	17420-####*	91	99

^{*}Warranty claim MUST be submitted with the correct 10-digit OFP. Choose the correct OFP for the vehicle being repaired by searching for the parts in the Electronic Parts Catalog using the VIN filter.

APPLICABLE WARRANTY

- This repair is covered under the Lexus Federal Long-Term Emission Warranty. This
 warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the
 vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

L-SB-0003-23 February 2, 2023 Page 2 of 7

Exhaust Drone at Takeoff or Under Light Acceleration

Parts Information

PART NUMBER		PART NAME	ОТУ
PREVIOUS	· · · · · · · · · · · · · · · · · · ·		QTY
17420-0P250 17420-31570	17420-0P540	Pipe Assy, Exhaust, Center	1
17451-0D140		Gasket, Exhaust Pipe	1
90917-A6001		Gasket, Exhaust Pipe, No. 2.	1

Required Tools & Equipment

REQUIRED TOOLS & MATERIALS	QTY
Vernier Caliper Gauge	1

Repair Procedure

1. Confirm the condition exists.

Does the vehicle exhibit a droning noise from the exhaust system at takeoff or under light acceleration?

- YES Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

L-SB-0003-23 February 2, 2023 Page 3 of 7

Exhaust Drone at Takeoff or Under Light Acceleration


Repair Procedure (continued)

 Confirm if the vehicle has the NEW center exhaust pipe. The NEW part can be identified by the addition of a bracket and damper attached to the center exhaust pipe as shown.

Does the vehicle have the NEW center exhaust pipe?

- YES This bulletin does NOT apply.
 Continue diagnosis using the applicable Repair Manual.
- NO Continue to step 3.

Figure 1.



1	Old Center Exhaust Pipe
2	New Center Exhaust Pipe
3	Bracket and Damper

L-SB-0003-23 February 2, 2023 Page 4 of 7

Exhaust Drone at Takeoff or Under Light Acceleration

Repair Procedure (continued)


3. Remove the center exhaust pipe assembly.

CAUTION

To prevent burns, do NOT touch the engine, exhaust pipe, or other high-temperature components while the engine is hot.

- A. Remove the two bolts and two compression springs to disconnect the center exhaust pipe assembly from the front No. 3 exhaust pipe sub-assembly.
- B. Remove the center exhaust pipe assembly from the two exhaust pipe supports.
- C. Remove the exhaust pipe gasket from the front No. 3 exhaust pipe sub-assembly.

Figure 2.



1	Compression Spring
2	Bolt

Exhaust Drone at Takeoff or Under Light Acceleration

Repair Procedure (continued)


4. Install the NEW center exhaust pipe assembly.

NOTICE

The flexible joint of the center exhaust pipe assembly may become deformed if subjected to extreme force.


- Do NOT bend the flexible joint.
- Do NOT hold the center exhaust pipe assembly by the flexible joint end.

Figure 3.



1	Flexible Joint
2	Do Not Bend

Figure 4.



1	Flexible Joint
2	Do Not Bend

L-SB-0003-23 February 2, 2023 Page 6 of 7

Exhaust Drone at Takeoff or Under Light Acceleration


Repair Procedure (continued)

A. Using a Vernier caliper gauge, measure the free length of the two compression springs.

STANDARD LENGTH	MINIMUM FREE LENGTH
43.0 mm (1.69 in.)	41.5 mm (1.63 in.)

If the free length is less than the minimum, replace the compression spring.

Figure 5.




- B. Temporarily install a NEW exhaust pipe gasket onto the front No. 3 exhaust pipe sub-assembly.
- C. Using a plastic hammer and wooden block, tap in the exhaust pipe gasket until its surface is flush with the front No. 3 exhaust pipe sub-assembly.

NOTICE

Be careful with the installation direction of the exhaust pipe gasket.

- Do NOT reuse the exhaust pipe gasket.
- Do NOT damage the exhaust pipe gasket.
- Do NOT push in the exhaust pipe gasket by using the exhaust pipes when connecting them.

Figure 6.



1	Front No. 3 Exhaust Pipe Sub-assembly
2	Exhaust Pipe Gasket
3	Wooden Block

L-SB-0003-23 February 2, 2023 Page 7 of 7

Exhaust Drone at Takeoff or Under Light Acceleration

Repair Procedure (continued)

D. Connect the center exhaust pipe assembly to the two exhaust pipe supports.


E. Install the center exhaust pipe assembly to the front No. 3 exhaust pipe sub-assembly with the two bolts and two compression springs.

Torque: 43 N*m (438 kgf*cm, 32 ft*lbf)

HINT

AFTER installation, check that the space between the flanges of the center exhaust pipe assembly and the front No. 3 exhaust pipe sub-assembly is consistent front-to-rear and left-to-right.

Figure 7.



1	Center Exhaust Pipe Assembly
2	Front No. 3 Exhaust Pipe Sub-assembly
3	Exhaust Pipe Gasket
4	Space Between Flanges: 8.5 mm (0.335 in.)

5. Confirm the droning noise is reduced.