

GROUP NUMBER

ENGINE ELECTRICAL 23-EE-006H

DATE MODEL(S)

**Technical Service Bulletin** 

**APRIL 2023** 

SONATA (DN8)

SUBJECT:

JE202 JOINT CONNECTOR REPAIR (P049D,P0405,P0489,P0191,P0507 AND/OR P240F)

**Description:** This bulletin provides the procedure to repair poor pin tension at joint connector JE202 in certain Sonata (2.5L GDI engine) with one or more DTC.

## **Applicable Vehicles:**

• All 2020-2023MY Sonata (DN8) equipped with 2.5L GDI Engine (VINs starting with 5NP)

#### **Parts Information:**

MODEL	PART NAME	РНОТО	QTY
Haisstronica Marine Grade Solder and Seal Connectors AWG 16-14	Locally obtained	AWG 16-14	3

### **Warranty Information:**

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSAL CODE
Sonata (DN8)	91201FJ2	Repair JE202	0.9 M/H	91410-L0063	I3T	ZZ3

**NOTE 1:** Normal Warranty applies.

NOTE 2: Include cost of AWG 16-14 in sublet as part of claim submission for reimbursement.

# JE202 JOINT CONNECTOR REPAIR

### **Service Procedure:**

1. Remove Engine Cover.

2. Disconnect Negative Battery Terminal and make note of customer radio presets to program back later.

\* NOTE

Tightening Torque 6.5 lb-ft

3. Disconnect both PCM Connectors.







TSB #: 23-EE-006H Page 2 of 3

- 4. Unclip Joint Connector JE202 from the Control Harness.
  - Trim the tape on the harness to allow for more wire.
  - Cut all wires going to JE202 as close to the Connector Body as possible as shown. (Discard the JE202 after wire cutting.)
  - Strip 3/8" of the insulation from all wires.
- 5. Using Solder and Seal Connectors, twist, install and splice circuits as stated below and shown on the right. Using a Micro Torch or Heat Gun, melt the solder in the connector and seal. Refer to Online ETM if additional information is required.
  - Connect all Red, Red/black wires together.
  - Connect all Orange, Orange/Black wires together.
  - Connect all White, White/Black wires together.


**NOTE:** Depending on vehicle options, there may be a different number if wires on JE202 that need to be spliced. Refer to online ETM if additional information is required.

# **△** CAUTION

Use caution when heating the connectors to prevent damage to the fuel line.

- 6. Using a Zip Tie, secure the repaired wiring to the Control Harness.
- 7. Reassemble in reverse order of disassembly.
- 8. Clear DTC's and Reset Adaptive Values.









TSB #: 23-EE-006H Page 3 of 3