

Published date: 04/4/2023

Preliminary Information

PIT5954B WIFI Hotspot Inoperative And OnStar Red LED And No Button Response After Remote Start With Keyfob

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions
			from	to	Engine:	Transmissions:
Cadillac	XT5	2020	All	All	All	All
Cadillac	XT6	2020	All	All	All	All
Chevrolet	Silverado	2020	All	All	All	All
Chevrolet	Traverse	2020	All	All	All	All
GMC	Sierra	2020	All	All	All	All
Involved Region or Country						

involved Region or Country	North America
Additional Options (RPO)	UE1, IOS, IOT
	Customers may comment that Wifi Hotspot is inoperative, and the OnStar has a red LED and no button response when using remote start feature from the keyfob.
	The cause of the concern is unknown at this time. Engineering is working to identify the root cause.

Correction:

Engineering is aware of the concern and working on the field fix.

The PI will be updated when a fix is made available. Until a fix is available, the concern can be temporarily corrected by turning off the ignition and then restarting the vehicle manually.

Do Not replace any parts at this time.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time	
3487638*	OnStar LED Red And Wifi Hotspot Inoperative After Remote Vehicle Start	.2 Hr.	
*This is a unique Labor Operation for Bulletin use only.			

Version History

Version	3
Modified	10/7/2022 - Created on.
	02/03/2023 - Updated to add 2020 Chevrolet Traverse
	04/04/2023 - Updated to add 2020 Cadillac XT5 & XT6



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.