GLOBAL SAFETY FIELD INVESTIGATIONS DCS6564 URGENT - DISTRIBUTE IMMEDIATELY

Date: May 15, 2023

Subject: N232397070 - Service Update

End Gate Cable

Models: 2023 GMC Sierra 1500

To: All General Motors Dealers

General Motors is releasing Service Update N232397070 today. The total number of U.S. vehicles involved is approximately 7. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated May 15, 2023. A Stock VIN list is not included as our records show there are no vehicles in dealer new inventory.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update

N232397070 Endgate Cable Incorrect Build



Release Date: May 2023 Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the

dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited

Warranty period.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
GMC	Sierra 1500	2023	2023				

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2023 model year GMC Sierra 1500 vehicles may have a condition in which the vehicle has the	
	incorrect endgate cable installed.	
Correction	Dealers are to replace the endgate cable.	

Parts

Quantity	Part Name	Part No.	
1	Pickup Box Endgate Cable	85146159	
1	Pickup Box Endgate Cable	85146160	


It is estimated that only 8 involved vehicles will require parts replaced. **Due to the small number of vehicles anticipated** that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Type	Item
9106812	Replace both Pickup Box Endgate Cables	0.4	ZFAT	N/A

Service Procedure



5028829

Note: Right side shown, left side similar.

1. Replace both the left and right Endgate Cables (2). Refer to Endgate Cable Replacement in SI.

Service Update

N232397070 Endgate Cable Incorrect Build



Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealer Reports - For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.