



TECHNICAL SERVICE BULLETIN

Active Air Dam System Fault See Manual Warning Message In IPC

23-2126

26 May 2023

Model:

Ford 2022-2023 F-150 Lightning
--

Issue: Some 2022-2023 F-150 Lightning vehicles may experience an Active Air Dam System Fault See Manual warning message in the instrument panel cluster (IPC). This may be due to the software level in the powertrain control module (PCM). To correct this condition, follow the Service Procedure to update the PCM to the latest software level via a coordinated flash.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2022-2023 F-150 Lightning
- Intermittent Active Air Dam System Fault See Manual warning message in IPC

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2022-2023 F-150 Lightning: Reprogram The Appropriate Modules As Required By The Software Update And Service Procedure (Do Not Use With Any Other Labor Operations)	MT232126	Actual Time

Repair/Claim Coding

Causal Part:	RECAL
Condition Code:	04

Service Procedure

1. Reprogram the PCM using the latest software level of the Ford Diagnosis and Repair System (FDRS). Follow all on-screen instructions carefully to complete all coordinated module software updates.

© 2023 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.