

### 97 Diagnostic tester does not communicate with vehicle via OBD socket - contacts widened

97 23 94 2070383/1 May 19, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4 allroad, A4, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, and RS 5 Sportback	2023	All	Not Applicable

# Condition

#### Workshop findings:

It is not possible to establish a connection between the vehicle and the diagnostic tester during the pre-delivery inspection.

Contacts on diagnostic connection U31 are damaged.

# **Technical Background**

Contacts on the diagnostic connection (OBD socket) may have been damaged in the production process.

# **Production Solution**


Improved production process.

### Service

#### Page 1 of 4

#### © 2023 Audi of America, Inc.

# **Technical Service Bulletin**



During PDI the diagnostic tester is unable to establish communication with the vehicle.

Pins within the OBD port U31 (Figure 1) may have been damaged in production.

Check contacts on diagnostic connection for damage.





Figure 1: OBD port (U31).



Repair the wires as needed using VAS 1978 B



Figure 2: Damaged pin.

### Warranty

Claim Type:

110 Up to 48 Months/50,000 Miles.

#### Page 2 of 4

#### $\ensuremath{\mathbb{C}}$ 2023 Audi of America, Inc.

# **Technical Service Bulletin**



	G10 for CPO Covered Vehicles – Verify C	Owner.	
	<ul> <li>If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
Service Number:	9709		
Damage Code:	0023		
Labor Operations:	Remove and install storage compartment under dash panel	6818 1900	See SRT with associated operations
	Check central wiring harness	9709 0199	10 TU
	Repair central wiring harness	9709 41xx	See SRT with associated operations
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2070383/1		

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

### **Required Parts and Tools**


Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Description	Quantity	
Individual wire 000979011E	As needed	
Crimp connectors 000979940	As needed	

Tool Number	Tool Description
VAS 1978 B	Wire harness repair set

# **Additional Information**

### Page 3 of 4

#### © 2023 Audi of America, Inc.



All parts and service references provided in this TSB (2070383) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

#### © 2023 Audi of America, Inc.

Page 4 of 4