

#### Subaru Service and Technical Support Line Newsletter



© 2023 Subaru of America, Inc. All rights reserved.

### Articles Contained in this Issue

*Click on a title below to jump to the article.* 

CODE	ARTICLEPAGE
(00)	STIS New Releases 14
(01)	QMR of the Month1-2
(01)	QMR of the Month Award
	Presentations2
(01)	Virtual Meeting Rooms3
(01)	Updating Technician Profiles for Techline
	Communications4-5
(07)	Installing Window Tint and Applying
(07)	Water Inside a Vehicle
(07)	• • • • •
	Water Inside a Vehicle (Brake lights stay on)5-6 Condensation in Headlights
	Water Inside a Vehicle (Brake lights stay on)5-6
	Water Inside a Vehicle (Brake lights stay on)5-6 Condensation in Headlights and Taillights
(12)	Water Inside a Vehicle (Brake lights stay on)5-6 Condensation in Headlights and Taillights
(12)	Water Inside a Vehicle (Brake lights stay on)5-6 Condensation in Headlights and Taillights
(12)	Water Inside a Vehicle (Brake lights stay on)5-6 Condensation in Headlights and Taillights

(20) Solterra Connect Telematics Diagnosis, DCM Activation & Registration......10-13

#### SUBARU TECHLINE HOLIDAYS & HOURS OF OPERATION

Memorial Day: (C Monday, May 29,	
Mon Thurs.	8:30AM - 7:30PM EST
Friday	10:30AM - 5:00PM EST
Saturday	9:00AM - 3:00PM EST

# **01** TechShare QMR of the Month

We are pleased to announce this month's TechShare QMR of the Month Winner:

# **Robbie Magill** from **Adventure Subaru** in Fayetteville, AR

We are pleased to announce this month's TechShare QMR of the Month Winner: Robbie Magill from Adventure Subaru in Fayetteville, AR

Robbie created a high quality QMR using TechShare reporting on customer's concern of defrost, heat and air shutting off when it is below freezing. Robbie's report included detailed diagnostic steps, high-quality photos, and videos.

Please refer to the following link to review the TechShare QMR in detail:

#### TS-227378

In appreciation for going the extra mile and sharing his experience with us, Robie will be receiving the following from his District Service Quality Manager:

### \$500.00 Snap-On gift card

#### CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

The Subaru TechTIPS newsletter is intended for use by professional Technicians ONLY. Articles are written to inform those Technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained Technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, D0 NOT assume that your vehicle has or will have that condition. Impreza, Legacy, Justy, Loyale, Outback, Forester, Subaru SVX, WRX, WRX STI, Baja, Tribeca, BRZ, XV Crosstrek, Ascent, Crosstrek Hybrid, Solterra and "Quality Driven" are Registered Trademarks. SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



Continued on the next page

# **01** QMR of the Month (CONTINUED)

The other Regional winners selected from QMRs submitted during February 2023 were:

- Christopher Taper from Subaru of South Hills
- Gerald Costa from Long Subaru
- Gregory Beach from Ramsey Subaru
- Jordan Steckel from Phil Long Glenwood Springs Subaru

Any Subaru Technician can participate in the TechShare QMR of the Month program. See the November 2022 issues of TechTIPS for full details. You just might see your name and photo in a future issue of TechTIPS!

## **01** QMR of the Month Award Presentations

As part of our "enhanced" QMR of the Month recognition program, we will include a photo (whenever available) of the recipient's award presentation in TIPS. The winner selected from QMR of the Month submissions received during February 2023 was Robbie Magill, Technician at Adventure Subaru, Fayetteville, AR.




Robbie is shown above (right/center) after being presented with his \$500.00 Snap-On Gift Card. To his right are Adventure Subaru's Service Manager Jake Wheeler, and Adventure Subaru's General Manager Brent Baker. To his left is Subaru of America's District Service and Quality Manager Chris Owen. Congratulations and **THANK YOU** to our February 2023 QMR of the Month Award recipient!

#### April 2023 TechTIPS

#### Virtual Meeting Rooms

Subaru is excited to announce the introduction of a new powerful tool for our technicians, the "Virtual Meeting Rooms". Click here to visit. This is a feature that allows a technician to either share the screen of an SSM laptop or Techline/ DSQM can take control to aid in diagnostics or data collection. When discussing cases with Techline and DSQM's, there may be situations when sharing the screen or taking control of the SSM laptop may be necessary. The scenarios where this could be useful are endless.



### If a technician is in situation where this could be useful, <u>understand this is a tool for Techline</u> and DSQM's and they will make the determination if this option will be used.

Should the situation require using this new tool, it is important to be prepared. For example, data should have all the required PIDs and appropriate flags. Verify the "<u>Microsoft Teams</u>" program is up to date, this feature will not work if the software is out of date. If "<u>Teams</u>" needs to be updated, call Nuspire to request they update the software before contacting Techline/DSQM's.

Some of the uses for this feature include immobilizer registration, work support functions, data review, module reprogramming, MAX data collection and more.

### Click here for directions on joining a Virtual Meeting Room.

#### Virtual Meeting Rooms

This page is for Retail Shop Technicians to join and engage in a shared Teams Meeting Room with a District Service Quality Manager or a Techline Representative, if required.

Call the Technical Service Support Helpline at 1-866-782-2782 if you would like to initiate a Teams meeting with a Representative.

If a Retail Shop Technician initiates contact with a Techline Representative or a DSQM and it is determined that joining a collaborative Teams Meeting Room is required, then the DSQM or Techline Rep will <u>activate</u> an available room listed below and will communicate to you which meeting room to join.

\* Please do not join a room without consulting a DSQM or Techline Representative first.

For instructions on how to join the meeting and share the screen on a SDS Toughbook click here.

If a Subaru Representative has designated a meeting room for the two of you to use and that link is not working, please call the Subaru IT Helpdesk at 1-800-SOA-STAR (762-7827).

Phila Zone Meeting Room 1

#### Continued on the next page

Page 3 of 16

# **01** Updating Technician Profiles for Techline Communications

### Please update the email address listed in Subarunet profiles.

Techline is now in full swing as we move into TechShare. Techline has already started to email Technicians as the newest form of communication. Techline has found that some long-term retailer Technicians have email addresses that are no longer valid or from a provider that no longer exists.

Techline has been utilizing email for retailers who are in poor cellular coverage areas, when providing additional resources (pictures and questionnaires) and focused communication directly to the Technician. We want to encourage this form of communication as an additional option to get the best information faster to the Technician.

If a Technician is not provided with a retailer email address, they can source their own from a variety of free online hosting sites that meet the retailer's established internet guidelines. Technicians should be mindful of their email address and avoid inappropriate content. When creating an account, first initial last name with a retailer number is recommended. An example is Msmith501101@gmail.com.

To update a Subarunet profile, please log in to Subarunet. In the top right-hand corner is a <u>blue circle</u> with the employee's initials. Select the drop-down menu and select <u>Update profile</u>.

Ξ.	SUBARU SUBARUNE	C Find	1131	4		~3	Retailer	name here (123456)	) [[]
A E	Communications Cathy Test Vehicle Inquiry 2022 Pilot	Parts Sales Sanice Incentives Warrances Connected Vehicle Marieting Subscu U		Jan 23 Feb 16 Jan 24	0	☆ ☆	VEHICLE S, A01911 DAILY Q	Test TestUser Dealer Sales Manager Dashboard Preferences Update Profile	
=	Announce Change			Jan 24	0		мтр <u>0</u>	Update Password	
	Test			Jan 23	0	\$	goal: O	Logout	ڻ ا
							0.0% Updated 2:39 PM	0.0%	
							opuniou 2.09 Pm		
	MMUNICATION CENTER . SEARCH					-	SALES RESULTS	RETAILER RANKINGS CH	0


From the next page, a retailer employee will be able to update their profile information. When finished, select <u>Update Profile</u> at the bottom right of the page to save the changes. **Techline does not share any personal contact information, this information will only be used to contact a retailer employee about a Techline case.** The system takes approximately five minutes to update to SOA.

Reminder, the Technician should have this email account web page open, or notifications turned on so that they see messages from Techline.


Groups Dealer General	Access Subarunet	
are required to locked fields, co	ntact your SOA Human Resources r	representative.
	Last Name	
M.I.	TestUser	Suffix
	Dealer General	Dealer General Subarunet

# **07** Installing Window Tint and Applying Water Inside a Vehicle (Brake lights stay on)

Techline has received reports of issues after installing aftermarket window tint on 2024 Crosstrek and Impreza. There have been reports of the brake lights staying on due to water intrusion. This may be due to the water application on the inside of the rear window glass during aftermarket window tint installation. When applying water to the inside of an open tailgate, the water may run down the inside of electrical harnesses. Extreme caution should always be taken when applying water to areas of a vehicle that are not intended to see water. This could cause corrosion inside connectors not equipped with weather pack or mildew and mold build up in areas that can hold or soak up moisture and not properly drain.



Should a '24 Crosstrek/Impreza come in with a concern of brake lights on all the time, inspect for window tint on the rear glass, and water intrusion in connector Db11.



As a reminder a vehicle should always be inspected for anything aftermarket. Aftermarket window tint may not seem like it could cause problems. However, similar water intrusion concerns directly connected to window tint installation have been seen from time to time when the water application is excessive during installation.


There has been an increase in replacement of exterior lamp assemblies due to condensation build up. This condensation often occurs due to a temperature differential caused by the seasonal temperature and the sun.

It is important to note that this is a normal condition and parts should not be replaced for this concern. It is more common to see this during late fall and early spring. TSB <u>07-59-07R</u> covers this topic and details the cause for this.




### From page 2 of TSB 07-59-07:

1) If a lamp is unevenly warmed by sunshine as shown in the illustration below, temperature of the area where the sun shines can be about 50° F higher than the other (cold) area. When air circulates inside the lamp, the warm air reacts to the cold surface resulting in formation of condensation.





2) If an already warm lamp lens gets cooled down rapidly (e.g. when water is applied to the lens during vehicle washing), a sudden temperature change can occur resulting in the development of condensation.




Continued on the next page Page 7 of 16

#### **15** Eyesight Camera Replacement and Programming U1C00, U01046, B28A2, B28A1, U1P07, U1P08, U1C07, U1C08

Techline continues to receive calls related to issues after replacing or swapping an Eyesight camera for testing. Any time a module is replaced in a vehicle it is critical to read and perform all the installation directions in STIS for that vehicle. **The programming needed varies depending on year and model.** If the correct installation and programming steps are not followed it is possible that there will be new DTC's after installing a new camera, calibration problems or the Eyesight disabled light illuminating.

For example, a 20MY Outback does not need to have the "Vehicle Information Registration – Parameter Selection" performed:



## Compare that to a 20MY Forester that does need the "Parameter Selection" input:

FORESTER PubNo.G82	70BE				
TOP Index	DTC Search	Wiring Diagram	Print	Search	SST
General Description   Engine   Suspe	nsion   Driveline/Axl	e   Brakes   Transmission	n/Transaxle   Stee	ring   Heater & Aircon	ditioner/Ventilator   Airbag
Body & Electrical/WIRING SYSTEM	2. VEHIC	LE INFORMATI	ON REGIS	TRATION	
LIGHTING SYSTEM	Perform v	when replacing ster	eo camera. (D	o not perform wh	hen performing stere
WIPER AND WASHER SYSTEMS					e of "Selection of Para
ENTERTAINMENT & MONITORING	PARAN	IETER SELECTION	4		
	Not				
COMMUNICATION SYSTEM		To check the ap If you entered a			odel number plate'
GLASS/WINDOWS/MIRRORS		n you entered a	i wrong appi	ied model, you	can re-write it.
BODY STRUCTURE		onnect the Subaru			
INSTRUMENTATION/DRIVER INFO		n [Start] screen, se n [Vebicle selection		-	ation and select [Conf
		n [Main Menu] scre			ition and select [Com
SEATS				, -	then select [Enter].
SECURITY AND LOCKS		n [Select Function]			
SUNROOF/T-TOP/CONVERTIBLE		n the work support		-	-
TOP (SUNROOF)					on the "Model numb and press the Enter
EXTERIOR/INTERIOR TRIM					entering the applied
EXTERIOR BODY PANELS	11.	When the confirma	tion screen in	dicating the vehic	cle information appea
CRUISE CONTROL SYSTEM		Note:			
POWER REAR GATE SYSTEM					option code are diff ing to option code i
			ecking the u	ight correspond	ing to option code i
EyeSight	Not	NETER CHECK			
General Description			a registered i	in the stereo ca	mera is shown on
Relay and Fuse					
EyeSight System		onnect the Subaru n [Start] screen, s			
Control Unit				-	on and select [Set].
Stereo Camera		n [Main Menu] scre			
Camera Adjustment, Inspection					then select [Enter].
PROCEDURE		n [Select Function]	-		
Switches and Harness		n the work support			arameter]. the applied model an
Combination Meter		-	-		nt vehicle are not dis
Stop Light & Brake Switch		Note:			
Roll Connector		Note that che	cking the dig	it correspondin	g to option code is
Multi-function Display (MFD)	3. AD1US	TMENT VALUE	CLEAR		
Diagnostics with Phenomenon	5. A0303		CLLAR (	t f 1	

When comparing the service manual between models, the steps that need to be followed are different. Always refer to STIS for the vehicle being repaired for all installation and programming steps required.

 Refer to the <u>July 2022 TechTIPS</u> that covers Gen 4 Eyesight programming. Gen 4 Eyesight is now included on multiple years and models. <u>The Eyesight camera needs to be registered</u>. Below is the July 2022 TechTIP:

#### **Eyesight Camera Replacement and Programming** 15 U1C00, U01046, B28A2, B28A1, U1P07, U1P08, U1C07, U1C08 (CONTINUED)

It is important to note that for vehicles equipped with Version 4 Eyesight and a Gateway Control Module, registration may be required during stereo camera replacement. Refer to the applied model installation process on STIS for complete instructions. Below is an example of instructions that include the registration process. The registration menu can be found under Immobilizer registration on the SSM. This must be completed before performing the camera adjustment and inspection procedure.

- Install the light assembly map. 
   Ref. to LIGHTING SYSTEM>Spot Map Light>INSTALLATION.
- 5. When the stereo camera has been replaced, perform the module registration. 🚳 Ref. to COMMON (DIAGNOSTICS)>Unit Registration>OPERATION.
- 6. Perform the adjustment or inspection of the stereo camera. ( Ref. to EyeSight>Camera Adjustment, Inspection.
- 1. On [Start] screen, select [Immobilizer etc. registration].
- 2. On [Select Registration] screen, select [Unit Registration (Update & Verification)].
- Then, when a message screen is displayed, follow the instructions on the screen.
- Techline has had situations where the technician has installed the camera but did not follow the correct steps for installation and programming. There is a chance the camera will now be stuck in a "loop", there is a DTC set, it cannot be cleared, but the calibration cannot be completed either. Refer to the final step listed at the bottom of the "Stereo Camera Adjustment, Inspection", below is an example of this. The "Camera Initialization" procedure will delete ALL data from the camera. All programming procedures will need to be completed as if the camera is "new out of the box". Always review STIS for the specific model being repaired as these directions may vary.

#### 7. CAMERA ALL INITIALIZATION

Caution

This is a recovery measures prepared for the data failure caused by the low battery voltage during data storage to inside the stereo camera Perform the procedure only when the stereo camera adjustment and inspection result is NG even if the vehicle parked position is normal as shown in the flowchart described in "Procedure". After camera all initialization, perform stereo camera adjustment and inspection in the same procedure as for the stereo camera replacement. @ Ref. to EveSight>Stereo Camera Adjustment, Inspection>PROCEDURE.

#### Do not usually perform camera initialization because it will clear the stereo camera adjustment and inspection data and/or diagnostic codes (DTCs).

- 1. Turn the ignition switch to ON and wait for approx. 10 seconds.
- 2. Using Subaru Select Monitor, perform [EyeSight All Initialization] in the [Work Support] of [EyeSight]. The [Contemport of [EyeSight]. The [Contemport of [EyeSight]] and the [EyeSight] and [EyeSight] and [EyeSight] and [EyeSight] and [EyeSight] and [EyeSight] and [EyeSight]] and [EyeSight] and [EyeSigh "Clear Adjustment Value", Vehicle information registration", Aiming" etc. according to "Service Manual". Do you really want to do it?] is displayed, select [Yes]. 4. When ["EyeSight all initialization" Processing Please wait,,,] is displayed, wait until it finishes.

5. ["EveSight all initialization" completed normally. 1) Please IG switch or key switch to OFF. 2) Wait for 5 seconds. 3) Click the OK button, exit SSM4.] is displayed after EveSight all initialization is successfully completed, select [OK] to exit. 6. Turn the ignition switch to OFF and wait for 5 seco

# IT IS CRITICAL TO READ AND FOLLOW ALL STEPS OF MODULE INSTALLATION LISTED IN THE SERVICE MANUAL

#### 20 Solterra Connect Telematics Diagnosis, DCM Activation & Registration

The Solterra Connect Telematics system does not function the same way as other Subaru STARLINK Telematics systems. This TechTIP will cover best practices to follow when servicing Solterra Telematics. The most important thing to remember is the importance of contacting Techline when encountering uncertainty or difficulty with Solterra Connect Telematics. We also want to remind Technicians that the best way to ensure they get the information they need to diagnose Solterra Telematics concerns efficiently is to complete QMR's with a high level of detail to ensure a steady flow of information to the field.

# **20** Solterra Connect Telematics Diagnosis, DCM Activation & Registration (CONTINUED)

The most significant difference with Solterra Telematics is that it is an opt-out, always-on Telematics service. Even when a customer is not subscribed and the satellite icon is not illuminated on the dash, the Technician can push the Solterra Connect button and reach an operator. Technicians should use this service, identify themselves as a retailer Technician testing Telematics operation and request the VIN and GPS location of the vehicle. Successfully connecting to an Operator and getting the requested information is an excellent first step for diagnosis or after a repair to confirm a correctly functioning Telematics system.

After completing a test call, Technicians must utilize the Global Tech Stream (GTS) "Health Check." This check provides much more data than the SSM4 all-system scan. Review the Health Check results by verifying there are no current Telematics or Infotainment DTCs, confirm that all modules are communicating and then review Telematics and Infotainment ROB data. Telematics operation in Solterra differs significantly from that of Starlink. Technicians applying Starlink operating and diagnostic principles to Solterra Connect Telematics will be quickly misled.

The Solterra service manual and the Technician Reference Books available on STIS are the Technicians most valuable tools when trying to diagnose Telematics and Infotainment concerns. As with any new resource, there is a learning curve to mastering its use. If a Technician has difficulty finding the information they are looking for, feel free to contact Techline or your DSQM for assistance.

There have already been Solterra DCM replacements performed by retailers. Initial analysis indicates that these DCMs were not the root cause of the customer concern. A review of the diagnostic method used by the Technicians indicates that Subaru STARLINK Telematics principles were utilized in the diagnosis. It took a lot of work for Technicians to find the information they needed to successfully diagnose the customer's concern.

One of the most critical pieces of information to find was the DCM Activation and Code registration procedures. These must be performed when installing a new DCM. Below are the steps to find this information for reference. Please note this is not an endorsement for DCM replacement but instead is presented as a lesson for the correct diagnostic and replacement methodologies regarding Solterra Connect Telematics.

After opening the Service Manual for Solterra, follow the click path shown below.

General→ SETUP → WHEN REPLACING OR... → WORK PROCEDURE

Scroll down to find "DCM (telematics transceiver)" in the listed parts.



>Results	Repair Manual	>NCF >E	WD BRM	
G6710BE ×				
<ul> <li>□ General</li> <li>■ INTRODUCTION</li> <li>□ SETUP</li> <li>■ WHEN DISCONNECTI</li> <li>□ WHEN REPLACING OF</li> </ul>		teering gear as:	sembly	
WORK PROCEDURE	Radio and display receiv	er assembly		
ECU CONFIGURATION	DCM (telematics transce	iver)		
🗄 🎨 CUSTOMIZE PARAME	Mobilephone battery			
<ul> <li>PREPARATION</li> <li>SPECIFICATIONS</li> <li>MAINTENANCE</li> <li>Engine / Hybrid System</li> <li>Drivetrain</li> </ul>	Clearance warning ECU a	assembly		
Select the li	inks to the right of " <b>DCM (t</b> o	elematics tran	sceiver)″	
PROCEDURES NECES ARY WHEN ECU OR OTHER PARTS ARE REP Replacement Part	PLACED Necessary Procedure	Effect/Inoperat	ive Function when Necessary Procedu Performed	Ire not Link
DCM (telematics transceiver)	DCM activation Code registration	Safety Connect System Telematics System		

# **DCM** Activation

CEI	LLULAR COMMUNICATION SAFETY CONNECT SYSTEM DCM ACTIVATION
D	CM ACTIVATION
a.	Enter the following menus: Body Electrical > Telematics > Utility
	Tester Display
	VIN Synchronization
	Execute
b.	According to the display on the GTS, read the IMEI, ICCID, software version and VIN.
c.	Turn the ignition switch off.
d.	Turn the ignition switch to ON and wait until only the manual (SOS) green indicator turns on. <b>HINT:</b> If only the manual (SOS) switch green indicator does not turn on even after 20 minutes elapse with the ignition switch ON, refer to "GREEN INDICATOR REMAINS OFF". Click here <u>Audio / Visual / Telematics&gt;CELLULAR COMMUNICATION&gt;SAFETY CONNECT SYSTEM&gt;GREEN INDICATOR REMAINS OFF</u>



	C	ode registrat	ion		
NOTICE: PRECAUTION WHEN REPLACING PA	ARTS	-			
<ul> <li>Code registration is necess</li> </ul>	ary when any of the following parts is r	eplaced with a new one. Af	ter replacing a part, any p	art that has performed regi	stration cannot be returned
<ul> <li>Certification ECU (smar</li> <li>ID code box (immobilis)</li> <li>Electrical key transmitte</li> <li>Main body ECU (multip)</li> <li>DCM (telematics transc</li> <li>Digital key ECU assemb</li> <li>BLE door digital key rec</li> <li>BLE luggage digital key re</li> <li>BLE indoor digital key re</li> <li>*1: w/ Remote Conn</li> <li>*2: w/ Digital Key S</li> </ul>	er code ECU) er sub-assembly ex network body ECU) eiver)*1 ly*2 eiver assembly*2 receiver assembly*2 eceiver assembly*2 hect Service				
Malfunctioning ECU	Condition	ECU code registration	ECU communication ID registration	Remote door lock and unlock registration*1	Remote start and stop registration*1
Refer to P	ROCEDURE	"7"	"8"	"9"	"10"
	When replacing a new one	-	-		
EV control ECU	When replacing a used one	-	•		
Main body ECU (multiplex network body ECU)	When replacing a new one		-		-
DCM (telematics transceiver)*1	When replacing a new one	-	-		
BLE indoor digital key receiver assembly"2	When replacing a new one		-	-	-
DLE muon uigitai key receiver assembly~2	When replacing a used one		-	-	-

The Code registration chart shown above indicates that registration procedure "9" and "10" need to be completed when installing a new DCM. Continue to scroll down to find those procedures.

HINT: After completing the registered work to vehicle, it is	required to turn the vehicle connection setting to ON with the Smartphone Application.	
Process	Procedure	
1. Start of registration	<ol> <li>Ignition switch off.</li> <li>Connect the GTS to the DLC3.</li> <li>Turn the ignition switch to ON.</li> <li>Turn the GTS on.</li> <li>Enter the following menus: Body Electrical / Telematics / Utility / Remote Door Lock Setting.</li> </ol>	
2. Registration of remote door lock and unlock	1. Perform operation according to prompts on the GTS screen	
3. End of registration	Finish remote door lock and unlock registration.	
10.REMOTE START AND STOP REGISTRAT	ION	
	required to turn the vehicle connection setting to ON with the Smartphone Application.	
	required to turn the vehicle connection setting to ON with the Smartphone Application.  Procedure	
After completing the registered work to vehicle, it is Process	Procedure  1. Ignition switch off, 2. Connect the GTS to the DLC3, 3. Turn the ignition switch to ON. 4. Turn the GTS on.	

ITEM CODE	ITEM TYPE	TITLE	CREATED DATE
17-18-23	Accessory Installation Guide	Air Bag Curtain Module Mountin	8-May-23
12-249-23	Technical Service Bulletin	Cleaning of Painted Surfaces A	5-May-23
15-282-21R	Technical Service Bulletin	STARLINK Remote Engine Start (	4-May-23
07-210-22R	Technical Service Bulletin	Hybrid Battery / High Ambient	4-May-23
07-209-22R	Technical Service Bulletin	EyeSight® Reprogramming DTC B2	4-May-23
15-256-19R	Technical Service Bulletin	FOTA (Firmware Over-The-Air) R	2-May-23
TKC-20R	Subaru Product/Campaign Bulletin	Takata Front Passenger Airbag	2-May-23
TKB-20R	Subaru Product/Campaign Bulletin	Takata Front Passenger Airbag	2-May-23
TKA-20R	Subaru Product/Campaign Bulletin	Takata Front Passenger Airbag	2-May-23
F0010FN000	Accessory Installation Guide	2024MY Crosstrek - Window Defl	2-May-23
L101SXC005	Accessory Installation Guide	2019MY Ascent - Trailer Hitch	2-May-23
15-247-19R	Technical Service Bulletin	Harman Navigation "Route Calcu	2-May-23
WRC-23	Subaru Product/Campaign Bulletin	VDC control module reprogrammi	2-May-23
WRD-23R	Subaru Product/Campaign Bulletin	12V Inverter Connector Corrosi	2-May-23
16-132-20R	Technical Service Bulletin	Diagnostic Information for All	27-Apr-23
15-308-23	Technical Service Bulletin	Diagnostic Information - Testi	27-Apr-23
15-305-22R	Technical Service Bulletin	Reprogramming File Availabilit	26-Apr-23
15-293-22	Technical Service Bulletin	Remote Climate Control Operati	26-Apr-23
16-140-23	Technical Service Bulletin	Judder Concern During Low-Spee	26-Apr-23
TIPS0522	TechTIPS NewsLetter	2022 May TechTIPS Newsletter	26-Apr-23
WRI-23	Subaru Product/Campaign Bulletin	Safety Recall/STOP SALE – Stop	26-Apr-23
11-204-23	Technical Service Bulletin	PCV Hose Design Change / Odor	25-Apr-23
L101SXC005	Accessory Installation Guide	2019MY Ascent - Trailer Hitch	25-Apr-23
H001SAN001	Accessory Installation Guide	2020MY+ Legacy / Outback Remot	25-Apr-23
J501SFN250	Accessory Installation Guide	2024MY Crosstrek Wilderness	25-Apr-23
F541SFN000	Accessory Installation Guide	2024MY Crosstrek - Moonroof Ai	25-Apr-23
S0A843X036	Accessory Installation Guide	2024MY+ Crosstrek - Adjustable	25-Apr-23
S0A843X036	Accessory Installation Guide	2024MY+ Crosstrek - Adjustable	25-Apr-23
S0A843X026	Accessory Installation Guide	2022-23MY WRX - Fixed Cross Ba	25-Apr-23
S0A843X026	Accessory Installation Guide	2022-23MY WRX - Fixed Cross Ba	25-Apr-23
L101SFN000	Accessory Installation Guide	24MY Crosstrek (all Trims) - T	25-Apr-23
L101SFN000	Accessory Installation Guide	24MY Crosstrek (all Trims) - T	25-Apr-23
J131SXC000	Accessory Installation Guide	2019-24MY ASCENT DOOR SCUFF PR	25-Apr-23
	Service Diagnostics	2024 Legacy/Outback Service Ma	24-Apr-23

# All revised publications are highlighted in yellow.

ITEM CODE	ITEM TYPE	TITLE	CREATED DATE
H1010FN210	Accessory Installation Guide	2024MY Impreza/Crosstrek Wirel	24-Apr-23
H1010FN200	Accessory Installation Guide	2024MY Impreza//Crosstrek - Wi	24-Apr-23
15-307-23R	Technical Service Bulletin	Discontinuation of SUBARU STAR	24-Apr-23
15-309-23	Technical Service Bulletin	Procedure for Infotainment Con	24-Apr-23
WRB-23R	Subaru Product/Campaign Bulletin	Telematics Data Communications	20-Apr-23
15-304-22R	Technical Service Bulletin	Procedure for Techline Infotai	19-Apr-23
F6010FN000_0M	Owner Manual	2024MY Crosstrek and Impreza R	18-Apr-23

All revised publications are highlighted in yellow.

# \*\*\* Now you can e-mail your TechTIPS input and suggestions to: tech@subaru.com \*\*\*

This is your chance to offer suggestions for use in future issues of TechTIPS! Make sure that if you e-mail us, you place in the subject line of your e-mail "For TechTIPS Newsletter". Thank you!
Model:
Year:
VIN:
Description of situation encountered:
Your suggestion for repair procedure, product improvements, etc.:
Please attach separate sheets, if necessary. You may also want to include Service Manual diagrams or references, or your own drawings to assist in describing your suggestion. All information submitted becomes the property of Subaru of America, Inc. Permission is granted to Subaru of America, Inc. to print your name and suggestions in TechTIPS and other Subaru of America, Inc. publications. Mail items to: PO Box 9103; Camden, NJ 08101-9877.
Your Name:
Signature:
Dealer's Name:
City:
Date:
Dealer Code:



Monday – Thursday 8:30 am to 7:30 pm Friday 10:30 am to 5 pm and Saturday 9 am to 3 pm