

APAO - Re-Programming DME and Transmission Control Units (Recall Campaign)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Year: **2016**

Model Line: **911 GT3 RS (991)**

Concerns: **DME control unit**

Information: **During internal tests, Porsche has discovered that exhaust emissions can be increased under certain driving conditions in Sport+ mode on the 991 GT3 RS model.**

Action required: Re-program the DME and transmission control units using the PIWIS Tester with software version **41.900.020** (or higher) installed.



Information

During programming, the DME control unit and the PDK control unit are **automatically** programmed and then coded.

It takes **approx. 15 minutes** in total to **program and code** both control units.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Required tools

- Tool:
- **9900 - PIWIS Tester 3 / 4** with PIWIS Tester software version **41.900.0200** (or higher) installed
 - Battery charger with a current rating of **at least 90A**, e.g. **VAS 5908 battery charger 90A**

Re-programming DME control unit

Work Procedure: 1 Carry out general preliminary work for control unit programming as described in ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*.

2 Re-program DME control unit.

The basic procedure for control unit programming is described in the Workshop Manual ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*.

For specific information on control unit programming during this campaign, see table below.

Required PIWIS Tester software version:	41.900.020 (or higher)
Type of control unit programming:	Control unit programming using the ' Automatic programming ' function of the DME control unit: 'DME' control unit – ' Coding / programming ' menu – ' Automatic programming ' function.
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the DME control unit is re-programmed first, depending on the model year the instrument cluster and then the PDK control unit is re-programmed. Both control units are then automatically re-coded . Do not interrupt programming and coding. Once the control units have been programmed and coded, you will be prompted to switch the ignition off and then back on again after a certain waiting time. Backup documentation of the new software versions is then performed.
The programming sequence takes (approx.):	15 minutes
Software version programmed as part of this campaign:	See ⇒ <i>Technical Information '9X00IN Warranty processing'</i> section

<p>Procedure in the event of a termination of control unit programming:</p>	<ul style="list-style-type: none"> • Switch ignition off and then on again. • Read out and delete the fault memories ⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - "Rework" section'</i>. • Repeat control unit programming by restarting programming.
<p>Procedure in the event of other error messages appearing during the programming sequence:</p>	<p>⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Fault finding"</i></p>

- 3 Select the **DME** control unit in the **Overview**.
- 4 Select **Maintenance/repairs**. Press •F12" to continue.
- 5 Select **Throttle valve adaptation**. Press •F12" to continue.
- 6 Function selected. Press •F12" to continue.
- 7 Adapt function. Press •F8" to start.
Perform adaptation according to menu guidance. End adaptation with •F8" .
- 8 Read out all **fault memories**, process and delete existing faults if necessary.



Information

If control units are found to have faults that are **not** caused by control unit programming, these must first be **found and corrected**. This work **cannot** be invoiced under the workshop campaign number.

- 9 Exit the diagnostic application.
- 10 Switch off ignition.
- 11 Disconnect the Tester from the vehicle.
- 12 Switch off and disconnect the battery charger.
- 13 Enter the campaign in the Warranty and Maintenance booklet.
For warranty processing, see the Section ⇒ *Technical Information '9X00IN Warranty processing'*

Software overview

911 (991):

Type	Model year	Software part number	Software version
911 (GT3 RS)	2016	DME 99161866204	DME 3143
		Transmission 99161839405	Transmission Q061

Warranty processingScope: **Re-programming DME control unit**

<p>Labor time:</p> <p>Re-programming DME control unit</p> <p>Includes: Connecting and disconnecting battery charger Connecting and disconnecting PIWIS Tester Re-programming PDK control unit Perform throttle valve adaptation Reading out and deleting fault memories</p> <p>⇒ Damage Code APA0 099 000 1</p>	<p>Labor time: 71 TU</p>
---	---------------------------------

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2023 Porsche Cars North America, Inc.