

# Technical Service Bulletin



## 40 Active Roll stabilization: DTC C129700 logged in address 00D4 and/or 00D5

40 23 58 2067804/2 May 25, 2023. Supersedes Technical Service Bulletin Group 40 number 22-47 dated August 18, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 – 2023	All	Dynamic Ride Control
Q8	2019 - 2023		
SQ7, SQ8, and RS Q8	2020 - 2023		

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model Year)
1	08/18/2022	Initial publication

### Customer states:

The message “Air suspension fault” and/or a message concerning the “roll stabilization/suspension” is shown in the instrument cluster.

### Workshop findings:

The following DTC is logged in one of the two roll stabilizer control units J924 or J1096 (*diagnostic address 00D4 or 00D5*):

- **C129700** (symptom code **12664851**) Function limitation due to malfunction in the control module.

## Technical Background

Not Applicable

## Production Solution

Not Applicable

## Service

# Technical Service Bulletin



If no further relevant DTCs relating to the suspension and/or roll stabilization are logged, please perform the following steps:

- Unplug the diagnostic connector from the vehicle.
- Switch off the ignition.
- Lock the vehicle (doors, hood, and rear lid closed).
- Wait until the vehicle has entered bus sleep mode.
- Unlock the vehicle.
- Plug the diagnostic connector into the vehicle.
- Switch on the ignition.
- Attempt to erase the DTCs.
- Then perform the step “Replace Control Module” on both roll stabilization control units J924 and J1096 with the ODIS tester (**but do not replace the control unit**).

**If the DTC in question is still logged, follow the instructions in Guided Fault Finding to solve the issue. If there are no DTCs stored, release the vehicle.**

## Warranty

<b>Claim Type</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/48,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	4024		
<b>Damage Code:</b>	0040		
<b>Labor Operations:</b>	Check vehicle (CAN BUS Sleep mode)	0689 0199	10 TU
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 004	10 TU
<b>Claim Comment:</b>	As per TSB 2067804/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



## Additional Information

All part and service references provided in this TSB (**2067804**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.