



TECH TALK - VOLUME 274 May - June 2023

INSIDE THIS ISSUE:

Technical Information- Page 1 TSB/TIN/ATIN Review - Page 6 Technical Training- Page 7 News & Notes - Page 9

TECHNICAL INFORMATION

Protective Film on Scuff Plate accessories

Affected Vehicles: 2022-2023 Outlander

Part Information:

MZ576623EX Front and Rear Scuff Plates MZ315221 Front and Rear Scuff Plates with LED Illumination MZ527151EX Cargo Scuff Plates

Concern:

Several warranty claims have been submitted for Scuff Plates with a dull finish. Investigations have found that the protective film was not removed during PDI.

	DETAIL INSPECTION
De	tailing Before PDI
	Remove RAP-film and remove RAP-film residue ² Inspect paint for damage
De	tailing After PDI
00000	Wash exterior body panels, and check for water leaks after washing Wash and inspect wheels, remove glue residue, and apply tire dressing Check door and trunk/cargo area opening and under hood cleanliness Inspect body panels and paint for damage, alignment and finish quality Inspect all plass for damage and cleanliness inside and nut
	Inspect all moldings, trim, and chrome and remove protective tape
	Inspect weatherstripping and nubber moldings Clean interior and check interior panel/trim fit Check for stains, dirt, scuffs, and damage Check that all door edge guards are in place Check cargo net' and install accessories' Install paper mats on all floors

Check headliner and sun visor cleanliness

The protective film can be identified by an "R" and "L" on the front scuff plates. The rear scuff plates do not have any identification characteristics.



SECOND 2023 QUARTERLY TECHNICIAN QUIZ -TQ0223

The second 2023 Quarterly Technician Quiz is available between April 10 - July 10, 2023.

Dealer personnel must successfully complete the quiz no later than July 10, 2023.



DATES TO REMEMBER:

Mother's Day - May 14th Memorial Day - May 29^{th*} Juneteenth - June 19^{th*} Independence Day - July 4^{th*}

*Observed Holiday - MMNA closed



Protective Film on Scuff Plate accessories (Continued)

When the protective film is removed, the finish is much more reflective and does not stain.



SERVICE MANUAL CHANGES

We are striving to have the best and most accurate Service Manuals in the industry but to be successful, we need your help. Please advise us of errors that our found and provide any suggestions that you may have.

Located in each Service Manual you will find a Mitsubishi Publication Comment Form like the one below. The form is not mandatory, you can email us without it, but please include the information outlined on the form.

Thank you!

MITSUBISHI PUBLIC		FURIN
Use this form to advise us of any errors you might f suggestions that might help us improve Mitsubishi p		also welcome your
Publication that contains error:		
Page number where the error appears:		
Figure number where the error appears:		
Vehicle application and system identification:		
Describe, in detail, the error found or your suggestion	on. Please attach additiona	Il pages as necessary.
Dealer	Dealer Code	
From: Name		
City/Town	State	Zip Code
Signature	Date	Phone
Mail To: Mitsubishi Motors North America, Inc. P.O. Box 689040 Franklin, Tennessee 37068 Attn: Technical Information Dept.	Email to:servicesuppo	rt@mmsa.com
2 c	of 9	

MITSUBISHI PUBLICATION COMMENT FORM

General Information: Removal/Installation of the Side View Mirror

The claws of the side view mirror may become hard and prone to breakage when working in cold outside temperatures. This article advises of precautions to be taken when removing or installing the side view mirror glass in cold outside temperatures.

Affected Vehicles: All

Before Removing/Installing the Side View Mirror Glass:

- Use a hair dryer to warm up the mirror tabs (claws) and the surrounding area
- Avoid heating the side view mirror too quickly or touching the surface structure directlyto prevent cracking or breakage

When Removing/installing the Side View Mirror Glass:

- Use a tool wrapped with protective tape
- Apply the force near the claw areas and not at the edge of the mirror

The structure of the mirror differs by model therefore the application of force and positioning will vary for the removal/installation process. Listed below are some examples. For further details, please refer to the applicable Service Manual.



Precautions: Quarter Window Sash Molding Loose

Affected Vehicles: 2022-2023 Outlander and 2023 Outlander PHEV

The quarter window sash molding [outer] may become loose or wobble and come off easily. If the claws of the quarter window sash molding [outer] are not tightly fitted, the parts may become deformed and should be replaced. This article introduces the precautions required when replacing the parts with new ones.



Quarter window sash molding [outer]



Quarter window sash molding [inner]

The claws at the bottom of the part (2A in the image above) are not tightly fitted.

Precautions and Confirmation Methods:

Please make sure that the claws are tightly fitted by following this procedure when replacing the parts.



Spare Part Information: Tip When Carpet Rolls Up

Affected Vehicles: 2018-2020 and 2022-2023 Eclipse Cross

When the floor carpet is exposed to a hot environment for a long period of time, the front end of the carpet may deform and roll up.

To prevent this phenomenon, the shape of the floor carpet has been modified (effective March 2023).

This modification enables the floor carpet to be fixed into position with a clip (red circled areas in images) on the cowl side trim.





Part Name	Old Part Number	New Part Number	Remark
	7270B648XA	74902W131P	
	7270B649XA	74902W141P	After
	7270B651XA	74902W161P	21MY
CARPET, FLOOR	7270A990XA	74902W091P	Dánha
	7270A991XA	74902W101P	Prior to 20MY
	7270A995XA	74902W121P	



TSB/TIN/ATIN REVIEW

Since Tech Talk 273, the following bulletins have been published:

UBLISH DATE	TSB/ATIN/TIN #	SUBJECT	MODELS
			2017-2020 OUTLANDER, 2018-
7 (27 (2027	TCD 07 54 005	BLIND SPOT WARNING (BSW) SERVICE	2021 AND CERTAIN 2022
3/27/2023	<u>TSB-23-54-001</u>	REQUIRED WARNING ON MULTI INFORMATION	OUTLANDER PHEV, 2018-2020
		SYSTEM (MID)	ECLIPSE CROSS, AND 2019
		COOL AIR EXPELLED WHEN A/C SWITCH IS	OUTLANDER SPORT
	TSB-23-55-002	-	2022-2023 OUTLANDER
		TURNED OFF WHILE IN ECO MODE TRANSMISSION CONTROL MODULE (TCM)	
	TSB-23-23-002	SOFTWARE UPDATE FOR DTC: P0780/P0706	2022-2023 OUTLANDER
		SHIFT BY WIRE CONTROL (SCU) SOFTWARE	
	<u>TSB-23-23-003</u>	UPDATE WHEN REPLACING TCM	2022-2023 OUTLANDER
		CORRECTION/ADDITION OF INSPECTION	
	TSB-23-55-003	PROCEDURE AND TROUBLE SYMPTOM CHART	2018-2021 OUTLANDER PHEV
	150 25 55 665	FOR A/C - SMR	
		CORRECTION TO THE DESCRIPTION OF ENGINE	
	<u>TSB-23-13-001</u>	WARNING MESSAGE - SMR	2022-2023 OUTLANDER
	TCD 07 77 007	PROCEDURE CORRECTION FOR THE LOWER	2014-2020 OUTLANDER AND 2018
	<u>TSB-23-33-003</u>	ARM BUSHING REPLACEMENT - SMR	2021 OUTLANDER PHEV
	TED 37 75 007	CORRECTION TO THE WARNING LIGHT	
	<u>TSB-23-35-003</u>	DISPLAY DESCRIPTION - SMR	2022-2023 OUTLANDER
		TORQUE CHANGE OF BOLTS FOR THE A/C	2018-2020 ECLIPSE CROSS AND
	TSB-23-55-004	CONTROL UNIT AND HAZARD WARNING LAMP	2018-2020 ECLIPSE CROSS AND 2022-2023 ECLIPSE CROSS
		SWITCH - SMR	2022-2023 ECLIPSE CR033
3/29/2023	TSB-23-54-002	ENGINE START DELAY WHEN USING REMOTE	2022-2023 OUTLANDER
		START	
4/24/2023	<u>TSB-23-00-001</u>	LOAD CARRYING CAPACITY LABEL	ALL MODELS
	<u>TSB-23-00-004</u>	RAP-FILM ADHESIVE RESIDUE REMOVAL	ALL MODELS
	TSB-22-55-001REV	A/C INOPERATIVE WITH DTC B20C8-14 -	2022 OUTLANDER
	<u>TSB-23-54-003</u>	TESTING 12V BATTERY WITH MIDTRONICS	2022-2023 OUTLANDER
		CPX-930 DURING PDI	2016-2017 LANCER, 2015-2023
			OUTLANDER SPORT, 2016-2020
	TSB-23-23-004	MAINTENANCE PROCEDURE CHANGE FOR CVT	OUTLANDER, 2018-2020 ECLIPSE
	150 25 25 004	- SMR	CROSS AND 2022-2023 ECLIPSE
			CROSS
		DESCRIPTION CORRECTION FOR ECM	
	<u>TSB-23-13-002</u>	REPLACEMENT PROCEDURE - SMR	2022-2023 OUTLANDER
(/DE /DODZ	TED 37 00 002	GENERAL PDI PROCEDURES FOR 2024	
4/25/2023	<u>TSB-23-00-002</u>	MODELS (EXCEPT PHEV)	ALL MODELS (EXCEPT PHEV)
	TSB-23-00-003	GENERAL PDI PROCEDURES FOR 2024	OUTLANDER PHEV
	130-23-00-003	OUTLANDER PHEV	UUILANDER PHEV
		ADDITION OF SERVICE PROCEDURE	
5/9/2023	TSB-23-11-003	DESCRIPTION FOR HEADLIGHT AIMING AND	2022 OUTLANDER
2, 7, 2023		EXHAUST GAS TEMPERATURE SENSOR - SMR	
		DESCRIPTION CORRECTION FOR EVAPORATIVE	
	TSB-23-13-003	EMISSION CONTROL SYSTEM AND MULTIPORT	2018-2021 OUTLANDER PHEV
		FUEL INJECTION SOLENOID VALVE - SMR	
	<u>TSB-23-54-004</u>	DIAGNOSTIC PROCEDURE CORRECTION FOR	2018-2021 OUTLANDER PHEV
	<u>TSB-23-54-004</u>	DIAGNOSTIC PROCEDURE CORRECTION FOR BATTERY MANAGEMENT UNIT - SMR CORRECTION AND CHANGE TO THE SERVICE	2018-2021 OUTLANDER PHEV

IMPORTANT

Affected new or used vehicle inventory must be repaired before the vehicle is sold or delivered. Dealers must check their vehicle inventory VINs on the Warranty Superscreen to verify whether the vehicle is involved in a recall campaign.

It is a violation of Federal Law for a dealer to sell or deliver a new motor vehicle or any new / used motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or non-compliance is remedied.



TECHNICAL TRAINING COURSE SCHEDULE

Atlanta Technical Training Center - Southeast Region 801 Interstate West Parkway, Lithia Spring, GA 30122 (770) 732-3000 Airport: Atlanta (ATL)

May '23						
Monday Tuesday Wednesday Thursday Friday						
1	2	3	4	5		
	MED4	STV	EL1	EL1		
8	9	10	11	12		
15	16	17	18	19		
22	23	24	25	26		
	MED4	STV4	EL1	EL1		
29	30	31	1	2		
	PHEVG2TT	PHEVG2TT				

	JUNE '23								
Monday	Tuesday	Wednesday	Thursday	Friday					
29	30	31	1	2					
	PHEVG2TT	PHEVG2TT							
5	6	7	8	9					
	STV4	MED4	EL1	EL1					
12	13	14	15	16					
	EECS	EECS	EECS	EECS					
19	20	21	22	23					
26	27	28	29	30					
	CES	CES	ADAS	ADAS					

JULY '23						
Monday Tuesday Wednesday Thursday Friday						
3	4	5	6	7		
10	11	12	13	14		
17	18	19	20	21		
	EECS	EECS	EECS	EECS		
24	25	26	27	28		
	CES	CES	ADAS	ADAS		
31	1	2	3	6		

 Dallas Technical Training Center - Central/West Region

 8100 Mesquite Bend Drive, Irving TX 75063

 (972) 401-5930
 Airport: Dallas-Fort Worth (DFW)

May '23							
Monday Tuesday Wednesday Thursday Friday							
1	2	3	4	5			
	PHEVG2TT	PHEVG2TT	PHEVG2TT	PHEVG2TT			
8	9	10	11	12			
15	16	17	18	19			
	EECS	EECS	EECS	EECS			
22	23	24	25	26			
	STV4	MED4	EL1	EL1			
29	30	31	1	2			
			PHEVG2TT	PHEVG2TT			

	JUNE '23							
Monday	Monday Tuesday Wednesday Thursday Friday							
29	30	31	1	2				
			PHEVG2TT	PHEVG2TT				
5	6	7	8	9				
12	13	14	15	16				
	STV4	MED4	EL1	EL1				
19	20	21	22	23				
	PHEVG2TT	PHEVG2TT	PHEVG2TT	PHEVG2TT				
26	27	28	29	30				

JULY '23							
Monday Tuesday Wednesday Thursday Friday							
3	4	5	6	7			
		ER1	ER1	ER1			
10	11	12	13	14			
	MED4	STV4	EL1	EL1			
17	18	19	20	21			
24	25	26	27	28			
	PHEVG2TT	PHEVG2TT	CC1	CC1			
31	1	2	3	4			
	EECS	EECS	EECS	EECS			

New Jersey Technical Training Center - Northeast Region 516 Heron Drive, Swedesboro NJ 08085 (856) 467-7100 Airport: Philadelphia (PHL)

May '23						
Monday Tuesday Wednesday Thursday Friday						
1	2	3	4			
8	9	10	11	17		
15	16	17	18	19		
	10	±1	10			
22	23	24	25	26		
29	30	31	1	2		
	CC1	CC1	ADAS	ADAS		

JUNE '23						
Monday Tuesday Wednesday Thursday Friday						
29	30	31	1			
	CC1	CC1	ADAS	ADAS		
5	6	7	8			
	CES	CES	ADAS	ADAS		
12	13	14	15	16		
19	20	21	22	23		
		ER1	ER1	ER1		
26	27	28	29	30		

JULY '23							
Monday	Tuesday	Wednesday	Thursday	Friday			
3	4	5	6	7			
10	11	12	13	14			
	MED4	STV4	EL1	EL1			
17	18	19	20	21			
	PEVG2TT	PHEVG2TT	CC1	CC1			
24	25	26	27	28			
31	1	2	3	4			
	CES	CES	ADAS	ADAS			

Course Title	Days	Code	Prerequisites	
Engine & Emission Control Systems (ILT)		EECS	ES1W, EL1, STV4, MED4, ME3W	
Engine Repair (ILT)	3	ER1	ES1W, EL1, STV4, MED4, ME3W	
Climate Control (ILT)	2	CC1	ES1W, EL1, STV4, MED4, ME3W	
Manual Transaxles & Transfer Cases (ILT)	3	MTT2	ES1W, EL1, STV4, MED4, ME3W	-
Plug-In Hybrid Electric Vehicle (Virtual)	2	PHEVG2TT	EL1, STV4, MED4, DGPHEVWT	
MEDIC4 (Virtual)	1	MED4	ME3W	_
STV4 (Virtual)	1	STV4	No Prerequisites	
Electrical Systems 1 (Virtual)	2	EL1	ES1W	
Advanced Driver Assistance Systems (ILT)	2	ADAS21TT	ES1W, EL1, STV4, MED4, ME3W	
Chassis Electrical Systems	2	CES22TT	EL1, STV4, MED4, ME3W, ES1W	
CVT OVERHAUL PROCEDURES	2	CVT	STV4, MED4, EL1, ATFW	
New Model Training 2022 Outlander (Virtual)	1	NM221TT	NM221W	

Note: Green = Virtual Course / White = Face to Face Instructor Led Training

*

NEWS & NOTES

FRANKLIN, Tenn., April 5, 2023 – Mitsubishi Motors North America (MMNA) today announced the promotion of Kim Ito to the role of vice president, marketing. Ito, 40, has been with MMNA since 2016, and was promoted to director, marketing, in February, 2022. She will continue to report directly to MMNA president and CEO, Mark Chaffin.

Ito has responsibility for all marketing and advertising activities and strategies for the brand, including TV, digital, social, print and out-of-home, interactive platforms including digital retailing, CRM and retail marketing programs with the company's dealer partners. In addition, Ito will add customer experience (CX) activities to her marketing responsibilities as MMNA changes the definition of customer to the very point where a potential customer comes into the company's ecosystem, as they begin their shopping journey with research, vehicle configuration and pricing, and initial dealer contact.

Additionally, and in further recognition of this internal shift and the continued prioritization of CX, Kiri Kiely-Rodriguez is promoted to director, customer and retail experience, from senior manager. Kiely-Rodriguez will report directly to Kim Ito.

"These promotions are well-deserved, and are recognition of their hard work, successes and vision for the future," said Mark Chaffin regarding this announcement. "Once again, MMNA is promoting from within, and proof that our employee team is the very best in the industry. This further bolsters female representation on MMNA's VP leadership team to three, and I'm proud to see the diversity of thought, experience and backgrounds that shape our company."

As part of the recent announcement of its Midterm Plan, "Challenge 2025", MMNA's parent company, Mitsubishi Motors Corporation, noted that MMNA will be a global leader when it comes to growing the company's local leadership

position in the use of innovative digital tools for sales and marketing. The two promotions announced today, and the move of CX into the marketing team, directly support that leadership position, and set the company up for future success.



NEWS & NOTES (Continued)

Northwest Automotive Press Association: Northwest Outdoor Activity Vehicle of the Year

Rugged, capable, and reliable. But don't just take our word for it. The 2023 Outlander Plug-In Hybrid is Northwest Automotive Press Association's "Northwest Outdoor Activity Vehicle of the Year" and also came out top in the "Best Three-row Family SUV" category.

FRANKLIN, Tenn., Apr. 24, 2023 – Members of the Northwest Automotive Press Association (NWAPA) wrapped up two days of on- and off-road testing at The Ridge Motorsports Park in Shelton, Wash., and the votes are in and conclusive: the <u>2023 Mitsubishi Outlander Plug-in Hybrid</u> is NWAPA's Northwest Outdoor Activity Vehicle of the Year, against stiff competition from 21 other SUVs and pickup trucks. The vehicle also won a category award, being named "Best Three-row Family SUV". Since its launch in December 2022, the 2023 Outlander PHEV has been garnering awards and media accolades² for its interior and exterior styling, driving dynamics, Super-All Wheel Control (S-AWC)³ all-wheel drive system, and seamless blend of electric and gasoline drive systems.

"Every award is special, and is a nod to our design and engineering teams' passion and talent," said Mark Chaffin, president and CEO, Mitsubishi Motors North America, Inc. "But awards that recognize the Outlander Plug-in Hybrid's onand off-road all-weather breadth of capability, as well as the unique three-row, seven-passenger capability, speak directly to how our customers use their vehicles every day, regardless of road conditions."

The 2023 Outlander Plug-in Hybrid offers up to 38 miles of all-electric range, up to 420 miles of overall range and is the only plug-in hybrid on the market with available DC fast-charging capability (SEL and above models), which can fill the 20kWh battery pack to 80% capacity in just 38 minutes.⁴ All models also feature Mitsubishi's new "Innovative Pedal" technology, which allows near-one-pedal acceleration and deceleration, similar to full battery electric vehicles.⁵ This system further differentiates the Outlander PHEV from other plug-in hybrids, and highlights the vehicle's electric-first design philosophy.

"The victory might be a surprise for some, but not for those that tested the all-new Mitsubishi Outlander Plug-in Hybrid," said NWAPA President and Event Chair Nik Miles. "It is well-equipped, extremely capable, and is loaded with features not seen on other plug-in hybrids."

All plug-in hybrid Outlander models are equipped as standard with the brand's signature Super All-Wheel Control (S-AWC) all-wheel drive system, allowing for greater vehicle control and increased driver confidence. The twin-motor system, utilizing the gasoline engine and front motor to drive the front wheels, and a stand-alone rear-mounted motor to drive the rear axle, boasts a combined 248-horsepower and 332 lb./ft of torque and achieves a 64 MPGe (miles-per-gallon equivalent) rating⁶.

In its recently announced Midterm Plan – <u>"Challenge 2025"</u> – MMNA's parent company Mitsubishi Motors Corporation (MMC) as committed to accelerating its efforts toward a sustainable carbon-neutral future, setting goals of 40 percent reduction in vehicle CO2 emissions and 50 percent reduction in operational CO2 emissions by 2030. Additionally, MMC has set targets for global sales of electrified vehicles at 50 percent by 2030 and 100 percent by 2035, leveraging a blend of plug-in hybrids (PHEV), hybrids (HEV) and pure electrics (BEV).

