



Bulletin No.: PIT6026

Published date: N/A

## Preliminary Information

### PIT6026 Dead Battery / Radio Inoperative / OTA Failed Message As a Result of OTA Update N22-238206

Product Investigation Review Required

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2022	All	All	All	All
Chevrolet	Suburban	2022	All	All	All	All
Chevrolet	Tahoe	2022	All	All	All	All
GMC	Yukon	2022	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	United States, Canada, Mexico, Europe, Uzbekistan, Russia, Middle East, Argentina (Mercosur), Brazil (Mercosur), Bolivia (West), Chile (West), Colombia (West), Ecuador (West), Paraguay (West), Peru (West), Uruguay (West), Japan, Cadillac Korea (South Korea), Thailand (ASEAN), Australia/New Zealand, Other Africa
Condition	Some vehicles may not power on or have a dead battery along with a radio that's inoperative, blank or shows a failed to update message. A technician may also find that OTA update N22-238206 is waiting to install or has failed to install.
Cause	The cause of this condition could be related to an OTA update attempting to install.

#### Correction:

- Charge the vehicle battery and test for a good battery. Then confirm the vehicle will start and run.  
**NOTE: When connecting the negative battery charger lead, use a solid engine ground or the ground stud in the engine compartment that is connected directly to the battery negative cable/terminal/post. Do NOT connect the battery charger lead directly to the negative battery post.**
- Go into vehicle settings and verify under "Vehicle Updates" that it shows OTA N22-238206 Pending or Failed.  
**NOTE: If the vehicle does not power up or start once the battery is charged, then this procedure does not apply and perform normal SI Diagnostics.**
- If OTA N22-238206 shows Pending or Failed, Reprogram the A11- Radio using Techline Connect SPS2.  
**NOTE: Programming may require use of a USB flash drive. Be sure to follow the programming instructions in Service Information.**

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810335	Radio Programming With SPS	Use Published Time

## Version History

Version	<b>1</b>
Modified	05/23/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.