

HVAC Drain Hose Disconnected From HVAC Case and/or Oil/Grease Odor From Vents

Service Category Vehicle Interior

Section Heating/Air Conditioning

Market USA

Toyota Supports
ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2020 - 2022	Highlander, RAV4	
2022	Tundra	

Introduction

Some 2020 – 2022 model year Highlander and RAV4 vehicles, and 2022 model year Tundra vehicles equipped with a start/stop switch may exhibit water entry to the vehicle from the HVAC drain hose being disconnected from the air conditioning radiator assembly and/or a grease/oil odor emitting from the vents. This condition may be caused by paraffin wax leaking from the evaporator. Follow the repair procedure in this bulletin to address this condition.

HVAC Drain Hose Disconnected From HVAC Case and/or Oil/Grease Odor From Vents

Production Change Information

This bulletin applies to:

- All 2020 model year RAV4 vehicles.
- All 2021 model year RAV4 vehicles produced by Takaoka* and TMMC*.
- All 2021 model year RAV4 vehicles produced by Shokki Nagakusa* **BEFORE** the Production Change Effective VIN shown below.
- All 2022 model year RAV4 vehicles produced by Takaoka* and TMMC* **BEFORE** the Production Change Effective VINs shown below.
- All 2020 – 2021 model year Highlander vehicles.
- All 2022 model year Tundra and Highlander vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	MODEL YEAR	PLANT*	DRIVETRAIN**	VIN
RAV4	2021	Shokki Nagakusa (D)	FWD	JTM#1RFV#MD084963
			AWD	JTM#1RFV#MD084913
	2022	Takaoka (J)	FWD	JTM#1RFV#NJ024345
			AWD	JTM#1RFV#NJ040396
		TMMC Cambridge (C)	2WD	2T3#1RFV#NC207902
			AWD	2T3#1RFV#NC313526
		TMMC Woodstock (W)	2WD	2T3#1RFV#NW230598
			AWD	2T3#1RFV#NW317011

*The plant is determined by the 11th digit of the VIN: D = Shokki Nagakusa, J = Takaoka, C = TMMC Cambridge, and W = TMMC Woodstock.

**The drivetrain is determined by the 4th digit of the VIN: C or W = FWD and A, B, F, G, R, or P = AWD.

MODEL	MODEL YEAR	PLANT*	LINE**	DRIVETRAIN	VIN
Highlander	2022	TMMI (S)	Line 1	2WD	5TD#ZRAH#NS112708
				AWD	5TD#ZRBH#NS199947
			Line 2	2WD	5TD#ZRAH#NS546859
				AWD	5TD#ZRBH#NS571677

*The plant is determined by the 11th digit of the VIN: S = TMMI.

**The line is determined by the 12th digit of the VIN: 0 – 4 = Line 1 and 5 – 9 = Line 2.

HVAC Drain Hose Disconnected From HVAC Case and/or Oil/Grease Odor From Vents

Production Change Information (continued)

MODEL	MODEL YEAR	PLANT*	DRIVETRAIN	CAB	BED LENGTH	VIN
Tundra	2022	TMMTX (X)	2WD	Double Cab	6.5 ft.	5TF##5AA#NX007791
					8.1 ft.	5TF##5CD#NX001184
				Crew MAX	5.5 ft.	5TF##5AB#NX007791
					6.5 ft.	5TF#A5BC#NX001595
			4WD	Double Cab	6.5 ft.	5TF##5DA#NX024925
					8.1 ft.	5TF##5GD#NX001416
				Crew MAX	5.5 ft.	5TF##5DB#NX024925
					6.5 ft.	5TF#A5EC#NX005221

*The plant is determined by the 11th digit of the VIN: X = TMMTX.

Warranty Information

OP CODE	MODEL	DESCRIPTION	TIME	OFFP	T1	T2
883621	RAV4	R & R the Air Conditioner Radiator Assy & Drain Hose	5.4	87050-####*	66	14
	Highlander		5.1			
	Tundra		6.0			

*Warranty claim MUST be submitted with the correct 10-digit OFFP. Choose the correct OFFP for the vehicle being repaired by searching for the parts in the Electronic Parts Catalog using the VIN filter.

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

HVAC Drain Hose Disconnected From HVAC Case and/or Oil/Grease Odor From Vents

Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
870500R160	870500R160	Radiator Assy, Air Conditioner	1
870500R161	870500R161		
870500R110	870500R110		
870500R120	870500R120		
870500E280	870500E280		
870500C210	870500C210		
870500C200	870500C200		
885390R050	885390R050		
885390E100	885390E100		
885390C080	885390C080		

Required Tools & Equipment

REQUIRED TOOLS & MATERIAL	QTY
Robinair R1234YF A/C Machine	1

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream ADVI*	ADE	TSADVUNIT	1
Techstream 2.0		TS2UNIT	
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

*Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- GTS+ software version 2023.02.001.02 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

HVAC Drain Hose Disconnected From HVAC Case and/or Oil/Grease Odor From Vents

Repair Procedure

1. Is the vehicle equipped with a start/stop switch?

NOTE

ALL 2022 model year Tundra vehicles are equipped with a start/stop switch.

- **YES** — Continue to step 2.
- **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

Figure 1. Highlander Start/Stop Switch Location





Figure 2. RAV4 Start/Stop Switch Location



2. Is the drain cooler hose detached from the air conditioning radiator assembly and/or a grease/oil odor emitting from the vents?
 - **YES** — Continue to step 3.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

NOTE

If there is evidence of water intrusion or a musty smell is present in the vehicle interior, follow the procedures outlined in [T-SB-0094-21](#) *Odor Remediation After Water Intrusion*, to remediate the odor and address this concern.

HVAC Drain Hose Disconnected From HVAC Case and/or Oil/Grease Odor From Vents

Repair Procedure (continued)

3. Remove the air conditioning radiator assembly and drain cooler hose.
Refer to TIS, applicable model and model year Repair Manual:
 - 2020 – 2022 Highlander:
Vehicle Interior – Heating/Air Conditioning – “[Heating/Air Conditioning: Front Air Conditioning Unit \(for Gasoline Model\): Removal](#)”
 - 2020 RAV4:
Vehicle Interior – Heating/Air Conditioning – “[Heating/Air Conditioning: Air Conditioning Unit \(for A25A-FKS\): Removal](#)”
 - 2021 – 2022 RAV4:
Vehicle Interior – Heating/Air Conditioning – “[Heating/Air Conditioning: Air Conditioning Unit \(for A25A-FKS\): Removal](#)”
 - 2022 Tundra:
Vehicle Interior – Heating/Air Conditioning – “[Heating/Air Conditioning: Front Air Conditioning Unit: Removal](#)”

4. Install the NEW air conditioning radiator assembly and drain cooler hose.
Refer to TIS, applicable model and model year Repair Manual:
 - 2020 – 2022 Highlander:
Vehicle Interior – Heating/Air Conditioning – “[Heating / Air Conditioning: Front Air Conditioning Unit \(for Gasoline Model\): Installation](#)”
 - 2020 RAV4:
Vehicle Interior – Heating/Air Conditioning – “[Heating / Air Conditioning: Air Conditioning Unit \(for A25A-FKS\): Installation](#)”
 - 2021 – 2022 RAV4:
Vehicle Interior – Heating/Air Conditioning – “[Heating / Air Conditioning: Air Conditioning Unit \(for A25A-FKS\): Installation](#)”
 - 2022 Tundra:
Vehicle Interior – Heating/Air Conditioning – “[Heating / Air Conditioning: Front Air Conditioning Unit: Installation](#)”

5. Confirm the condition no longer exists.