

- ATTENTION:**
- GENERAL MANAGER
  - PARTS MANAGER
  - CLAIMS PERSONNEL
  - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.


© 2023 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2022MY WRX

**NUMBER:** 09-102-23

**SUBJECT:** Diagnosis Procedures for DTCs  
P2404 & P2109

**DATE:** 06/28/23

**INTRODUCTION:**

This bulletin announces the diagnostic procedures and availability of reprogramming files to rectify DTCs P2404 (Evap System Leak Detection Pump Sense Circuit Range/Performance) and P2109 (Throttle/Pedal Position Sensor “A” Minimum Stop Performance). P2404 is caused by the internal pump of the Evaporate Leak Check Module (ELCM) being temporarily stuck/seized. P2109 is caused by the throttle body becoming frozen in the closed position. If these DTCs are found stored within the ECM, follow the procedures outlined in this bulletin.

**PRODUCTION CHANGE INFORMATION:**

These new files have been incorporated into vehicle production as per the table below.

Model	Transmission	Starting VIN
WRX	CVT	N8029088
	MT	N9029081

**PAK FILE APPLICABILITY:**


MY	Model	Trans	File Description	Old ECM Part #	Decryption Keyword	New CID #
22	WRX	CVT	22765AR885.pk2	22765AR880 22765AR881 22765AR882 22765AR883 22765AR884	1D2C307A	LHBHB10C00G
		MT	22765AR895.pk2	22765AR890 22765AR891 22765AR892 22765AR893 22765AR894	944297E3	LHBHB10B00G

These reprogramming files have been included in the January 2023 SSM software update.


<p><b>CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.</b></p> <p>Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.</p>	<p style="text-align: center;"><b>Subaru of America, Inc. is ISO 14001 Compliant</b></p> <p>ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.</p>
--	--

*Continued...*


**SERVICE PROCEDURE FLOWCHART:**



*Continued...*



*Continued...*



**SERVICE PROCEDURE / INFORMATION:**

**STEP 1:** Using Subaru Select Monitor (SSM), check for diagnostic trouble codes P2404 & P2109. Use the table below to confirm the next course of action. Always save SSM data and record the results of the following tests.

DTC Results	Next STEP
P2109	Proceed to STEP 9
P2404	Proceed to STEP 2
P2404 & P2109	

**STEP 2:** Are any of the diagnostic trouble codes listed below also stored withing the ECM?


- P2419 - Evap System Switching Valve Control Circuit Low
- P2420 - Evap System Switching Valve Control Circuit High
- P2401 - Evap System Leak Detection Pump Control Circuit Low
- P2402 - Evap System Leak Detection Pump Control Circuit High
- P24BA - Evap System Leak Detection Pump Pressure Sensor Circuit Low
- P24BB - Evap System Leak Detection Pump Pressure Sensor Circuit High
- P24B9 - Evap System Leak Detection Pump Pressure Sensor Circuit Range/ Performance

**NO** – Proceed to STEP 3.

**YES** – Perform diagnosis following the applicable Service Manual. Once repaired, perform the reprogramming procedure outlined in STEP 9.

*Continued...*

**STEP 3:** CAREFULLY disconnect the ELCM drain tube. Inspect for signs of water or oil.




Have signs of water or oil been detected within the ELCM drain tube?

**YES** – Clean and dry the drain tube using a non-alcohol base cleaner. Proceed to STEP 4.

**NO** – Proceed to STEP 4.

**STEP 4:** Connect the vehicle to a recommended power supply. See APPENDIX A for addition information regarding power supply. Using SSM, perform the Evaporative System Leak Test. Collect and save all data.



Once the evaporative system leak test is complete, check the DTCs and examine the vacuum value results. Record the value shown in the row labeled MID: \$3C, TID: \$C4, and Scaling ID: \$FE. This value should be lower than -0.26 PSI.

MID	TID	Scaling ID	Value	Unit	Minimum	Maximum	Result
\$3C	\$C1	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C2	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C3	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C4	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C5	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C6	\$35	0.00	psi	0.00	0.00	OK
\$3C	\$C7	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C8	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$C9	\$FE	0.00	psi	0.00	0.00	OK
\$3C	\$CA	\$FE	0.00	psi	0.00	0.00	OK

Value Must Be Lower Than -0.26 PSI

*Continued...*

Is DTC P2404 stored within the ECM?

**NO** – Proceed to STEP 5.


**YES** – Proceed to STEP 6.

**STEP 5:** Was the vacuum value result observed in STEP 4 found to be lower than -0.26 PSI?

**YES** – Proceed to STEP 9.

**NO** – Repeat STEP 4 one time then proceed to STEP 7.

**STEP 6:** Using SSM, perform the ELCM Pump Active Test for a period of 35 minutes or more. See APPENDIX A for addition information regarding power supply.



Once the ELCM Pump Active Test has been performed for a period of 35 minutes or more, repeat the Evaporative System Leak Test outlined in STEP 4. Check the DTCs and the vacuum value results.

Is DTC P2404 stored within the ECM?

**NO** – Proceed to STEP 7.

**YES** – Proceed to STEP 8.

**STEP 7:** Was the vacuum value result observed during the second Evaporative System Leak Test found to be lower than -0.26 PSI?

**YES** – Proceed to STEP 9.

**NO** – Proceed to STEP 8.

**STEP 8:** Replace the Evaporate Leak Check Module and repeat the Evaporative System Leak Test outlined in STEP 4. Check the DTCs and the vacuum value results.

Is DTC P2404 stored within the ECM?

**NO** – Proceed to STEP 9.

**YES** – Contact Subaru Techline with ability to provide SSM data and the testing results attained using this bulletin.

*Continued...*

**STEP 9:** Reprogram the ECM following the normal FlashWrite procedure. See APPENDIX A for addition information regarding power supply.

**WARRANTY / CLAIM INFORMATION:**

For vehicles within the Basic New Car Limited, an applicable Emission Warranty period or covered by an active Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
ECM REPROGRAMMING & DRAIN TUBE CLEAN / EVAP TESTING	A455-223	1.0H	UPG-48
LEAK CHECK MODULE R&R AND ECM REPROGRAMMING	A455-244	1.9H	

**IMPORTANT:** Always note the original Calibration Identification number (CID) the vehicle came in with on the repair order **before** reprogramming and, make sure to list the **NEW** CID for any newly-installed programming (as confirmed from the actual control module **AFTER** installation). The **NEW** CID **MUST** also be noted on the repair order as this information is required for entry in the Miscellaneous Detail field during claim submission.

**NOTE:** The PAK file listings provided in this bulletin are the latest available at the time of publishing. Updates are often released thereafter without revision to the original bulletin. For this reason, it is critical to always have the latest version of Select Monitor software installed on your system. You can confirm if a later version is available by entering the CID listed in this bulletin into FlashWrite. If a newer CID is shown as available in FlashWrite, reprogram using that file.

**IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

*Continued...*

## APPENDIX A

Subaru of America, Inc. (SOA) highly recommends utilizing either the Subaru Midtronics DCA8000 Dynamic Diagnostic Charging System or the Subaru Midtronics GR8-1100 Diagnostic Battery Charger to the vehicle in the Power Supply Mode feature anytime a vehicle control module is being reprogrammed. Once the Midtronics charger is connected to the vehicle, if the battery is fully charged, it will take less than three (3) minutes to boot-up the charger, select the Power Supply Mode, and have the battery voltage stabilized and ready for reprogramming.

### NOTES:

- For instructions on using the Power Supply Mode, reference the applicable User Manual for the Midtronics DCA-8000 Dynamic Diagnostic Charging System and the Midtronics GR8-1100 Diagnostic Battery Charger on STIS.
- Confirm all electrical loads such as lights, audio, HVAC, seat heaters, and rear defroster are all switched OFF before setting up the charger for Power Supply Mode.
- Select the correct battery type (Enhanced Flooded, Flooded, Gel, AGM or AGM Spiral).
- Input the CCA which matches the vehicle's battery. **NOTE:** OE and replacement batteries have different CCA ratings. Always confirm the battery's CCA rating before proceeding.
- If using a DCA-8000 Dynamic Diagnostic Charging System, set the power supply voltage to 13.5 Volts.
- DO NOT connect the DST-i or DST-010 until the Power Supply mode function has completed its battery test mode and the Charging Voltage has dropped to and shows a steady 13.5 Volts on the display.
- Once Power Supply Mode reaches a steady 13.5 Volts, connect the DST-i or DST-010 to the OBD connector and proceed with initiating the normal FlashWrite reprogramming process.
- Amperage will fluctuate based upon the vehicle's demand for power. **NOTE:** If the voltage rises beyond 14 Volts while programming is in process, the procedure will abort. This can indicate a need to test or charge the vehicle battery before any further attempt at programming is made.
- ALWAYS set the power supply voltage to 13.5 Volts when using Power Supply Mode. NEVER turn the ignition switch on when charging at voltages 15 Volts or higher.

**REMINDER:** If the DCA-8000 or GR8-1100 indicates the vehicle's battery must be charged, charge the battery fully before proceeding to reprogram the vehicle while using the Power Supply Mode.

**NOTE:** Control module failures resulting from battery discharge during reprogramming are not a matter for warranty. Should any DTCs reset after the reprogramming update is performed, diagnose per the procedure outlined in the applicable Service Manual.

*Continued...*



**VERY IMPORTANT:**

This information is applicable to the Subaru Midtronics DCA-8000 Dynamic Diagnostic Charging System and the Subaru Midtronics GR8-1100 Diagnostic Battery Charger **ONLY**. It does not apply to any other brand / type of “generic” battery charger whatsoever. **ONLY** the DCA-8000 and the GR8-1100 and their Power Supply Mode feature have been tested and approved by SOA.