

Subject: CREAK OR SQUEAK NOISE FROM FRONT OF VEHICLE WHEN TRAVELING OVER A BUMP WHILE TURNING AT LOW-SPEED	Bulletin No.: 02-002/23
	Last Issued : 06/14/2023


BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2024 CX-90

DESCRIPTION

Some vehicles may exhibit a creaking or squeaking noise from the front of the vehicle when traveling over a bump while turning at low-speed. This is caused by a stick-slip phenomenon occurring between the rubber bushing and the stopper on the rear of the front lower arm (1). A mass production change is under study.



Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.

NOTE: This is a provisional procedure, not a permanent one.

2. Prepare grease with the following specifications.

- Grease type: Rubber Grease or Silicone Grease.
- Penetration depth: 24 - 28 mm
- High viscosity and infusible

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Sample of Grease




Granville Red Rubber Grease


3. Lift up the vehicle.

4. Apply the grease on the contact surface (2) between the rubber bushing (3) and the stopper (4) on the rear of both left and right front lower arms (1).

NOTE: The yellow areas (2) should be filled (packed) with grease on both the front and rear sides of the bushing.




RH image shown



VIEW OF A

5. Wipe off excess grease (1) on the non-contact surface.

NOTE: Clear off the grease from the edge of the stopper. No need to wipe off the grease inside of the stopper.



6. Verify the repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	82
Damage Code	9W
Part Number Main Cause	KBB6-34-J00*
Quantity	0
Operation Number / Labor Hours:	XXWB7XRX / 0.5 Hrs.

NOTE: Grease amount is included in the labor time.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.