Mazda North American Operations Irvine, CA 92618-2922



Subject:

WRINKLES ON LEATHER SEAT SURFACE OF NEW (UNSOLD) VEHICLE

Bulletin No.: 09-007/23

Last Issued : 06/01/2023

BULLETIN NOTES

- This bulletin supersedes the previously issued bulletin(s) listed below: The changes are noted in Red text.
- This service bulletin is only for sublet repair. A qualified upholstery repair specialist is required for this repair procedure.
- · Please print a copy of this bulletin for the upholstery repair specialist.

Previous TSBs:	Date(s) Issued:
09-007/23	02/01/23 and 04/03/23
09-012/22	04/08/22
09-007/20	12/10/20 and 01/13/20
09-006/19	01/14/19
09-015/18	03/22/18 and 10/10/18
09-016/16	03/07/16 and 06/22/16
09-015/12	03/23/12

APPLICABLE MODEL(S)/VINS:

2020-2024 Mazda3 2020-2021 Mazda6 2020-2024 MX-5 2022-2024 MX-30 2020-2021 CX-3 2020-2024 CX-5 2020-2024 CX-9 2020-2024 CX-30 2023-2024 CX-50 2024 CX-90

DESCRIPTION

At PDI or when new vehicle is delivered, some customers may complain about wrinkles on the leather seat cushion and/or seat back surface.

Page 1 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



NOTE:

- This service information only applies to new/unsold vehicles currently in dealer inventory.
- Explain to the customer before performing the repair that the wrinkles may not be completely removed.
- This repair is not intended to be a permanent fix. It is only meant to make new seats look their best when the vehicle is first presented to the customer.
- Explain to the customer that the leather is a natural material and may develop some wrinkles due to aging or wear during normal use. This is normal behavior of the leather material.
- Once the vehicle is in service, the leather seat trim will start to conform to the customer and may develop some wrinkles. This is a normal occurrence that happens over time and mileage accumulation.
- This service information only applies to vehicles equipped with leather seat trim.
- It is important to determine what interior trim (leather or leatherette) the subject vehicle has before attempting this repair.
- Some vehicles have a combination of leather AND leatherette covered seat trim. The areas covered in leather are the seat bottom and seat back.
- Only the leather portion of the seat trim have wrinkles. The seat trim areas covered in leatherette DO NOT not have wrinkles and do not require ironing.

Customers experiencing this concern should have their vehicle repaired according to the following repair procedure.

REPAIR PROCEDURE

NOTE: This repair is only applicable to new vehicles during PDI or when a new vehicle is delivered to the customer.

CAUTION:

• DO NOT steam iron leatherette type seat trim, otherwise, the trim will be damaged and will not be covered under warranty.

• To avoid seat trim burn damage, NEVER use a flat iron without steam, ALWAYS use a commercially available steam iron.

- 1. Heat an iron to 284 356 °F(140 -180 °C).
- 2. Sufficiently spray water on a cloth with a spray bottle.

Page 2 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 09-007/23	Last Issued : 06/01/2023
-------------------------	--------------------------

NOTE: Always keep the cloth wet. Spray water on the cloth repeatedly before it dries.



- 3. Wrap the bottom of iron by the water-soaked cloth.
- 4. Stretch the wrinkled portion of seat surface by hand.
- 5. Run the iron with the cloth on the wrinkled area, as shown below.



CAUTION:

- Do not spray water on the ISO FIX button (shown below), seat belt and buckle.
- Do not run the iron on the ISO FIX button, seat belt & buckle.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2023 Mazda North American Operations, U.S.A.





CAUTION:

- **DO NOT** keep the iron in the same area for a long time. Doing so could damage the seat surface, as shown below.
- **DO NOT** run the iron without a water-soaked cloth, especially over the seat trim beading and seat side trim areas.

Page 4 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2023 Mazda North American Operations, U.S.A.



WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified new vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.
- This service bulletin is only for sublet repair. A qualified upholstery repair specialist is required for this repair procedure.

		Note
Warranty Type	A	
Symptom Code	87	
Damage Code	9E	
Part Number Main Cause	Refer to GEPC part number of concerned seat	
Quantity	0	
Operation Number / Labor Hours:	XXG23ARX / 0.0 Hrs.	
Sublet Allowance:	MM030XRX / 0.3 Hrs.	Sublet allowance can be claimed for administration

Page 5 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

tasks associated with the sublet repair.
--

UPHOLSTERY REPAIR SHOP

Cost to repair leather seats

Sublet Invoice Number	Number from the upholstery repair shop invoice or dealer p
	urchase order.
Sublet Type Code	Enter "F6"
Sublet Amount	Enter the upholster shop invoice amount. No mark-up allow
	ed.

Page 6 of 6

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2023 Mazda North American Operations, U.S.A.