



Preliminary Information

PIT5966B OTA Failure or Download Will Not Complete / No Crank / Dead Battery

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engino	Transmissions:		
			from	to	Engine:	Transmissions.		
All	All	2021 - 2024	All	All	All	All		
Involved Region or Country		North America						
Involved Region or Country		The Air (OTA) update: - The radio will remain of - No Crank due to a dea charged. - Intermittently at start Update Download R - When checking the Ve OTA available that will r NOTE: These messages downloaded examples: N22236365, N22238222 Warranty under Require	Some customers may comment on any of the following complaints after an Over The Air (OTA) update: - The radio will remain on for up to 11 minutes after RAP is cancelled. - No Crank due to a dead battery. Vehicle will start and run after the battery is					
Cause		The cause of these concerns could be an OTA is stuck in a pending or download state.						





Correction:

If you have a vehicle that has these symptoms, please perform the following to reset the OTA and clear the messages:

1. Charge the vehicle battery and test for a good battery. Then confirm the vehicle will start and run. NOTE: When connecting the negative battery charger lead, use a solid engine ground or the ground stud in the engine compartment that is connected directly to the battery negative cable/terminal/post. Do NOT connect the battery charger lead directly to the negative battery post.

2. Go into vehicle settings and verify under "Vehicle Updates" that it shows an OTA available. Record the campaign number that is shown.

NOTE: If the vehicle does not power up or start once the battery is charged, then this procedure does not apply and perform normal SI Diagnostics.

3. Move the vehicle to a location that has a known good cellular connection. Then turn the ignition off, exit the vehicle with the key/fob, close all doors and lock the vehicle.

4. Contact TAC by creating a DCM case and reference this PI number PIT5966 in the TAC case along with any other pertinent information including the previously recorded campaign number. For Canada dealership call TAC to create a TAC case.

5. TAC will send your VIN to engineering to have a reset performed. TAC will send a confirmation message back indicating the reset has been requested.

6. Once the confirmation message has been received back from TAC, allow the vehicle to remain undisturbed for 2 hours.

NOTE: Battery State of Charge SOC must be above 70% for the OTA to prompt the install button.

7. After 2 hours, start the vehicle and verify no update messages are shown on the radio display, but more importantly, go back into vehicle settings and check the "Vehicle Update" screen to make sure there are no OTA's available, examples shown below (4). In some cases there will be an OTA to accept.

NOTE: This is only an example showing your software is up to date and the version or dates will vary.

8. Next, confirm there are no excessive parasitic battery draws.

9. If no further issues are found, then before releasing the vehicle back to the customer, complete any open safety recalls.



Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time			
*3487878	Clear OTA Update Message	.6 Hr.			
* This is a unique labor operation for bulletin use only.					

Version History

Version	3
	12/22/2022 - Created on.
Modified	01/13/2023 - Update to the Warranty Section
	06/14/2023 - Update to cover all OTA failures



© 2023 General Motors. All Rights Reserved.