

REFERENCE:	TSB: 08-119-23 REV. A GROUP 08 - Electrical	Date:	May 10, 2023	REVISION:	08-119-23
VEHICLES AFFECTED:	2023 (GG) Dodge Hornet This bulletin applies to vehicles built on or before February 04, 2023 (MDH 0204XX) equipped with Uconnect 5 W 10.25" Display (Sales Codes UBH or UEH) or Uconnect 5 Nav W 10.25" Display (Sales Codes UBS or UES) with either Mph Primary Speedometer (Sales Code JCJ) or Kph Primary Speedometer (Sales Code JDA).	MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH			
CUSTOMER SYMPTOM:	Customers may comment on one or more of the following: <ul style="list-style-type: none"> • Potential message pop-ups and frequent lights on the cluster related to front camera issues. • Temporary front camera blindness due to sun reflection, fog, rain, snow, windshield fogging. 				
CAUSE:	IPC Software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-119-23, date of issue May 05, 2023, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include correction to the RSU number.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU)**23-128**, date of issue May 05, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

REPAIR SUMMARY:

This bulletin involves reprogramming the IPC with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-47-DW	Module, Instrument Panel Cluster (IPC) - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
18-19-47-DX	Module, Instrument Panel Cluster (IPC) - Inspect and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.8 Hrs.
Failure code	RF	Required Flash - RSU	
	CC	Customer Concern	

The dealer must choose which failure code to use depending on if this is a Rapid Service Update (RSU) or Technical Service Bulletin.

- The "RF" failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code "RF" (Required Flash) can no longer be used on Technical Service Bulletin flashes. The "RF" failure code must be used on an RSU.
- If the customer's concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C's must be supplied.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Is the vehicle on the RSU VIN list?
 - YES>>> Proceed to [Step 2](#).
 - NO>>> Proceed to [Step 3](#).
2. Does the IPC have the latest software already installed?
 - YES>>> This bulletin has been completed, use inspect LOP (18-19-47-DW) to close the active RSU.
 - NO>>> Proceed to [Step 3](#).
3. Key ignition in the Run position.
4. Reprogram the IPC with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
5. Key ignition in the Off position.
6. Allow the vehicle and modules to go to sleep for 2 minutes.
7. Key ignition in the Run position.
8. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.