

<b>REFERENCE:</b>	<b>TSB:</b> 18-056-23 <b>GROUP</b> 18 - Vehicle Performance	<b>Date:</b>	May 4, 2023	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	<b>2023 (M6) Jeep Compass</b> This bulletin applies to vehicles built on and before April 20, 2023 (MDH 0420XX) equipped with a 1.4L I4 Turbo Multi-air Engine W/ESS (Sales Code EAQ).	<b>MARKET APPLICABILITY:</b> <input type="checkbox"/> NA <span style="float:right"><input type="checkbox"/> MEA</span> <input type="checkbox"/> SA <span style="float:right"><input checked="" type="checkbox"/> IAP</span> <input type="checkbox"/> EE <span style="float:right"><input type="checkbox"/> CH</span>			
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience the following:</b> <ul style="list-style-type: none"> <li>Vehicle repeatedly cranks when Engine Stop/Start (ESS) is active but engine doesn't restart. Pushing ignition switch, engine starts normally.</li> </ul>				
<b>CAUSE:</b>	<b>PCM Software</b>				

**REPAIR SUMMARY:**

This bulletin involves reprogramming the PCM with the latest available software.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-06-AC	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs.
Failure Code	CC	Customer Concern	

**The dealer must use failure code CC with this Technical Service Bulletin.**

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	—	—

**REPAIR PROCEDURE:**

**NOTE:** Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

**NOTE:** If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*