

Technical Service Bulletin

91 MIB3 ASI: Apple CarPlay screen is blank

91 23 14 2065728/5 July 17, 2023. Supersedes Technical Service Bulletin Group 91 number 22-46 dated November 7, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi Vehicles	2020 – 2024	All	Audi Smartphone Interface

Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised title (added MIB version) Revised service (added software solution)
4	11/07/2022	Revised header (Simplified model list, added MY24) Revised <i>Technical Background</i> (updated iOS versions)
3	10/20/2022	Revised header (Added MY23)

- d (see Figure 1).





Figure 1: ASI display is blank when using wACP.

Workshop findings:

No relevant DTCs are stored.

Technical Background



Technical Service Bulletin

A non-standard behavior of the current Apple iOS versions (including all 14.x, 15.x, and most 16.x versions) causes the phone to fail to send screen data to the vehicle. Additionally, a hardware issue in iPhone 8, iPhone X, and iPhone XR models can cause the display to blank out.

Production Solution

Not applicable.

Service

No repair is available at this time.

1. Do not perform any repairs. Any repairs for this concern may be denied.
2. **For customers with iPhone 8, iPhone X, and iPhone XR:**
The problem is due to a hardware issue in the WiFi chipset of the listed phone models. As those phone models are already out of production, no repair will be available. It is advisable to use a wired connection to use Apple CarPlay for those models.
3. **All other iPhone models:**
Please inform the customer that this behavior is due to a bug in the phone's operating system (iOS). **The iOS bug is fixed in iOS version 16.5 or newer.**

CAUTION

Please ask the customer to always use the most current iOS software for iPhone to ensure the most up-to-date user experience.

NOTICE


In some cases, going to the home menu by clicking the home shortcut on the left of the screen and then reentering ASI resolves the concern. In other cases, the phone might need to be disconnected and then reconnected.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2065728**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



Technical Service Bulletin

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.