

<b>Reference</b>	SSM75869
<b>Models</b>	Defender / L663 Discovery / L462 New Range Rover / L460 New Range Rover Sport / L461 Range Rover / L405 Range Rover Sport / L494 Range Rover Velar / L560
<b>Title</b>	`Coolant Low` Warning Message Displayed On The Instrument Panel Cluster
<b>Category</b>	Engine
<b>Last modified</b>	17-Aug-2023 00:00:00
<b>Symptom</b>	402000 Cooling System Concerns
<b>Content</b>	<p><b><u>Model / Model Year / Derivative</u></b></p> <p>DEFENDER / 20MY onwards / INGENIUM I6 3.0L Diesel/Petrol only  DISCOVERY / 17MY onwards / INGENIUM I6 3.0L Diesel/Petrol only  RANGE ROVER (L405) / 13MY to 22MY / INGENIUM I6 3.0L Diesel/Petrol only  RANGE ROVER (L460) / 22MY onwards / INGENIUM I6 3.0L Diesel/Petrol and V8 4.4L Petrol only  RANGE ROVER SPORT (L494) / 14MY to 22MY / INGENIUM I6 3.0L Diesel/Petrol only  RANGE ROVER SPORT (L461) / 23MY onwards / INGENIUM I6 3.0L Diesel/Petrol and V8 4.4L Petrol only  RANGE ROVER VELAR / 18MY onwards / INGENIUM I6 3.0L Diesel/Petrol only</p> <p><b><u>Situation:</u></b></p> <p>JLR Engineering investigations have found a 'Coolant Low' warning message displayed on the Instrument Panel Cluster.</p> <p><b><u>Cause:</u></b></p> <p>Multiple potential engine coolant leak paths.</p> <p><b><u>Action:</u></b></p> <p>Follow the instruction(s) below.</p> <p><b><u>SERVICE INFORMATION:</u></b></p> <p>Vehicles must be returned to the customer with the engine coolant at the required maximum level and the correct concentration level.</p>

**SERVICE INSTRUCTION:**

NOTE: Make sure the outside surface of the coolant expansion tank is dry before completing the coolant pressure test. Residual engine coolant from a previous top-up may still be present on the outside surface of the coolant expansion tank.

Pressure test the engine cooling system as detailed in the TOPIx Workshop Manual, (see TOPIx Workshop Manual section 303-03: Engine Cooling - Diagnosis and Testing - Cooling System Pressure Test).

Make sure the following components are inspected as part of the cooling system pressure testing diagnosis:

1. Coolant expansion tank/coolant expansion tank filler cap
2. Coolant expansion tank bleed screw - If leaking then a new coolant expansion tank must be installed
3. Turbocharger coolant inlet/outlet hoses
4. Thermostat housing and hose connections
5. Auxiliary water pump connections
6. Radiators and coolers
7. Charge air coolers - external and internal (remove the charge air cooler intake pipe to inspect for internal leaks)
8. Electric supercharger bypass valve body

Complete a coolant concentration (see TOPIx Workshop Manual section 303-03C: Engine Cooling – General Procedures – Cooling System Concentration Check).

Vehicles must be returned to the customer with the engine coolant at the required maximum level and the correct concentration level.

(Ref 000363102, 000375446, 000368746, 000375470)

anBhd#RlcnM7MjAyMy0wOC0xN1QxMzo1ODowOS4zODRaOzEzN4yMjYyNDguMTE4Ow==