Advanced Technical Information

Bulletin #: 2317

Part ID: 1932

1

Macan III – Check engine light with DME fault code P05A(0/3)00

Vehicles Affected

| Models | Model Year | Model Type | VIN Range | Vehicle-Specific Equipment |
|--------|-------------|------------|-----------|----------------------------|
| Macan | 2022 - 2023 | 95B | n/a | n/a |

Revision History

| Revision | Release Date | Changes | |
|----------|-----------------|-------------------|--|
| 0 | August 16, 2023 | Original document | |

Condition

The customer states that the check engine light illuminates in the instrument cluster.

The workshop finds one or some of the following fault codes stored in the DME:

- DME P05A000 Cooling-air flap servo motor, top center mechanical fault (009D46)
- DME P05A000 Cooling-air flap servo motor, top center blocked (009D47)
- DME P05A300 Cooling-air flap servo motor, top center signal implausible (005D93)

Technical Background

This issue is still under investigation by Porsche.

Advanced Technical Information

Bulletin #: 2317 Part ID: 1932

Service Information

1. Check for dirt or contamination at the friction points or the bearings for the motor and clean as needed.



- 2. Check for tension in the radiator shutters and the motor.
- 3. Delete the fault code(s) and operate the radiator shutters via the PIWIS Tester:
 - DME => Drive links/checks => Drive links => Activation of cooling-air flaps, upper coolant radiator
 - a. If the fault does not return, no further diagnosis is necessary.
 - b. If the fault returns, please replace the motor for the front radiator shutters as instructed in WM 193219 Removing and installing motor for cooling-air flaps

Advanced Technical Information

Bulletin #: 2317

Part ID: 1932

Warranty

As always, please document the repair completely in PCSS.

For this repair, please code the "cause" as follows:Cause location:19320 Motor for cooling-air flapsCause symptom:1613 No function

Use the following labor operations **as needed**: 19321950 Motor for cooling-air flaps remove and reinstall

Additional labor operations may be claimed only as needed.

Search Items

Macan, DME, P05A000, P05A300, radiator, shutters, motor, cooling air flaps

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

