



Service Bulletin

Bulletin No.: 23-NA-067

Date: August, 2023

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated on Driver Information Center (DIC), DTC P0000 or P0000.00 Set

| Brand: | Model: | Model Year: | | VIN Breakpoint: | | Engine: | Transmission: |
|-----------|------------------------------|-------------|------|-----------------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado 2500 HD/3500 HD | 2024 | 2024 | — | — | — | — |
| GMC | Sierra 2500 HD/3500 HD | | | | | | |

| | |
|-----------------------------------|---|
| Involved Region or Country | North America |
| Condition | Some customers may comment on the Malfunction Indicator Lamp (MIL) illuminated on the Driver Information Center (DIC). Technicians may find DTC P0000 or P0000.00 set. |
| Cause | The condition may be due to software anomaly in the Electronic Brake Control Module (EBCM). |
| Correction | Replace the Steering Angle Sensor Module. Refer to <i>Steering Angle Sensor Module Replacement</i> in SI. |

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Parts Information

| Causal Part | Description | Part Number | Qty |
|-------------|--------------------|-------------|-----|
| X | SENSOR, STRG ANGLE | 13550726 | 1 |

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time |
|--|--|------------|
| 2486318* | New Steering Angle Sensor Module Replacement | 0.5 Hrs. |
| *This is a unique Labor Operation for Bulletin use only. | | |

| | |
|----------|--------------------------|
| Version | 1 |
| Modified | Released August 08, 2023 |

