



# TECHNICAL SERVICE BULLETIN

Classification: KS23-004	Reference: NTB23-067	Date: August 29, 2023
-----------------------------	-------------------------	--------------------------

## 2014-2020 ROGUE & 2017-2022 ROGUE SPORT; REPLACEMENT JACKKNIFE (FLIP STYLE) KEYS

**APPLIED VEHICLES:** 2014-2020 Rogue (T32)  
2017-2022 Rogue Sport (J11)

**APPLIED GRADES:** S

### SERVICE INFORMATION

For the **APPLIED VEHICLES** listed above:

- If the jackknife key is replaced with 80560-4BA1E, the new part provided will no longer be equipped with a key blade.
- New service parts will have a keyless entry remote with a separate mechanical key.
- Each vehicle can have a maximum of four (4) keys registered to the BCM. Each service part contains one (1) key and one (1) remote and will use two (2) of the available slots.
- Follow the **SERVICE PROCEDURE** starting on page 2 to register the new mechanical key and remote.



Figure 1

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## SERVICE PROCEDURE

### Key and Remote Registration

1. Adjust the steering column position.
  - a. Release the steering column tilt/telescoping lever.
  - b. Lower the steering column fully by pulling downward on the steering wheel.
  - c. Pull the steering wheel toward the rear of the vehicle until it stops.

**HINT:** Leave the steering column tilt/telescoping lever in the unlocked position.

2. Remove the two (2) steering column cover screws.
  - Turn the steering wheel to the 9 o'clock position and remove the LH steering column cover screw.
  - Turn the steering wheel to the 3 o'clock position and remove the RH steering column cover screw.




Figure 2

3. Disengage the four (4) fixing pawls, and then remove the cluster lid A skirt from the upper steering column cover.




Figure 3

4. Using a suitable tool, carefully separate the upper and lower steering column covers.
5. Remove the upper and lower steering column covers and place in a safe area to prevent damage.

6. Remove the new mechanical key from the key ring.
7. Have the new mechanical key cut using the vehicle's key cut code.



Figure 4

8. Connect the CONSULT PC to the vehicle.
9. Start C-III plus.
10. Wait for the VI to be recognized.
  - The serial number will display when the VI is recognized.
11. Select **Immobilizer**.




Figure 5

12. Follow the screen prompts to navigate to the screen shown in Figure 6.
13. Select **When performing key registration**.
14. Select **Register key**.
  - If needed, refer to the CONSULT III+ Operations Manual for key registration information.




Figure 6

15. Follow the screen prompts to navigate to the screen shown in Figure 7.
16. Insert the new mechanical key and turn the ignition to the ON position to register.
17. Verify the Red Security lamp in the combination meter blinks five (5) times.
18. Once the key is registered, the screen shown in Figure 8 will be displayed.
19. Continue to step 20 to register the new keyless entry remote.




Figure 7




Figure 8

20. Turn the ignition switch to the OFF position and remove the mechanical key from the ignition switch.

21. Remove the NATS antenna amp from the ignition switch while leaving the electrical harness connector connected.

- Lift the two (2) retaining tabs from the NATS antenna amp and slide the NATS antenna amp away from the ignition switch.




Figure 9

22. Register the keyless entry remote.

- a. Select **Add**.
- b. Insert the mechanical key into the ignition switch.
- c. Hold the keyless entry remote in the center of the NATS antenna amp as shown in Figure 11.
- d. While holding the keyless entry remote in the center of the NATS antenna amp, turn the ignition ON.
- e. Verify the Red Security light flashes five (5) times and the screen shown in Figure 10 indicates that two (2) keys have been registered.




Figure 10

23. Turn the ignition OFF.

24. Remove the mechanical key from the ignition switch and reinstall the NATS antenna amp.




Figure 11

25. Repeat key registration for any other remaining keys.
26. Follow the screen prompts to complete key registration and verify the mechanical keys and the keyless entry remotes operate correctly.

## PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
KEY KIT – BLANK, MASTER & FOB	80560-4BA1E	1
Included in kit		
Mechanical Key		1
Remote (Fob)		1

## CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	MODEL	PFP	OP CODE	SYM	DIA	FRT
Register Two (2) Mechanical Keys and Keyless Entry Remotes (Service Part)	Rogue Sport	(1)	SX17AA	ZE	32	0.5
	Rogue					
Register Four (4) Mechanical Keys and Keyless Entry Remotes (Service Part)	Rogue Sport		SX18AA			
	Rogue					

(1) Reference the **PARTS INFORMATION** table above and use the Key Kit (80560-\*\*\*\*\*) as the Primary Failed Part (PFP).

## AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
August 29, 2023	NTB23-067	Original bulletin published