

SIB 62 04 23

2023-08-22

SERVICE ACTION: PROGRAM I20 INSTRUMENT CLUSTER (VISUAL DISCREPANCIES)

☐ THIS REPAIR IS MOBILE FRIENDLY

MODEL

E-Series	Model Description	Production Date
i20	iX Sports Activity Vehicle	June 23, 2023 to July 28, 2023

SITUATION

The customer may notice visual discrepancies in the instrument cluster display or head-up display. These visual discrepancies may come in the form of missing icons, incorrect fonts or incorrectly displayed text.

CAUSE

Due to an error in software logistics, an incorrect software version was programmed on the instrument cluster.

CORRECTION

Program the instrument cluster control module (aka KOMBI).

PROCEDURE

Determine what is the vehicle's current I-level by either using AIR/ ISPA NEXT/AWP (Aftersales Workplace) applications.

When applicable, program the vehicle to I-level I020-23-07-533 or higher using ISTA 4.42.3x (released late July, 2023) or higher.

- Connect the battery charger to the vehicle
- Connect the programming system to the vehicle (ISTA 4)
- Determine measures plan
- Accept and fully work through the measures plan with the control units to be programmed/encoded and enabled
- · Follow the rework list
- Depending on the rework list, carry out a vehicle test and delete the fault memory if needed

After the programming has been fully completed, check the functionality of the system.

Note: ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply (SIB 04 23 10).

For information on programming and coding with ISTA, refer to Dealer Universal Portal / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

CLAIM INFORMATION

Vehicle Programming and Encoding

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Select one of these open Technical Campaigns to perform and submit for updating the vehicle to the required I-level or higher.

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

As determined by the above, reimbursement for this Service Action will be via normal claim entry utilizing the work package information below that applies.

Below are the special flat rate labor operation code choices for this action.

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 74 941	Programming and encoding the vehicle control units (instrument cluster), includes Carrying out vehicle test (00 00 556/61 21 528)	9 FRU
Or:			
# 2	00 74 942	Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to or during this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU

Or:

The vehicle arrives at your center and this Service Action shows open (No other Main work will be performed or claimed during this workshop visit)

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
#3	00 74 295	Programming and encoding the vehicle control units (instrument cluster), includes Carrying out vehicle test (00 00 006/61 21 528)	11 FRU
Or:			
# 4	00 74 296	Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B62 04 23 WP 1), unless otherwise required by State law.

Programming and Encoding – Additional Work (RO and Claim Comments Required)

Copyright ©2023 BMW of North America, Inc.

about:blank 2/4

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Repair Code in this bulletin with the labor operations that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Repair Code and labor operation codes (including the diagnosis*) that applies.

Based on which one applies to your center, please refer to **SI B01 01 20 or B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your	
	feedback in the rating box at the top of this bulletin	
	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS	
Warranty Feedback	ticket to the Warranty Department, or use the chat available in the	
	Warranty Documentation Portal	
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS	
	ticket to the Parts Department	