STELLANTIS PARTS & SERVICES		Technical Service Bulletin (TSB) Telematics Box Module (TBM) wiTECH update to 4.36				
REFERENCE:	<b>TSB</b> : 08-174-23 <b>GROUP</b> 08 - Electrical	Date:	July 15, 2023	REVISION:	_	
VEHICLES AFFECTED:	This bulletin applies June 15, 2023 (MDH	2021 - 2023 (WD) Dodge Durango This bulletin applies to vehicles built on and before June 15, 2023 (MDH 0615XX) equipped with the following: Global Telematics Box Module (Sales Code RDG).			CABILITY:	
CUSTOMER SYMPTOM:	<ul> <li>Uconnect box</li> <li>Uconnect box</li> <li>WiFi hotspot s</li> <li>Rear mirror LE</li> <li>Uconnect App</li> </ul>	<ul> <li>Customers may experience one or more of the following:</li> <li>Uconnect box requires service message (Fig. 1) .</li> <li>Uconnect box backup "battery low" message on the radio.</li> <li>WiFi hotspot streaming lost.</li> <li>Rear mirror LED blinking after ignition cycle.</li> <li>Uconnect App charge schedule / climate schedule setup issue.</li> <li>Customer not seeing profile or other vehicle information on the mobile app.</li> </ul>				




Fig. 1
Uconnect Box Error Message

Message display on the radio screen, "Uconnect Box requires service. Please visit an authorized dealer." (Fig. 1), with no active or stored Diagnostic Trouble Codes (DTC)s set by the TBM.

NOTE: "Uconnect Box requires service." message can be triggered by different reasons. For an issue on a new vehicle recently switched to customer mode, please follow the New Vehicle Preparation procedure to resolve the issue. For the customer vehicle with intermittent concerns, please check the TBM, antenna and instrument panel harness connections to fix related DTC issues.

# **REPAIR SUMMARY:**

This bulletin involves updating the TBM software from 4.27i to 4.36.

**TBM Software** 

CAUSE:

#### **CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-F5-91	Telematics Box Module, Perform Software Update (0 - Introduction)	6 - Electrical and Body Systems	2.9 Hrs.
Failure Code	CC	Customer Concern	

### The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

# **DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

#### SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	_	_

# **REPAIR PROCEDURE:**

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

- 1. Reprogram the TBM 2.0 with the latest software 4.36. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
- 2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

#### **POLICY:**

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.