

Technical Service Bulletin (TSB)

Noise When Turning

REFERENCE:	TSB: 02-004-23 REV. A GROUP 02 - Front Suspension	Date:	July 7, 2023	REVISION :	02-004-23	
VEHICLES AFFECTED:	2022 - 2023 (D2) RAM 3500 Pickup This bulletin applies to vehicles built or (MDH 0315XX) equipped with the 6.7L l Engine (Sales Code ETL).			MARKET AF ⊠ **NA ** □EE ⊠SA	PLICABILITY: CH IAP MEA	
CUSTOMER SYMPTOM:	The technician or customer may notice the following:Front suspension squeaking noise when turning the steering wheel.					
CAUSE:	Not enough space between two frame s	sections.				

This bulletin supersedes Technical Service Bulletin (TSB) 02-004-23, date of issue June 15, 2023, which should be removed from your files. All revisions are highlighted with **asterisks** and include an updated region.

REPAIR SUMMARY:

This bulletin involves creating a space between two frame sections and adding wax.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
02-20-03-95	Create A Greater Space At Trackbar Support Mount and add wax (1 - Semi-Skilled)	2 - Front Suspension	1.30 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)		WAX TUNAP 299 Leaf spring protection (Only warranty reimbursement, do not order part)	

DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

- 1. Raise and support vehicle. Refer to the detailed service procedures listed in DealerCONNECT>Service Library under: Service Info>04 Vehicle Quick Reference / Hoisting / Standard Procedure.
- 2. Clean suspension and frame area prior to disassembly. Remove trackbar and trackbar mount (Fig. 1) .




Fig. 1 Trackbar and Trackbar Mount

1 - Trackbar

2 - Trackbar Mount

3. Insert a screwdriver or long chisel between frame sections above trackbar mount as shown in (Fig. 2) :




Fig. 2 Screwdriver Or Chisel Placement

4. Drive the screwdriver or chisel forward with a hammer to create a space between the two frame sections.

CAUTION! Avoid material removal or damage.

5. Ensure there is a 5 - 10 mm (3/16 - 3/8") gap between the frame sections.

6. Apply wax to area shown (TUNAP 299) to the newly opened frame sections (Fig. 3) .




Fig. 3 Wax Area

7. Apply tape to the waxed area (Fig. 4) .

NOTE: Be careful to not disturb the wax when installing the tape.



Fig. 4 Wax/Tape Area

8. Reinstall the trackbar and trackbar mount (Fig. 1) .

02-004-23 REV. A

9. **Hand tighten** all the trackbar mount - to - frame fasteners and the trackbar - to - mount fastener (Fig. 5) .




Fig. 5 Trackbar And Trackbar Mount

- 1 Trackbar to Trackbar Mount Fastener
- 2 Trackbar to Frame Fasteners
- 10. Torque the two right hand mount fasteners first to 175 N·m (129 Ft. Lbs.) (Fig. 6) .




Fig. 6 Trackbar Mount

1 - Right Hand Fasteners

- 11. Torque the remaining three trackbar mount fasteners to 175 N·m (129 Ft. Lbs.).
- 12. Lower the vehicle completely to put full vehicle weight on the ground.
- 13. Torque the one trackbar to trackbar mount fastener to 387 N·m (285 Ft. Lbs.) (Fig. 5) .

NOTE: Allow 24 hours before returning the vehicle to the customer for the wax to cure.

14. Test drive vehicle and ensure noise is no longer present.

POLICY:

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

Reimbursable within the provisions of the warranty.