

Release date:

Transaction No:

9/5/2023

Condition

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All Models (Except ID.4)	2018- <mark>2024</mark>	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2049039/19	9/5/2023	87-18-08	To update model year applicability and flush machine filter cost claiming
2049039/17	11/9/22	87-18-08	To update model year applicability and front bumper claiming instruction.
2049039/15	12/13/21	87-18-08	Adding MY 2021 Atlas and Coupe bumper removal labor operation and updating note for 2021 Atlas and Coupe since 3/1/2021.
2049039/14	9/9/21	87-18-08	Add "Atlas only" to clamping washer in parts table.
2049039/1	11/9/17	V871713	Original publication.

Debris can be dispersed throughout the refrigerant circuit after A/C component damage. In order to maintain A/C operating efficiency, it is important to flush the refrigerant circuit after A/C component repairs.

Technical Service Bulletin



87-18-08 - Air Conditioning, Cleaning of the R1234yf Refrigerant Circuit (U.S. Only)

Release date:

Transaction No:

9/5/2023

2049039/19



Note:

This bulletin must be read in its entirety before beginning repair.

Technical Background

In cases where an air conditioning system component (such as a compressor or other system component) has failed and debris from the compressor or component is circulated throughout the refrigerant circuit, the refrigerant circuit must be cleaned of any and all debris or damage to the replacement components will result.



Any replacement of A/C compressors-regardless of the reason for failure must complete the A/C flush procedure to ensure the proper amount of oil is re-introduced into the refrigerant system.

Production Solution

No production change required.



Release date:

Transaction No:

9/5/2023

Service

Tools



Use an approved R1234yf servicing machine and the R1234yf Flush Kit RTI360831840 (Figure 1).

Used for effective refrigerant handling and air conditioning circuit flushing after air conditioning component failure.

Figure 1. The VAS581005 Air Conditioning Service System with Flushing Device.

The VAS 6338/1 Adapter Set for Refrigerant Circuits along with an additional adapter VAS 6338/38 for the expansion valve bypass this kit, contains the adapters necessary to complete a thorough flush operation of a contaminated circuit.

Elsa contains the technical information for each model regarding the necessary adapter applications and connections of the servicing station for the flush operation. See Heating, Ventilation & Air Conditioning >> Refrigerant R1234yf-Servicing >> 00 General Technical Data>> Refrigerant Circuit removing contaminates>> Refrigerant Circuit, Flushing with Refrigerant R1234yf in Elsa.

All other refrigerant recovery, evacuation and recharge operations are performed using the usual procedure specified in Elsa. An operations manual will accompany each servicing station that will describe operation of the unit.

Technical Service Bulletin



87-18-08 - Air Conditioning, Cleaning of the R1234yf Refrigerant Circuit (U.S. Only)

Release date:

Transaction No:

9/5/2023

2049039/19

Procedure

Front A/C:

- 1. If an air conditioning component has been diagnosed as the root cause of the failure, and this particular component has been verified to have released debris through the circuit, continue with the flush procedure.
- 2. Switch the power to the servicing station ON and begin by recovering the refrigerant from the system through the normal service fittings.



Note:

For all compressor replacements it is mandatory to flush the system of all oil in the system. The replacement compressor comes with a full charge of oil for a complete A/C system.



Tip:

During the entire process avoid interrupting the power to the station. The station's internal memory will keep a log of all operations and can conveniently be recalled and printed. If the power is interrupted, the station will lose the memory of the process, and the oil volume recovered, oil volume added, refrigerant volume recovered, etc. will have to be manually determined.

3. Disconnect the service hoses from the AC service ports of the refrigerant circuit.

The VAS 6338/1 adapters will be used to bypass the following:

- Compressor.
- Expansion Valve.
- Rear AC lines to rear AC unit (If Equipped)
- Rear AC unit Expansion Valve (If Equipped)



Note:

For models with receiver drier desiccant cartridge the desiccant cartridge <u>must</u> be removed for the flushing process.

For vehicles where the receiver drier is located on the condenser and DOES NOT have a remove-able desiccant cartridge, the receiver drier must be left in the system and flushed through.

After the flush procedure is complete replace the receiver drier or drier cartridge.

- 4. Install the approved R1234yf servicing machine.
- 5. Remove Receiver Drier. Refer to Elsa Repair Manual.



Release date:

Transaction No:

9/5/2023



Note:

For Atlas MY2018-2020, the front bumper <u>does not</u> need to be removed as stated in the Elsa repair manual. Since 3/1/2021, MY2021 Atlas and Cross Sport the bumper must be removed.

When removing front grille ensure ignition is switched OFF and negative battery cable is disconnected before disconnecting the front distance regulation module.




Figure 2. Location of the Receiver Drier

6. Remove receiver drier cartridge.

Reinstall cartridge cap with O-ring. (Figure 2)



9/5/2023 Release date:

Transaction No:



Figure 3. Installation of front expansion valve bypass adaptor VAS 6338/38.

7. Remove expansion valve and install flush plate VAS 6338/38. (Figure 3)



Figure 4a. Installation of high side rear A/C Line connection block adaptor VAS 6338/63.



Note:

(Atlas Only) The rear A/C unit refrigerant lines must be disconnected and replaced with block off adaptors VAS 6338/5 and VAS 6338/63 before performing the front A/C unit flush procedure.

8. (Atlas Only) Disconnect rear refrigerant lines and install adaptors VAS 6338/5 and VAS 6338/63 as shown. (Figure 4a, 4b)



Release date:

Transaction No:

9/5/2023



Figure 4b. Installation of Low side rear A/C Line connection block adaptor VAS 6338/5.



Figure 5. A.C hose adaptor 6338/44.

9. Remove A/C Recovery machine high side coupler from hose.

Install flush adaptor VAS 6338/48 to high side A/C recovery machine hose. (Figure 5)



Note

You do not have to remove low side A/C hose coupler. The low side coupler will be connected to the flush tank filter adaptor.



Release date: 9/5/2023

Transaction No:



Figure 6. Installation of VAS 6338/3 and 6338/12.

10. Disconnect A/C compressor hoses from the compressor.

Install flush adaptor VAS 6338/3 on the high side compressor hose.

Install flush adaptor VAS 6338/12 on low side compressor hose. (Figure 6)



Figure 7.

11. Attach high side A/C Recovery machine hose with VAS 6338/48 fitting to low side compressor hose adaptor VAS 6338/12. (Figure 7)



Note:

This connection strategy allows for a system flush *in the opposite* direction of the normal refrigerant flow.



Release date:

Transaction No:

9/5/2023



12. Connect the low side A/C machine coupler to the flush tank filter adaptor. (Figure 8)

Figure 8.



13. Connect flush tank hose (Yellow) to the high side compressor hose adaptor VAS 6338/3. (Figure 9)

Figure 9.

- 14. Perform an extended 3 cycle flush.
- 15. After the flush process completes remove any adapters that were installed from the VAS 6338/1.
- 16. (Atlas Only) Proceed to section for cleaning the rear A/C unit. All others models continue to step 17.

Technical Service Bulletin



87-18-08 - Air Conditioning, Cleaning of the R1234yf Refrigerant Circuit (U.S. Only)

Release date:

Transaction No:

9/5/2023

2049039/19


- 17. Install a new Expansion Valve and Receiver Drier Cartridge. Reassemble all refrigerant lines.
- 18. Print the extended flush log of the job and attach to the repair order.
- 19. Connect the station in the usual manner through the service fittings and perform the normal evacuation and refrigerant recharge operations.



For Atlas a rear A/C unit flush must be performed before vacuum testing and recharging.

Atlas Rear A/C Unit

The flush process will be repeated for the additional rear air conditioning unit according to the repair information in Elsa.



20. Lower the exhaust by removing the rear exhaust clamp and single rubber hanger. (Figure 10)

Figure 10.



Release date:

Transaction No:

9/5/2023



21. Remove the cross bar located in the center under carriage area. (Figure 11)

Figure 11.



Figure 12.

22. Remove middle heat shield from under previously removed cross bar to access rear expansion valve. (Figure 12)



Replace the clamping washer before reinstalling the heat shield.



Release date:

Transaction No:

9/5/2023



Figure 13. Location of rear air conditioning unit expansion valve.

23. Remove rear expansion valve and install VAS6338/38 as shown. (Figure 13)



24. Connect the VAS 6338/3 and VAS 6338/60 to the rear refrigerant A/C lines. (Figure 14)



Release date:

Transaction No:

9/5/2023



Figure 14. Location and connection of the adaptors for the rear unit A/C lines



Figure 15. Removal of dowel pin.



Later models may have a dowel pin in the high pressure refrigerant line that does not allow the VAS 6338/60 to be installed. The pin must be temporarily removed to install the VAS 6338/60. DO NOT cut the pin flush with the refrigerant. Side cutters can be used to remove the pin and pliers to reinstall the pin (Figure 15 and 16).



Release date:

Transaction No:

9/5/2023



Figure 16. Installation of rear refrigerant line dowel pin.



- 25. Connect the VAS 6338/48 to adaptor VAS 6338/60.
- 26. Connect flush tank hose (Yellow) to the high side compressor hose adaptor VAS 6338/3. (Figure 17)



Note:

Reverse flushing not required for rear A/C unit cleaning.



Release date:

Transaction No:

9/5/2023



Figure 17. Attaching service station and flush hoses to rear A/C lines.

27. Perform an extended 3 cycle flush on the rear A/C unit.



Note:

Do not use the short flush option in the ACX1281 service menu. This is for clearing the ACX1281 machine hoses only and does not flush the vehicle refrigerant system.

- 28. When complete, remove any adapters that were installed from the VAS 6338/1.
- 29. Install a new rear Expansion Valve and reinstall all the refrigerant lines.
- 30. Connect the station in the usual manner through the service fittings and perform the normal evacuation and refrigerant recharge operations.
- 31. Print the extended flush log of the job and attach to the repair order.
- 32. Connect the station in the usual manner through the service fittings and perform the normal evacuation and refrigerant recharge operations

A/C Components Replacement

The following components must be replaced:

- Expansion Valve
- Rear Expansion Valve (If equipped)
- Receiver-drier/cartridge



Release date:

Transaction No:

9/5/2023

Warranty



The procedure outlined in this Technical Bulletin must be included with the warranty repair(s) and not claimed independently.

You may claim \$11.20 per A/C System flush for the A/C System Flush filter 0268056100 (which represents 1/5 the cost of a replacement filter)

A print out from the approved R1234yf servicing machine of the flush procedure must be attached to the warranty claim.

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
All Models (Except ID.4)	2018-2024	All	All	All	All

SAGA Coding

Claim Type:	aim Type 1)			
Service Number:	Damage Code	нѕт	Damage Location (Depends on Service No.)	Parts Manufacturer (removed part)
Use Service Number of Defective Component	Use damage code appropriate for root cause of failure		Use applicable when indicated in Elsa (L/R)	Use Vendor code from failed component
·			•	

Labor Operation 3): Refrigerant drain and fill (Except Atlas)	8703XXXX = Claim appropriate SRT for vehicle and engine in Elsa
Labor Operation ³⁾ : Air Conditioner Check, All Vehicles. (Except Atlas)	87010150 = See Elsa for the latest time units



9/5/2023 Release date:

Transaction No:

Labor Operation 3): Air Conditioner Clean, All Vehicles, Front A/C only (except Atlas)		87012999 = 11	0 TU
· · · · · · · · · · · · · · · · · · ·		8755XXXX = C engine in Elsa	laim appropriate SRT for vehicle and
Labor Operation 3): Replace Explif equipped. (Except Atlas)	pansion Valve,	8770XXXX = C engine in Elsa	laim appropriate SRT for vehicle and
Labor Operation 3): R/I Front Bu	mper		laim appropriate SRT for vehicle and per model applicability.
	Atlas wi	th Rear A/C uni	t.
Labor Operation 3): Refrigerant	drain and fill	87031700 = Se	e Elsa for the latest time units
Labor Operation 3): Air Condition	ner Check	87010150 = Se	e Elsa for the latest time units
Labor Operation 3): Air Condition	ner Clean	87013099 = 30	0 TU
Labor Operation 3): R/I Front Bumper			laim appropriate SRT for vehicle and per model applicability.
Labor Operation 3): Front grille remove and reinstall.		66051999 = 20	TU
Labor Operation 3): Replace Receiver-Drier		87555550 = Se	e Elsa for the latest time units
Labor Operation 3): Replace Exp	ansion Valve	87701950 = Se	e Elsa for the latest time units
Labor Operation 3): Replace Rear Expansion Valve		88701900 = Se	e Elsa for the latest time units
	Α	II Vehicles	
Outside Material: R1234yf Flush Kit filter 0268056100			/C System Flush which accompanies a bunt equals 1/5 of the cost of the A/C ilter)
	Diag	nostic Time 4)	
GFF Time expenditure	01500000 = 00	0 TU max.	NO
	_	47 of 00	



Release date:

Transaction No:

9/5/2023

Road Test	01210002 = 00 TU 01210004 = 00 TU	NO
Technical Diagnosis	01320000 = 00 TU max.	NO

Claim Comment: Input "As per Technical Bulletin 2049039" in comment section of Warranty Claim.

Required Parts and Tools

Part Description	Part No:	Quantity
Receiver-Drier	Vehicle Specific	1
Expansion Valve	Vehicle Specific	1
Rear Expansion Valve (Atlas only)	3QF820712A	1
Self-locking bolt	WHT000729A	3
Rivet (if unable to be re-used)	N 0385494	1
Clamping Washer (Atlas only)	N 90335004 with WHT003386	1

¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.

⁴⁾ Documentation required per Warranty Policies and Procedures Manual.



9/5/2023 Release date:

Transaction No:

Tool Description	Tool No:
Air Conditioning Service System	MAHLE R1234yf A/C Service Unit
	VAS581005
N BE	Or
O Car	Robinair R1234yf - ROB1234YFX
MASS MILLOW	Or
marks	MAHLE RTI4608046401
	Or
	Ecotechnics EEAC830BVW
6	
	R1234yf Flush Kit
	RTI360831840
Air Conditioning System Flushing Device Filter	R1234yf Air Conditioning Unit - Filter - External Flush
	Item: 0268056100



Release date:

Transaction No:

9/5/2023

Adapter set for refrigerant circuits VAS1785/3 /21 VAS1785/5 VAS1785/1 VAS1785/1 VAS1785/8 123 124 125 130 VAS1785/8 124 125 130 131 16 18 17 18 17 18 17 18 17 18 17 18 18 19 19	VAS 6338/1
Refrigerant circuit adapter for MAHLE A/C Service Unit and R1234yf Flush Kit	VAS6338/48
Refrigerant circuit adapter for expansion valve bypass	VAS6338/38



Release date:

Transaction No:

9/5/2023

Refrigerant circuit adapter for expansion valve bypass	VAS 6338/18
Adapter bypass for A/C compressor line	VAS 6338/3
Adapter bypass for A/C compressor line	VAS 6338/12



9/5/2023 Release date:

Transaction No:

·	
Additional adapter bypass for Atlas rear A/C unit high side rear line.	VAS 6338/60
Additional adapter for Atlas rear A/C line block off.	VAS6338/63
Ace I may ear	
Additional adapter bypass for Atlas rear A/C unit low side rear line.	VAS 6338/3



Release date: 9/5/2023

Transaction No:

Additional adapter for Atlas rear A.C line block off.	VAS6338/5

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.