

Technical Service Bulletin

48 Steering: rattling noise at full steering lock

48 23 55 2071439/1 September 13, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7, SQ7, Q8, SQ8, and RS Q8	2022 – 2024	All	Not Applicable

Condition

Customer states:

• There are rattling noises/vibrations when turning the steering wheel to full lock.

Workshop findings:

• The complaint can be reproduced.

Technical Background

Not applicable.

Production Solution

New parameter set introduced in production in August, 2023.

Service

Please perform the following test with ODIS SVM - Check Control Module Configuration (address word 0044).

Warranty

Claim Type	• 110 Up to 48 Months/50,000 Miles		
	G10 for CPO Covered Vehicles – Verify Owner.		
	 If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	4835		
Damage Code:	0020		

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 30 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2071439/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2071439**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.