



STAR ONLINE PUBLICATION



Case Number: S2308000053 Rev. A

Release Date: August 2023

Symptom/Vehicle Issue: Traffic Sign Recognition (TSR) Speed Displayed on the Cluster Does Not Match the Actual Speed Limit Sign

Customer Complaint/Technician Observation: Owner complaint, when using the TRS system the cluster displays a speed limit sign showing a different speed then the posted speed limit sign for the area; or at times the change is slow to update to the correctly posted speed limit sign. Technician observed the same on certain roads.

Discussion: Do not replace any parts for this concern, replacement parts will perform the same. Engineering is requesting the Half module software to be updated for this this concern. Update the Half module, see TSB 08-132-23 to ensure the newest software version has been applied and the vehicle has been proxi aligned to complete.



Incorrect speed for NAFTA – Displays European speed limit.

Correct

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found