



Service Bulletin

Bulletin No.: 23-NA-173

Date: September, 2023

TECHNICAL

Subject: Radio Software Version 170.5.1-M166-SQBR3-187.1 – Multiple Updates for Infotainment System RPO IVD

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	LYRIQ	2023	2023	—	—	—	—

Involved Region or Country	North America
Condition	Some customers may comment on software related issues. Continuous improvement software updates are being released with improvements made in several areas.
Cause	The cause of the condition may be software anomalies.
Correction	<p>A new radio software update, version 170.5.1-M166-SQBR3-187.1, was released to service for vehicles equipped with Infotainment system RPO IVD being brought into the service department. In addition to providing general robustness and stability enhancements, this update includes all enhancements from previous software version releases. Along with the vehicles mentioned above; fleet customers may need the dealer to reprogram the radio with the new software package.</p> <p>This new radio software update has been released via an Over-the Air-Update. the customer will receive a Software Update notification once the software has been downloaded to their vehicle. Customers need to accept the OTA when prompted.</p> <p>Caution: To avoid potential programming errors, ensure both programming events (Programming and USB File Transfer) are performed.</p> <p>Important: Improvements will vary by model, build configuration, system, and sales region. Not all vehicles have all features.</p> <p>For proper programming instructions, refer to the latest versions of PIC6488 for correct programming steps and PIT6047 for the battery ignore file creation.</p>

Most notable improvements contained in this release may include:

A. Radio:

- General Stability Improvements
- No audio.
- Rear view camera does not work or shows red triangle.
- Android System doesn't boot/slow to boot, sometimes shows "Android System" message.
- OnStar Turn by Turn Connection Fails or Shows Incorrect Information.
- Camera app not showing the correct image or icons.
- Window/app sizing and screen quality.
- Vehicle info data inconsistent.
- IPC/ICS info does not match.
- Google Assistant pop up/icon sticks.
- Scroll bar does not quickly follow finger.
- Radio favorites not working.
- Steering wheel switch not functioning.
- Camera app stuck.

- Saved contacts don't display on both screens.
- User data/settings not saved.
- Service Vehicle Display alert with U3000.55.
- Audio source changes after sleep cycle.
- Teen driver audio mute not functioning.
- Google maps layout incorrect in custom view.
- Can't launch Android Auto/Apple CarPlay.
- Audio source switches without user input.
- SXM loading message.
- Left side of efficiency screen distorted.
- Virtual headlights pop up overlaps.
- Media Menu Selection Unresponsive.
- Can't exit virtual controls.
- MFC cannot select rear camera views.
- Can't launch drive mode app.
- Missing assistant/app settings.
- Choppy audio when starting.
- Missing button text in SXM app.
- SXM stuck in demo mode but plays music.

- Missing door ajar indicator in cluster.
 - Universal remote menu selections not functioning.
 - Missing scroll bars in menus.
 - Wi-Fi goes down after a few minutes.
 - Missing system settings.
 - Radio display shakes horizontally.
 - Native assistant activates instead of Android Auto assistant when in Android Auto.
 - Repeat advisor call doesn't show call screen.
 - Navigation apps missing compass.
 - RVC screen intermittent flickering.
 - Auto Park assist not available.
 - Can't scroll device selection.
 - No notification for "Key Not Detected."
 - Share Hotspot data option greyed out.
 - AM tune page shows "No Stations Available."
 - Factory reset failure.
 - Google navigation pop up flickering.
 - SXM not updating.
 - OnStar call stuck on cluster.
 - SXM tabs flicker.
 - App tray doesn't retain camera.
 - Text pop up doesn't come up on radio display.
 - Phone call pop up not displayed.
 - Vehicle odometer not increasing intermittently.
 - Podcast slider disappears.
 - Volume increases without user input.
 - Power knob flickering.
 - FM cuts out when opening audio app.
 - Projection Audio pops and clicks.
 - Projection device name not showing.
 - No touch response on radio display.
 - Album art not loading.
 - Notification window doesn't disappear.
- B. Phone:**
- Phone connection stability.
 - Projection drops and does not/is slow to connect/reconnect.
 - Android Auto/CarPlay black screen.
 - Cannot add/connect Bluetooth device, sometimes Add Phone Button Greyed Out.
 - Can't launch Android Auto/Apple CarPlay.
 - CarPlay stability improvements.
 - App icons incorrect with CarPlay.
 - Media app not showing BT paired phone.
 - Wired projection pop ups cannot be dismissed automatically.
 - CarPlay audio heard from phone after call ends.
 - CarPlay navigation disappears.
 - Bluetooth pairing screen stuck up.
 - CarPlay missing navigation trip info.
 - CarPlay Home Page scroll inoperable.
- C. Display:**
- Cluster black screen.
 - Display flickering.
 - HUD layout/Settings not remembered.
 - Blank speedometer.
 - HUD does not show navigation information.
 - Route in native navigation doesn't show after ignition cycle.
 - When exiting Android Auto, the screen flashes.
 - Trip reset button does not highlight when pressed.
 - Hazards turn off incorrectly.
 - Both displays blank at start up.
 - High voltage telltale on incorrectly.
 - Speedometer missing when changing display layout.
 - Vehicle graphic has bad quality.
 - Cluster gauge bars turn red incorrectly.
 - Wi-Fi list flickers.
 - Missing speed limit.
 - Hazards indicators don't show during welcome animation.
 - Cluster map view not available.
 - HUD text overlapping.
- D. Programming:**
- Blank cluster screen after programming.
- E. Charging App:**
- Charging app black screen.
 - Charging app descriptions updated.
 - Battery charging features/info not appearing.
 - Charging app time to charge bad text icons.
 - Charging app shows unavailable dates.
 - Charging app won't work.
 - Charging app charge now/later time doesn't match in IPC/ICS.
 - Peak in charging complete time is not correct.
 - Charging app delay charging time wrong format.
 - Charging app flickers.
 - Charging app lock out not holding.
- ## Service Procedure
- Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**
- Important:** This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment

requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.


Caution: Before downloading the update files, be sure the computer is connected to the internet through a network cable (hardwired). DO NOT DOWNLOAD or install the files wirelessly. If there is an interruption during programming, programming failure or control module damage may occur.

- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to www.gmdesolutions.com for further information. If not available, connect a fully charged 12V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Follow the on-screen prompts regarding ignition power mode, but ensure that anything that drains excessive power (exterior lights, HVAC blower motor, etc) is off.
- Please verify that the radio time and date are set correctly before inserting USB drive into vehicle for programming, **otherwise an error will result.**
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.

Important: The service technician always needs to verify that the VIN displayed in the TLC left side drop down menu and the top center window match the VIN plate of the vehicle to be programmed prior to using Service Programming System 2 (SPS2) for programming or reprogramming a module.


- For the TLC application, service technicians need to always ensure that the power mode (ignition) is "ON" before reading the VIN from the vehicle's VIN master module and that they do not select a VIN that is already in the TLC application memory from a previous vehicle.
- If the VIN that shows up in the TLC top center window after correctly reading the VIN from the vehicle does not match the VIN plate of the vehicle, manually type in the VIN characters from the vehicle VIN plate into the TLC top center window and use these for programming or reprogramming the subject module with the correct vehicle VIN and software and/or calibrations.
- The Engine Control Module (ECM) is the master module (for VIP vehicles) that TLC reads to determine the VIN of the vehicle. If the VIN read from the vehicle by TLC does not match the VIN plate of the vehicle, the ECM also needs to be reprogrammed with the correct VIN, software and calibrations that match the vehicle's VIN plate.
- The Body Control Module (BCM) is the master module (for GEM vehicles) that TLC reads to determine the VIN of the vehicle. If the VIN read from the vehicle by TLC does not match the VIN plate of the vehicle, the BCM also needs to be reprogrammed with the correct VIN, software and calibrations that match the vehicle's VIN plate.

Caution: Be sure the VIN selected in the drop down menu (1) is the same as the vehicle connected (2) before beginning programming.




5743643

Important: If the vehicle VIN DOES NOT match, the message below will be shown.



5877000



Important: Techline Connect screen shown above.

Important: If the same calibration/software warning is noted on the TLC Summary screen, select OK and follow screen instructions. After a successful programming event, the WCC is located in the Service Programming System dialogue box of the SPS

5644477

Summary screen. Record the WCC on the job card. No further action is required. Refer to the Warranty Information section of this bulletin.

1. Reprogram the radio. Refer to the latest version of PIC6488 for programming procedure.



5644478

Note: The screenshot above is an example of module programming and may not be indicative of the specific module that is being programmed. Module selection and VIN information have been blacked out.

Important: To avoid warranty transaction rejections, you **MUST** record the warranty claim code provided on the Warranty Claim Code (WCC) screen shown above on the job card. Refer to callout 1 above for the location of the WCC on the screen.

2. Record the SPS Warranty Claim Code on the job card for warranty transaction submission.


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.


Labor Operation	Description	Labor Time
2889848*	Program Radio to 170.5.1-M166-SQBR3-187.1 Via USB/SPS	0.6 hr

*This is a unique Labor Operation for bulletin use only.

Important: To avoid warranty transaction rejections, carefully read and follow the instructions below:




Labour Time [\[Top\]](#)
 Labour Operation Code:
 Additional labour op code information: SPS Warranty Claim Code:



6125814

- The Warranty Claim Code must be accurately entered in the “Warranty Claim Code” field of the transaction.
- When more than one Warranty Claim Code is generated for a programming event, it is required to document all Warranty Claim Codes in the “Correction” field on the job card. Dealers must also enter one of the codes in the “Warranty Claim Code” field of the transaction, otherwise the transaction will reject. It is best practice to enter the FINAL code provided by SPS2.

Warranty Claim Code Information Retrieval



6125774

If the Warranty Claim Code was not recorded on the Job Card, the code can be retrieved in the SPS2 system as follows:

1. Open TLC on the computer used to program the vehicle.
2. Select and start SPS2.
3. Select Settings (1).
4. Select the Warranty Claim Code tab (2).

The VIN, Warranty Claim Code and Date/Time will be listed on a roster of recent programming events. If the code is retrievable, dealers should resubmit the transaction making sure to include the code in the SPS Warranty Claim Code field.

Version	1
Modified	Released September 25, 2023

