Technical Service Bulletin

57J3 UPDATE

Door Seam Cavity Sealing – (NVLW)



Applicable Vehicles						
Country Beginning Model Year		Ending Model Year	Vehicle	Vehicle Count		
USA	2022	2022	GOLF R	583		
USA	2022	2022	GTI	1,970		
CAN	2022	2022	GOLF R	276		
CAN	2022	2022	GTI	267		

Revision History			
Revision	Date	Purpose	
1	October 12, 2023	Original publication	

Condition/Technical Background

This Update has been proactively released to prevent the following condition(s) from occurring in the vehicle:			
Criteria	Criteria Technical Background		
01	On Golf vehicles of a limited production period, there may be insufficient cavity sealing of the door seam area. This may cause corrosion of the doors over time.		

Remedy

Crite	eria	Remedy	
01	1	Apply cavity wax to the affected areas on all four door cavities.	

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the **57J3** code in the ELSA Campaign/Action Information screen on the day of repair.
- Vehicle must be within the New Vehicle Limited Warranty (NVLW).
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

October, 2023 57J3 Page 1 of 7

Technical Service Bulletin

57J3 UPDATE


Door Seam Cavity Sealing – (NVLW)




Service

NOTE:

- ELSA is the only valid inquiry/verification source. Check ELSA on the day this vehicle UPDATE will be performed to verify vehicle eligibility for the UPDATE. Status must show "open". Attach an ELSA printout showing the "open" status to the repair order.
- If this UPDATE appears to have already been performed but the code still shows open in ELSA, contact
 Warranty before proceeding further. Another dealer may have recently performed this UPDATE but not
 yet entered a claim for it in the system.
- ELSA may also show additional open action(s); if so, inform your customer this work can be done while the vehicle is in for this UPDATE.
- Contact the Warranty Helpline (U.S.) or the Warranty Campaign Specialist (Canada) if you have any questions.





 Enter the VIN in ELSA and proceed to the "Campaign/Action" screen.

i TIP

On the date of repair, print this screen and keep a copy with the repair order.

- Confirm the Campaign/Action is open <arrow 1>. If the status is closed, no further work is required.
- Note the Applicable Criteria ID <arrow 2> for use in determining the correct work to be done and corresponding parts associated.



All Safety Recalls must be completed prior

to completing this campaign.

date <arrow 3>. The oldest should be performed

October, 2023 57J3 Page 2 of 7

Technical Service Bulletin


57J3 UPDATE

Door Seam Cavity Sealing – (NVLW)



U NOTE

- Damages resulting from improper repair or failure to follow these work instructions are the dealer's responsibility and are not eligible for reimbursement under this action.
- Diagnosis and repair of pre-existing conditions in the vehicle are not covered under this action.



- Remove both front and rear supports for door components per the ELSA repair manual:
 - Front doors: Repair manual > Body >
 Body Exterior > 57 Front Doors,
 Central Locking System > Door
 Components > Support for Door
 Components, Removing and Installing
 - Rear Doors: Repair manual > Body >
 Body Exterior > 58 Rear Doors > Door
 Components > Support for Door
 Components, Removing and Installing

i TIP

The glass panels in the doors do not have to be removed. Once loosened from the door component support, raise the glass panel all the way up and apply adhesive tape to hold it in place.



 Apply cavity wax to the inside of all four doors at the lower seams in the area indicated <arrows>.

U NOTE


The cavity wax should be applied the length of the seams.

Technical Service Bulletin

57J3 UPDATE

Door Seam Cavity Sealing – (NVLW)





! NOTE

The area where cavity wax is to be applied **INSIDE** the door <1> is shown from the outside for clarity. **CAVITY WAX IS ONLY TO BE APPLIED INSIDE THE DOOR, NOT THE OUTSIDE!**



① NOTE

The area where cavity wax is to be applied **INSIDE** the door <1> is shown from the outside for clarity. **CAVITY WAX IS ONLY TO BE APPLIED INSIDE THE DOOR, NOT THE OUTSIDE!**

- Reassemble in reverse order of removal.
- Clean any excess wax leaking from the door drains using isopropyl alcohol as needed.
- Replace any damaged door panel clips as needed.
- If the ignition is switched on during the repair, faults may be generated.
 - Clear the fault memory after the repair if necessary.

October, 2023 57J3 Page 4 of 7

Technical Service Bulletin

57J3 UPDATE

Door Seam Cavity Sealing – (NVLW)



Claim Entry Instructions

After Update has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the ELSA screen print showing action *open on the day of repair* to the repair order.

If customer refused campaign work or vehicle is out of the specified warranty parameter for this Update:

- ✓ <u>U.S. dealers:</u> Submit request via WISE under the *Campaigns/Update/Recall Closure* option.
- ✓ <u>Canada dealers:</u> Upload the repair order [signed by customer] to Volkswagen WIN/Operations/Campaign Closure.

Glocal C.				
Service Number	57J3			
Damage Code	0099			
Parts Vendor Code	wwo			
Claim Type	Sold vehicle: 7	10		
	Unsold vehicle: 7 90			
Causal Indicator	Mark labor as causal			
Vehicle Wash/Loaner	Do not claim wash/loaner under this action			
	<u>U.S.A.:</u> Loaner/rental coverage cannot be claimed under this action. However, loaner/rental may be covered under the Alternate Transportation Program. Please refer to the Volkswagen Warranty Policy and Procedures Manual for loaner claims information and reimbursement details.			
	<u>Canada:</u> Loaner/rental coverage cannot be claimed under this action. Please refer to the Volkswagen Service Loaner Program to determine loaner eligibility.			
Criteria I.D.	01			
	Remove all four door panels, door component supports, and apply cavity wax			
	LABOR			
	Labor Op	Time Units	Description	
	5729 76 99	230 TU	Remove door component supports and apply cavity wax	
	2706 89 50	10	Connect battery charger (if necessary)	
	0150 00 00	Time stated on diagnostic protocol	GFF operations for clearing faults (if necessary)	
			PARTS	
	Quantity	Part Number	PARTS Description	
	Quantity 0.15			

October, 2023 57J3 Page 5 of 7

Release Date

10/12/2023

Technical Service Bulletin

57J3 UPDATE

Door Seam Cavity Sealing – (NVLW)



Additional Actions Some of the affected vehicles may be involved in additional Actions. Please check your

ELSA Campaign/Action Information screen so that any additional required work can be

done simultaneously.

Verifying Vehicle Eligibility To verify vehicle eligibility for this Update, *always* check the ELSA Campaign/Action Information screen. The ELSA system is the *only* binding inquiry and verification system;

other systems are not valid and may result in non-payment of a claim.

Help for Claim Entry For questions regarding claim entry, contact Volkswagen Warranty.

Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

Required
Customer
Notification

October, 2023 57J3 Page 6 of 7

Release Date

10/12/2023

Technical Service Bulletin

57J3 UPDATE

Door Seam Cavity Sealing – (NVLW)



Required Parts

Parts Control Type:	Parts will be managed with a weekly Upper Order Limit. Please see Parts On
Upper Order Limit (UOL)	Command (POC) for your Upper Order Limit quantity.

Initial Allocation:	Please reference the Repair Projection Tool (below) to view your potential VIN population.			

Criteria	Quantity	Part Number	P.O.C. Part Description	Ordering Method
01	60 ml	D -329-215-M2	PRESERV.	UOL

! NOTE

Campaign parts should always be ordered as per the parts information in this circular. The ordering system will supersede the part, if applicable.

• Properly store (retain), destroy or dispose of removed parts in accordance with all state/province and local requirements, unless otherwise indicated and/or requested through the Warranty Parts Portal (WPP) for U.S. and the Part Destruction and Core Disposition Report for Canada.

Additional Information

All parts and service references provided in this Update are subject to change and/or removal. Always check ELSA for the most current version of this document.

October, 2023 57J3 Page 7 of 7