



Technical Service Bulletin

91 Park assist plus: currently unavailable message displayed in the MMI while located in NY, VT or Puerto Rico

91 23 41 2066110/3 October 31, 2023. Supersedes Technical Service Bulletin Group 91 number 23-12 dated July 7, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 – 2024	All	Park Assist Plus
e-tron quattro, e-tron Sportback quattro, and e-tron S	2023		
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron GT, RS e-tron GT, Q7, SQ7, Q8, SQ8, and RS Q8	2023 - 2024		

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Added Models/Model Years) Revised <i>Service</i> (Added instructions for MY24 Q8 vehicles)
2	07/07/2023	Revised title (Added Puerto Rico) Revised header (Added MY23/24 vehicles with park assist plus) Revised <i>Technical Background</i> (Added Puerto Rico)
1	03/04/2022	Initial publication

Customer states:

- The park assist plus system does not activate when pushing the park assist plus button.



Figure 1 : Park assist plus button



Technical Service Bulletin

- The message “Park assist plus: currently unavailable” is displayed on the MMI screen.



Figure 1: Park assist plus: currently unavailable message

Workshop findings:

- No relevant DTCs are stored.

Technical Background

Prior to MY24, park assist plus was geofenced to be unavailable if the vehicle is physically located in one of the following states/territories:

- New York
- Vermont
- Puerto Rico

Production Solution

Not applicable.

Service

For all MY22 and MY23 vehicles with Park Assist Plus (PR number FT1/FT3) located in NY, VT, PR, as well as all MY24 with Park Assist Plus (PR number FT1/FT3) in PR:

No repair is available at this time as the vehicle is operating as designed.

1. Do not perform any repairs. Any repairs for this concern may be denied.
2. Instruct the customer that this condition is normal.

For MY24 Audi Q8 e-tron

1. In ODIS, select “guided functions” for control module 00A5 - Front Sensor for Driver Assistant Systems.
2. Select the option “Check control module configuration” then execute and complete that test plan. This test plan writes a new control module configuration to the vehicle which disables the geofence for NY and VT.



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2066110**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.