Service Alert

Mazda North American Operations Irvine, CA 92618-2922



Subject:

CONNECTED VEHICLE SYMPTOM TROUBLESHOOTING

Service Alert No.: SA-009/23

Last Issued: 10/23/2023

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:			
SA-009/23	08/28/23, 08/15/23, 07/05/23, 06/12/23, 05/24/23, 04/25/23, 03/28/23, 03/01/23 and 02/06/23			
SA-017/22	12/13/22, 10/10/22, 08/25/22, 05/06/22, 04/04/22			
SA-013/21	12/22/21, 10/13/21, 09/14/21, 05/11/21, 04/27/21, 03/15/21, 02/22/21, 02/08/21 and 02/02/2021			
SA-031/20	12/09/20,11/30/20, 11/06/20, 10/28/20, 06/16/20, 06/05/20, 06/01/20, 05/18/20, 04/14/2020, 04/02/20, 03/11/20 and 02/27/20			

APPLICABLE MODEL(S)/VINS:

2019-2024 Mazda3

2020-2024 CX-30

2021-2024 CX-5

2021-2023 CX-9

2022-2023 MX-30

2023-2024 CX-50

2024 CX-90

DESCRIPTION

Some customers may complain about any of the following:


- 1. Infotainment Center Display does not provide the Authorization Code (OTP) during the MyMazda App Connected Vehicle enrollment.
- 2. Remote function(s) inoperative.
 - Engine Start / Stop
 - Door Lock / Unlock
 - Lights ON / OFF
- 3. MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".

Page 1 of 40


Index

- MAZDA CONNECT Indication
- Remote Engine Start Will Not Function
- · Remote Engine Start Function Will turn engine OFF
- · Deactivation Mode

MAZDA CONNECT Indication



Page 2 of 40



Page 3 of 40

Remote Engine Start Will Not Function under the following conditions

Item	ote Engine Start <u>Will Not</u> Function under the following conditions Condition		
1	Remote Engine Start function is not available on PHEV (inline 4) models. See SA-038/23		
2	Vehicle battery voltage low		
3	Automatic Transmission shift position except "P"		
4	Vehicles equipped with manual transmission		
5	Vehicle speed above 3 mi/h (5 km/h)		
6	Brake pedal switch malfunction		
7	Engine has been running by remote engine start function		
8	Engine started by remote engine start more than 2 consecutive times while the vehicle is not driven. The vehicle must be driven 1-mile or 24-hours must pass from the last successful Remote Engine Start for the use count to reset.		
9	2021 Mazda3, 2021 CX-30, CX-50, MX-30: Vehicle's electrical control area network (CAN) is in "Sleep Mode" Low Battery Risk Start Vehicle to Charge 12V Battery Or A registered key is detected in the vehicle		
==	A registered key is detected in the vehicle		
11	Brake pedal switch detects brake application Low fuel warning		
12			
	Engine starts, then turns OFF due to abnormal high engine rpm detected. (Engine rotation ov 3000 rpm continued for more than 0.2[s])		
	No engine rpm detected after sending engine start request. (Engine rotation 0 rpm continued for more than 0.2[s])		
15	When the CAN data signal for engine shut off is present (e.g.: door ajar signal)		
16	After 10 second maximum cranking time		
17	Burglar alarm status is "Alarm" and "Alarm stand by" (CAUTION - DO NOT enable, see Theft- Deterrent System section in SA-012/20)		
18	Room fuse blown/missing		
19	Connected Vehicle Maintenance Mode enabled (Restricted Transmitting Mode in MDARS)		

Page 4 of 40



Vehicle is parked (stored) for approximately 1 week or longer or in deep sleep mode. Drive the vehicle for a few miles to recover.

DTC Stored

21



22 Aftermarket Remote Engine Start accessory installed.

Mazda Remote Engine Start (BCKA-V7-620) accessory installed (No MyMazda app remote engine start function).

- 23 Mazda Remote Engine Start (RES) Removal
 - a. Remove the Mazda Remote Engine Start (RES) accessory module.
 - b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)]
- First remote control attempt fails, second attempt works fine. Go to TSB 16-002/20.
- 25 CSP04 Status Open

Remote Engine Start Function Will turn engine OFF under the following conditions

Item	Condition	
1	Vehicle door(s) opened	
2	Vehicle trunk opened	
3	Vehicle hood opened	
4	Ignition switch push button "ON" detected	
5	Remote engine STOP request	
6	Brake pedal switch detects brake application	
7	DTC Stored	
8	Engine will stop running automatically after 15 minutes for safety, security and emissions.	

Page 5 of 40


Deactivation Mode

- Deactivation Mode Temporary Suspension 6/16/2023 (6/11/2023 retail date and later)
- Vehicles retailed before 6/11/2023 and in Deactivation Mode will remain in Deactivation mode.


NOTE:

- Customer/Dealer can activate CV services anytime via MyMazda app
 - Customer There might be a slight delay in making the backend connection since it was temporarily deactivated.
 - Dealer Go to Repair Procedure -> TCU Activation
- When TCU is in Deactivation Mode, infotainment Over-the-Air (OTA) Connectivity Master Unit (CMU) software update is not possible (disabled).
- Prior to Retail Date, the TCU is active.


Deactivation Mode Status Check:



Page 6 of 40



Page 7 of 40



REPAIR PROCEDURE

CAUTION: DO NOT swap TCU with another vehicle as the TCU is VIN locked after activation. A TCU swap with another vehicle will disable Connected Services on both vehicles.

PREPARATION:

- 1. Confirm that the Telematics Communication Unit (TCU) is at the latest software level. Go to Telematics Communication Unit (TCU) Updates
 - Mazda3 built before July 1, 2021
 - 104603 _ or later (Verizon)
 - Mazda3 built after July 1, 2021
 - 10007 or later (AT&T)
 - CX-30 built before July 1, 2021
 - 304603_ _ or later (Verizon)
 - CX-30 built after July 1, 2021
 - 10007 or later (AT&T)
 - CX-5 10024 or later
 - CX-9 10024 or later
 - MX-30: 10020 or later
 - CX-50: 10004 or later
- 2. Go to eMDCS Vehicle Inquiry and confirm the following campains are not shown or closed:
 - CSP06
 - CSP07

Page 8 of 40

Last Issued : 10/23/2023

SSPC7

Service Alert No.: SA-009/23

- DRW41
- 3. Go to eMDCS Vehicle Inquiry and confirm CSP04 is not shown.
- 4. In most cases, the customer will not leave their device with you for troubleshooting, therefore a connected vehicle take-over is necessary. Use your personal device or dealer supplied device for troubleshooting. Go to **Enrollment**.
 - At customer pick-up, inform customer to re-enroll into Connected Services as a new primary user.
- 5. Confirm the customer's phone and vehicle have good to strong reception during the concern as shown in the table below.



• If the reception icon shows "X", the TCU is deactivated. Enrollment is not possible. Go to TCU Activation.



- · Customer/Dealer can activate CV services anytime via MyMazda app
 - Customer There might be a slight delay in making the backend connection since it was temporarily deactivated.
 - Dealer Go to TCU Activation
- If the reception icon shows "\", move the vehicle to an area with a clear view of the sky.



- If the reception is weak, move the vehicle to a location where the reception is good to strong as shown in the table, then try to get the Authorization Code and/or operate the remote functions before proceeding to the Repair Procedure if there is still an issue.
- If the reception is good to strong, proceed to Connected Vehicle Troubleshooting below.

NOTE: Vehicles stored for long periods may loose GPS clock sychronization. If the vehicle is stored for a long

Page 9 of 40


period, test drive the vehicle to give the GPS clock time to sychronize before enrolling or testing connected vehicle functions.

Index

- 1. Unable to create a MyMazda account
- 2. Remote function(s) inoperative
- 3. No One Time Pass Code (OTP)
- 4. Connected vehicle reception strength icon shows "X" or "\"
- 5. MyMazda App displays incorrect tire pressures (Except CX-5 and CX-9)
- 6. Unable to activate Connected Services (2019 Mazda3)
- 7. Software Update Error (2020 Mazda3)
- 8. Functions inoperative (2021-> CX-30, CX-50, Mazda3 and MX-30)
- 9. First remote control attempt fails, second attempt works fine
- 10. Engine turns off when opening door
- 11. Low Tire pressure will not clear after correcting tire pressue
- 12. MyMazda App does not display tire air pressures (CX-5, CX-9)
 - MCVV One Time Passcode (OTP) Troubleshooting
 - TCU Activation
 - Educational Videos
 - Resources

	Connected Vehicle Troubleshooting			
	Symptom	Cause	Action	
1	MyMazda App - Internal Usher SDK error.	Customer	1. Text "Start" to 1-949 518-0058 (Twilio SMS for Mazda) 2. Retry to create a MyMazda account. NOTE: USA and Canada only 1 (949) 518-0058 Start You have successfully been resubscribed to messages from this number. Reply HELP for help. Reply STOP to unsubscribe. Msg&Data Rates May Apply.	

Page 10 of 40



Page 11 of 40

Screen Tap the Detail Tap the push alert card Tap "check notification vehicle status" Go to the MyMazda App INBOX -> ACTIVITY HISTORY -> to view reason for remote function failure. 2021 MAZDA3 2.5 S PF FWD **Activity History** Go to eMDCS Vehicle Inquiry and confirm the following campains are not shown or closed: CSP06 Campain Status CSP07 SSPC7 **DRW41** 1. Use MDARS to ID the vehicle and check for DTC's stored. Are DTC(s) stored? Yes - Go to MGSS and perform normal DTC diagnostics. · No - Go to next step. 2. Confirm TCU software version is at the following using TCU Software Version Check Mazda3 built before July 1, 2021 Troubleshooting 104603_ or later (Verizon) needed Mazda3 built after July 1, 2021 10007 or later (AT&T) CX-30 built before July 1, 2021 304603 or later (Verizon) CX-30 built after July 1, 2021 10007 or later (AT&T) • CX-5 - 10024 or later CX-9 - 10024 or later MX-30: 10020 or later CX-50: 10004 or later

Last Issued: 10/23/2023

Service Alert No.: SA-009/23

Page 12 of 40

Service Alert No.: SA-009/23	Last Issued : 10/23/2023
------------------------------	--------------------------

	 3. Disconnect battery for 30 seconds and then reconnect (KAM reset). NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to sychronize before retrying Authorization Code. 4. Perform one of the following: Customer: Un-enroll Connected Services, then re-enroll into Connected Services as a new primary user. Dealer: Perform customer take-over enrollment for test confirmation, then at customer pick-up, inform customer to re-enroll into Connected Services as a new primary user. 5. Contact Hotline for additional technical support if needed.
Only a single remote request can be made per 60-second period	Customer needs to wait 60 seconds for the initial request cycle to be completed to make the second request.
Remote Transmitter Key(s) in the vehicle	Do not leave keys in vehicle.
Aftermarket Remote Engine Start accessory installed. Mazda	Remove the aftermarket accessory. The customer can use either the Mazda Remote Engine Start accessory or the MyMazda app function. Cannot use both.
Remote Engine Start (BCKA- V7-620) accessory installed.	Mazda Remote Engine Start (RES) Removal a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)].
TCU in "deep sleep" mode due to vehicle being parked for a long period.	ů ů
Low fuel	Advise customer that Remote Engine Start may start vehicle temporarily, but vehicle will turn off automatically when the fuel level is low to conserve the remaining fuel.
Vehicle is	Advise customer that vehicles with a manual

Page 13 of 40

		Manual Transmission	transmission do not have the Remote Engine Start/ Stop function capability.	
		Engine started with key transmitter instead of MyMazda App.	Advise customer they will see an error message when attempting to make a Remote Engine Off request if they initially turned on vehicle with a physical key (instead of through their MyMazda app).	
		MyMazda App Enrollment Preparation 1. Create a MyMazda account. 2. Complete any "OPEN" Recalls / Special Service Programs. Go to MGSS -> warranty Veh. Inq. 3. Update the Telematics Communication Unit (TCU) to the latest software version. Go to MGSS -> Telematics Communication Unit (TCU) Updates.		
3	No One Time Passcode (OTP) (Vehicle infotainment center display	 Mazda3 built before July 1, 2021 104603_ or later (Verizon) Mazda3 built after July 1, 2021 10007 or later (AT&T) CX-30 built before July 1, 2021 304603_ or later (Verizon) CX-30 built after July 1, 2021 10007 or later (AT&T) CX-5 - 10024 or later CX-9 - 10024 or later MX-30: 10020 or later CX-50: 10004 or later 		
3	does not provide the Authorization Code during the MyMazda App enrollment)	the latest softwa 5. Check TCU ao a. Go to N	only - Update the Connectivity Master Unit (CMU) to re version. Go to MGSS -> MAZDA CONNECT Updates ctivation status. MAZDA CONNECT home screen. Entertainment	
		• FM • AN		
		d. Check the Connected Vehicle reception strength in		

Page **14** of **40**

to Enrollment.

 Reception strength icon shows normal strength.
 The TCU is active and ready for enrollment. Go Reception strength icon shows "X". The TCU is deactivated. Enrollment is not possible. Go to TCU Activation.

Note: Use MCVV to check OTP status. Go to Mazda Connected Vehicle Viewer (MCVV) One Time Passcode (OTP) Troubleshooting

> Reception strength icon shows "\". Move the vehicle to an area with a clear view of the sky.





Enrollment

1. After registering for a MyMazda account, the Select Vehicle screen will lappear, Tap "Add Vehicle" and follow the onscreen instructions to add your vehicle. 2. To enroll in Connected Services, tap "Enroll" on the "My Vehicles" screen. 3. On the Connected Services Enrollment screen, tap

Start to begin the enrollment process.




Page 15 of 40

4. Switch the ignition ON in your Mazda vehicle.
5. Wait 30 seconds.
6. Tap Next.




7. Tap Request to receive authorization code on your vehicle's Mazda Connect center display.

Wait a few minutes for the infotainment center display to show the Authorization Code.



8. After a few minutes, the infotainment center display will show the Authorization Code. Enter the authorization code in the

Page **16** of **40**



Page 17 of 40

		No - Perform ODR Data Collection Procedure, then go to step 2.
		Confirm TCU software version is at the following using TCU Software Version Check.
		 Mazda3 built before July 1, 2021 104603 or later (Verizon) Mazda3 built after July 1, 2021 10007 or later (AT&T) CX-30 built before July 1, 2021 304603 or later (Verizon) CX-30 built after July 1, 2021 10007 or later (AT&T) CX-5 - 10024 or later CX-9 - 10024 or later CX-9 - 10020 or later CX-50: 10004 or later CX-50: 10004 or later A Retrieve MAZDA CONNECT CMU log data. Go to MGSS -> Infotainment -> MAZDA CONNECT CMU Data Retrieval Perform "Activating Remote Control by Smart Phone" (links TCU to BCM) Clear DTC(s). NOTE: If DTC 2050:55 is stored, go to SA-003/20 to clear DTC. Check TCU Remote Service Flag Information
		 Remote Service Flag Information 1101 go to step 8. Remote Service Flag Information 0000 go to step 9.
		8. Disconnect 12V battery for 5-10 minutes, then retry connected vehicle enrollment. NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to sychronize before retrying Authorization Code. 9. Contact Hotline for additional technical support if needed.
4	MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\". Mazda3, CX-30, CX-50, MX-30	Customer/Dealer can activate CV services anytime via MyMazda app • Customer - There might be a slight delay in making the backend connection since it was

Last Issued: 10/23/2023

Service Alert No.: SA-009/23

Page 18 of 40

temporarily deactivated. Dealer - Go to TCU Activation Go to eMDCS Vehicle Inquiry and confirm the following CX-5, CX-9 campains are not shown or closed: CSP06 Campain Status CSP07 SSPC7 DRW41 Go to eMDCS Vehicle Inquiry. Does eMDCS show Customer CSP04 status closed? deactivate Connected Yes - Customer opt-out. No action needed. Services (Opt- No - CSP04 is not shown. Go to next Action Out)) below. 1. Check for DTCs. Are there any DTC's stored? Yes: Go to MGSS for normal DTC diagnosis. No: Go to next step. Confirm TCU software version is at the following using TCU Software Version Check. Mazda3 built before July 1, 2021 104603_ _ or later (Verizon) Mazda3 built after July 1, 2021 10007 or later (AT&T) CX-30 built before July 1, 2021 304603_ _ or later (Verizon) CX-30 built after July 1, 2021 No reception 10007 or later (AT&T) CX-5 - 10024 or later CX-9 - 10024 or later MX-30: 10020 or later CX-50: 10004 or later 3. 2019 Mazda3 Only - Confirm CMU software version is at 11012 or later. 4. Disconnect battery terminal for 5-10 minutes, then test drive the vehicle. Is the reception strength signal normal? · Yes: Repair complete. · No: Go to next step.

Last Issued: 10/23/2023

Service Alert No.: SA-009/23

Page 19 of 40

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

5. Perform TCU activation. Go to SA-004/21. Is the

reception strength signal normal? · Yes: Repair complete. · No: Go to next step. 6. Compare Tel antenna No. 1 signal strength with good known vehicle near by. Go to DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)] Functional Inspection / Adjustment -> Navigation System Inspection Good - Contact Hotline for technical support No Good - Swap Tel antenna No. 1 with known good vehicle Except CX-5 and CX-9 MAZDA CONNECT and/or MyMazda App displays incorrect tire pressures after battery disconnect and/or infotainment CMU software update. Incorrect calendar entry (month/day/ year) after a battery Go to SA-002/21 5 disconnect or linfotainment system software update. 2019 Mazda3 only Improper 6 telematics Go to CSP07 Repair instructions. communication

Last Issued: 10/23/2023

Service Alert No.: SA-009/23

Page 20 of 40


unit (TCU) The customer is not able to software. activate Connected Services via the MyMazda app after CSP06 completion. MAZDA CONNECT connected vehicle reception strength icon is missing or shows unsubscribed after CSP06 completion. 2020 Mazda3 only Infotainment center display does not provide the Authorization Code Infotainment center display "Software Update Error" message Enrollment error Go to SSPC1 2021 Mazda3, CX-30, CX-50, and MX-30 functions inoperative Vehicle's or Vehicle Status Alert electrical control · Remote Engine Start / Stop 8 area network · Remote Door Lock / Unlock (CAN) is in Remote Hazard Lights ON / OFF "Sleep Mode" · Vehicle Finder (vehicle location mapping function is available) No dealer visit is required. Sleep Mode can be reset by starting the engine and idling or driving for 5 minutes or longer.

Last Issued: 10/23/2023


Service Alert No.: SA-009/23

Page **21** of **40**


			Go to 09-010/22.
9	First remote control attempt fails, second attempt works fine. • Engine Start / Stop • Door Lock / Unlock • Lights ON / OFF	Improper telematics communication unit (TCU) software.	Go to TSB 16-002/20.
10	Engine turns off when customer opens vehicle door.	Normal Operation	Advise that, for customer's safety and security, vehicle is designed to shut-off automatically when the vehicle door is opened.
11	 Low Tire pressure will not clear after correcting tire pressue. Vehicle status is inaccurate. 	MyMazda App is not real time.	Customer must go to MyMazda app's Inbox and read/open all the messages related to the low tire pressure alert, then the "Low tire pressure" alert will clear from MyMazda app's Health Report Message will clear after next drive cycle.
12	CX-5, CX-9 The MyMazda App does not display tire air pressures SOURCE STATUS DOORS CHARACTER COURSE COU	CX-5 and CX-9 Normal Operation	No action Needed



Page 22 of 40




Page 23 of 40




TCU Activation


Page 24 of 40




Page 25 of 40




Page 26 of 40




Page 27 of 40



Page 28 of 40



Page 29 of 40



Page **30** of **40**

매 중 86

13. Agree to the Terms & Conditions, then select

"AGREE"

Connectivity Privacy Policy

Mazzla collects and processes

Connectivity Privacy Policy

Mazzla collection and use of data, inc

collection, use, and disclosure


location data, as described in

Connectivity Privacy Policy


DECLINE

10:02

14. You will see a message stating "Activation Process in Progress", Select "CLOSE"



Page **31** of **40**



Page **32** of **40**

 Reception strength icon shows "X". TCU activation is still processing. Repeat steps 16 -18

Note:


- This step may need to be repeated a few times until normal strength is shown.
- If steps 16-18 was repeated several times with no change, disconnect 12V battery for 5-10 minutes, then recheck reception strength icon.




ODR Data Collection Procedure



Page **33** of **40**




Page **34** of **40**



Activating Remote Control by Smart Phone (links TCU to BCM)

NOTE: This procedure cannot be performed if the key transmitter power saving function is enabled. See SA-040/20.


Page **35** of **40**



2. Use MDARS to verify if the Telematics Control Unit (TCU) is at the latest software level (Toolbox > Software Update > Run > TCU).

Is the TCU at the latest software level?

- Yes: Go to step 3.
- No: Update TCU software, then go to step 3.
- 3. Select the following:
- a. Toolbox
- b. Repair icon
- c. MAZDA CONNECT
- d. Activating Remote Control by Smart Phone
- e. RUN.




4. Follow the on-screen instructions and wait for process to complete.

NOTE: If the Activating Remote Control by Smart Phone shows "Incomplete", the possible causes are:

- a. The advanced key is not in the vehicle.
- b. The connected Vehicle Maintenance Mode is enabled.
- c. The Key transmitter power saving function is enabled.

Page 36 of 40



TCU Software Version Check

1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/Service Inspection screen will appear.

CX-5 and CX-9

Except CX-5 and CX-9

Page **37** of **40**

Diagnostic Test Functional Inspection/Adjustment Select Service Information. Service Information Device Program Update End Diag Mode Connected Device Information Backup Restore Select TCU Linked information. Personal Information Deletion **TCU Linked Information** Scroll down to TCU Software Version and confirm the software version is at: Mazda3 built before July 1, 2021 104603_ _ or later (Verizon) Mazda3 built after July 1, 2021 10007 or later (AT&T) CX-30 built before July 1, 2021 CMU Chip Serial No. AEALEOAMFI 304603_ _ or later (Verizon) TCU TEL Number 5256201320 CX-30 built after July 1, 2021 10007 or later (AT&T) TCU MFID 35769109957232 : 00010020 (CX-5, CX-9) • CX-5 - 10024 or later **TCU Software Version** : 00010004 (Mazda3, CX-30) CX-9 - 10024 or later Connection Server Public Server MX-30: 10020 or later CX-50: 10004 or later Flag Information Is the TCU software version correct?

Last Issued: 10/23/2023

Service Alert No.: SA-009/23


· Yes: TCU Software Version Check is

Page 38 of 40


complete.

 No: Go to Telematics Communication Unit (TCU) Updates to update the TCU software version.

TCU Remote Service Flag Information Check



Page **39** of **40**



Educational Videos

Overview
Using MyMazda App
In-car Wi-Fi hotspot
MyMazda remote
Notifications
Saftey features

Resources

SA-015/23 - MAZDA CONNECTED SERVICES - FREQUENTLY ASKED QUESTIONS (FAQ)

Connected Services Owner's Manual

MAZDA CONNECT and MAZDA CONNECTED SERVICES USER GUIDE

MAZDA CONNECTED VEHICLE VIEWER (MCVV) USER GUIDE

MAZDA CONNECT ESSENTIALS (30076WBT)

MAZDA CONNECT & CONNECTED SERVICES FOCAL POINT (30093FOC)

MAZDA CONNECTED SERVICES SMART CARDS

MAZDA CONNECTED SERVICES: CUSTOMER OUTREACH