



Technical Service Bulletin

| | |
|--------------|-----------------------|
| GROUP | NUMBER |
| CAMPAIGN | 23-01-073H-1 |
| DATE | MODEL(S) |
| October 2023 | KONA ELECTRIC (OS EV) |

SUBJECT: KONA EV DTC INSPECTION AND BMS UPDATE (SERVICE CAMPAIGN 9A4)

This TSB supersedes TSB 23-01-073H with updated part tables for 19-20 MY vehicles.

* IMPORTANT

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair. Access the "Vehicle Information" screen via WEBDCS to identify open campaigns.

Description: Certain 19-23MY Kona Electric (OS EV) vehicles may experience a condition of EV warning light ON with DTC P1AA6 to P1AAF found stored. The Battery Management System (BMS) software update will be performed to enhance battery diagnostics logic.

Flowchart summary of the service procedure is provided on page 2 summarized as follows:

- Vehicles that do not have EV Warning Light On will only need the BMS software update.
- Certain vehicles incurring EV Warning Light On and DTC P1AA6 found stored with Freeze Frame Data Information Code 1=128 will only require the BMS Update.
- Certain other DTC P1AA6 Information Code 1-2 values or DTC P1AA7 to P1AAF will require the Battery System Assembly (BSA) to be replaced and then the BMS Update to be performed.

Applicable Vehicles (Certain):

- 2019-23MY Kona Electric (OS EV) produced from 8/28/2018 to 3/8/2023

GDS Information:

| System | Event # | Description |
|--------|---------|-----------------------------------|
| BMS | 999* | OS EV NEW LOGIC (RDV) BMS UPGRADE |

* or select the latest available Event # that displays in GDS.

Warranty Information:

| MODEL | OP CODE | OP NAME | CAUSAL PART | OP TIME | NATURE | CAUSE |
|-----------------------|----------------------------|---|----------------------------|----------------------------|--------|-------|
| Kona Electric (OS EV) | 30D055R1 | DTC (INFO CODE) CHECK AND BATTERY MANAGEMENT SYSTEM SOFTWARE UPDATE | 375A0-K4000 | 0.4 M/H | I3A | ZZ3 |
| | <i>Refer to pages 9-10</i> | BSA REPLACE | <i>Refer to Pages 9-10</i> | <i>Refer to pages 9-10</i> | | |

NOTE 1: The BMS software update and if necessary BSA replace are to be submitted on the Claim Entry Screen as "Campaign" type.

NOTE 2: If a part is found in need of replacement while performing this campaign and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing work.

NOTE 3: This TSB includes Repair validation photos. Op times including VIN, Mileage, and Repair validation photos as outlined in the Digital Documentation Policy.

NOTE 4: Each BSA replacement labor op code will include reimbursement for bolts, washers, and coolant. Please refer to TSB 23-EV-001H parts information chart for the applicable part numbers.'

Service Procedure:

STUI




This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

Table Of Contents:

| Section | Pages | Description |
|----------|-------|---------------------------------|
| A | 4-5 | DTC CHECK |
| B | 6-8 | BMS SOFTWARE UPDATE |
| C | 8-10 | BSA REPLACE (only when applies) |

Summary of Service Procedure Flow:



A. DTC CHECK

- A1. Perform BMS system Fault Search by GDS.
- A2. Check for any of **DTC P1AA6, P1AA7, P1AA8, P1AA9, P1AAA, P1AAB, P1AAC, P1AAD, P1AAE or P1AAF** found stored as an active or history DTC?
 - **No – (None of the above listed DTC are found stored):**
Go to section B - Perform BMS Software Update.
 - **Yes – (DTC P1AA6 is found stored):**
Go to next step A3. - Check the DTC P1AA6 Freeze Frame Information Code 1-2 values to determine next steps.
 - **Yes – (Any of DTC P1AA7, P1AA8, P1AA9, P1AAA, P1AAB, P1AAC, P1AAD, P1AAE or P1AAF are found stored):**
Go to section C. - Take STUI photo of Freeze Frame Data, Replace BSA and perform BMS Update if needed.
- A3. Check the DTC P1AA6 Freeze Frame Data and locate **Information Code1-2:**

| ■ DTC CAUSE TO SYSTEM ERROR : P1AA600 | | |
|---------------------------------------|---------------|------|
| Sensor Name | Value | Unit |
| MCU Controllable | NO | - |
| VCU Ready | YES | - |
| VCU Main Relay Off Request | NO | - |
| VCU EV Ready | NO | - |
| FATC Main Relay Off Request | NO | - |
| Accumulative Operating Time | 96397 | Sec |
| Information Code1 | 2 | No. |
| Information Code2 | 0 | No. |
| Information Code3 | 132 | No. |
| Information Code4 | 1 | No. |
| Quick Charge Relay ON Status | NO | - |
| Charging Lamp Status | Charging Fail | - |
| OPD Active ON | OFF | - |
| Winter Mode Status | OFF | - |
| Information Code5 | 0 | No. |
| Information Code6 | 6 | No. |
| Quick Charge Outlet Temperature | 24 | °C |
| Battery WCS Inlet Temperature | 24 | °C |
| Battery Master Temperature | 24 | °C |

A4. Find the **DTC** in the chart below,

..... then if **DTC P1AA6** also check the **Information Codes1-2** values,

..... then find the corresponding value in the last column **“BSA Replace?”**:

- **“BSA Replace?” = NO – Go to section B.** (BMS Update only)
- **“BSA Replace?” = YES – Go to section C.** (BSA Replace and BMS Update)
- **“BSA Replace?” = Techline Review** (Whether or not BSA is to be replaced will be decided after Techline review of the BMS Data with Engineering).

| Battery Incident Condition | Early BMS Software | | | Later BMS Software | BSA Replace? |
|--|--------------------|-------------|-------------|--------------------|---|
| | DTC | Info code 1 | Info code 2 | DTC | |
| Cell voltage deviation error | P1AA600 | 1 | - | P1AA700 | YES |
| Insulation resistance error | | 2 | - | P1AA800 | YES |
| Abnormal cell voltage change after charging | | 4~64 | - | P1AA900 | YES |
| Abnormal current change during charging (CV section) | | 128 | - | P1AAA00 | P1AA600- NO P1AAA00 *Techline review |
| Overtemperature | | - | 1 | P1AAB00 | YES |
| Overvoltage | | - | 2 | P1AAC00 | YES |
| Low voltage | | - | 4 | P1AAD00 | YES |
| Battery temperature deviation error | | - | 8 | P1AAE00 | YES |
| MAVD | | - | 16 | P1AAF00 | YES |
| RDV | | - | - | - | P1AB000 |

NOTE: *Techline review with Engineering to decide if BSA replace based on BMS data

B. BMS SOFTWARE UPDATE

B1.

WARNING

GDS Vehicle Battery Voltage:

- If the voltage is below 12 volts as per the GDS warning, then select **Back** and run the vehicle at least 20 minutes to reach an adequate battery state of charge to prevent an ECU Update failure. Cycle the ignition **OFF/ON** before retrying the ECU update again.




Information

GDS ECU Updates must be performed in Auto Mode.

- If ECU Update starts but then fails in Auto Mode, perform update in Manual Mode to recover.
- Turn off ignition for 30 seconds and try Manual Mode recovery.
- If unsuccessful, re-attempt Manual Mode after disconnecting the cables from the 12V battery terminals and performing cap discharge (connecting bar or heavy wire between "+" to "-" cables).


B2. Perform the BMS Update in Auto Mode.

Use the Auto Mode ID Check to verify the BMS ROM ID before updating the software.



- B3. After the ECU Upgrade process shows 100% complete, cycle the ignition key to OFF for at least 10 seconds to reset the control unit.
- B4. Take a screenshot of the ECU Update complete screen and upload to STUI.

STUI



Take a screenshot of the ECU Update Complete screen using your particular tablet's screenshot save method and upload to STUI.



ROM ID Information table:

| VEHICLE | SYSTEM | P/NO | ROM ID | |
|---------|--------|-------------|--|------|
| | | | OLD | NEW |
| OS EV | BMS | 375A0-K4052 | 6400 6500 6700 6730 6740 6770 6780 6790 6800 6820 6840 6860 6880 6900 | 6890 |
| | | 375A0-K4002 | 6402 6502 6702 6732 6742 6772 6782 6792 6802 6822 6842 6862 6882 6902 | 6892 |


| | | | | |
|--|--|-------------|--|------|
| | | 375A0-K4452 | 6504 6734 6744 6774 6784 6794 6804 6824 6844 6864 6884 6904 | 6894 |
| | | 375A0-K4402 | 6506 6736 6746 6776 6786 6796 6806 6826 6846 6866 6886 6906 | 6896 |
| | | 375A0-K4053 | 6960 6980 7020 7040 7050 7060 7080 7100 7120 | 7140 |
| | | 375A0-K4003 | 6962 6982 7022 7042 7052 7062 7082 7102 7122 | 7142 |
| | | 375A0-K4453 | 6964 6984 7024 7044 7054 7064 7084 7104 7124 | 7144 |
| | | 375A0-K4403 | 6966 6986 7026 7046 7056 7066 7086 7106 7126 | 7146 |

Manual Mode Password Information:


| MENU | PASSWORD |
|-----------------------|----------|
| OS EV BMS 375A0-K4052 | 5285 |
| OS EV BMS 375A0-K4002 | 0201 |
| OS EV BMS 375A0-K4452 | 2966 |
| OS EV BMS 375A0-K4402 | 2814 |
| OS EV BMS 375A0-K4053 | 9511 |
| OS EV BMS 375A0-K4003 | 3167 |
| OS EV BMS 375A0-K4453 | 3160 |
| OS EV BMS 375A0-K4403 | 0956 |

C. BATTERY SYSTEM ASSEMBLY (BSA) REPLACE (only when applicable)

C1. Take STUI photo of the DTC Freeze Frame data with the Information Codes 1-5 visible:

STUI 

Take a screenshot of the **DTC Freeze Frame Data showing Information Codes 1-5** using your particular tablet's screenshot save method and upload to STUI.



| DTC CAUSE TO SYSTEM ERROR : P1AA600 | | |
|-------------------------------------|---------------|------|
| Sensor Name | Value | Unit |
| MCU Controllable | NO | - |
| VCU Ready | YES | - |
| VCU Main Relay Off Request | NO | - |
| VCU EV Ready | NO | - |
| FATC Main Relay Off Request | NO | - |
| Accumulative Operating Time | 96397 | Sec |
| Information Code1 | 2 | No. |
| Information Code2 | 0 | No. |
| Information Code3 | 132 | No. |
| Information Code4 | 1 | No. |
| Quick Charge Relay ON Status | NO | - |
| Charging Lamp Status | Charging Fail | - |
| OPD Active ON | OFF | - |
| Winter Mode Status | OFF | - |
| Information Code5 | 0 | No. |
| Information Code6 | 6 | No. |
| Quick Charge Outlet Temperature | 24 | °C |
| Battery WCS Inlet Temperature | 24 | °C |
| Battery Master Temperature | 24 | °C |

- C2. Refer to TSB 23-EV-001H for the complete procedures for BSA Replace:
- Techline Approval (from inspection of Freeze Frame Data submitted via STUI)
 - PA Approval to allow for BSA Parts Ordering
 - Required Tools and Technician Training
 - BSA Replacement Procedures

C3. After BSA is replaced, go to Section B to perform BMS Update if it will apply.

BSA Parts Information:

| PART NAME | MODEL | PART NUMBER | REMARK |
|-------------------------------|-----------------------|---|--|
| BATTERY SYSTEM ASSEMBLY (BSA) | Kona Electric (OS EV) | 37501-K4xxxxx* (*as called out in Parts Catalog based on VIN) | Only as Needed per step A4. See TSB 23-EV-001H for BSA replace procedures including Techline and PA approval required. |

NOTE. Choose correct coolant and bolts P/N as indicated by TSB 23-EV-001H.

BSA Replace Warranty Information:

Follow these Instructions to choose the correct Opcode for BSA Replace:

1. **Choose the correct TABLE A vs TABLE B:**
 - a. **TABLE A – BSA REPLACE + BMS UPDATE**
 - b. **TABLE B – BSA REPLACE (No BMS Update)**
2. Then match your exact **BSA Part Number** received to the **CAUSAL PART** column to determine the **OP CODE** and **OP TIME**:

TABLE A - BSA Replace + BMS Update (NOTE: Must have STUI BMS Update complete photo uploaded)

| MODEL YEAR | MODEL | OP CODE | OP NAME | CAUSAL/ REPLACEMENT PART | OP TIME | NATURE | CAUSE | | | | |
|------------|-----------------------|----------|--|---|---------|--------|-------|--|-------------|-------------------------------|--|
| 19MY | Kona Electric (OS EV) | 30D055R2 | DTC (INFO CODE) CHECK, BSA REPLACEMENT , AND BATTERY MANAGEMENT SYSTEM SOFTWARE UPDATE | 37501-K4000AS | 3.6 M/H | I3A | ZZ3 | | | | |
| 20MY | | 30D055R8 | | 37501-K4001AS | | | | | | | |
| | | 30D055RF | | 37501-K4051AS | | | | | | | |
| | | 30D055RL | | 37501-K4051QQH | | | | | | | |
| 21-23MY | | 30D055RR | | 37501-K4004AS | | | | | | | |
| | | 30D055RT | | 37501-K4054AS | | | | | | | |
| | | 30D055RN | | 37501-K4005AS | | | | | | | |
| | | 30D055RP | | 37501-K4055AS | | | | | | | |
| | | | | 1. Campaign Claim 30D055R1 for the BMS Update. | | | | | 37501-K4005 | 0.4 + Refer to WebLTS for LTS | |
| | | | | 2. Claim additional Normal Warranty for BSA Replace – Refer to WebLTS for opcode. | | | | | 37501-K4055 | | |

TABLE B - BSA Replace (No BMS Update):

| MODEL YEAR | MODEL | OP CODE | OP NAME | CAUSAL/REPLACEMENT PART | OP TIME | NATURE | CAUSE |
|------------|-----------------------|--|---|-------------------------|---------|--------|-------|
| 19MY | Kona Electric (OS EV) | 30D055R3 | DTC (INFO CODE) CHECK AND BSA REPLACEMENT | 37501-K4000AS | 3.4 M/H | I3A | ZZ3 |
| 20MY | | 30D055R9 | | 37501-K4001AS | | | |
| | | 30D055RG | | 37501-K4051AS | | | |
| | | 30D055RM | | 37501-K4051QQH | | | |
| 21-23MY | | 30D055RS | | 37501-K4004AS | | | |
| | | 30D055RU | | 37501-K4054AS | | | |
| | | 30D055RO | | 37501-K4005AS | | | |
| | | 30D055RQ | | 37501-K4055AS | | | |
| | | Claim additional Normal Warranty for BSA Replace – Refer to WebLTS for opcode. | | 37501-K4005 | | | |
| | | 37501-K4055 | | | | | |