

Cause

Service Bulletin

Bulletin No.: 23-NA-181

Date: October, 2023

TECHNICAL

Subject: Excessive Brake Pedal Travel and/or Vehicle is Hard to Stop

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Express	2021	2023	_	_	_	_
GMC	Savana						

Involved Region or Country	North America		
Condition	Some customers may comment on having excessive brake pedal travel and/or the vehicle is hard to stop.		



6463220

The condition may be caused by the brake hose from the frame to the rear caliper is making contact with the tire, as shown in the picture above.



Correction

6463222

Rotate the brake line to the frame mounting bracket clockwise so the anti-rotation tab hits the top of the hole and the brake line is away from making contact with the tire, as shown in the picture above.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Refer to Rear Brake Hose Replacement in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information:

Labor Operation	Description	Labor Time			
2486338*	Rotate Brake Line on Frame Mounting Bracket	0.4 Hrs.			
*This is a unique Labor Operation for Bulletin use only.					

Version	1
Modified	Released October 16, 2023

