



Bulletin No.: PIP5942
Published date: 10/20/2023

Preliminary Information


PIP5942 Diagnostic Aid for possible Low Clamp Load of the Negative Battery Cable the Block


Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2023 - 2024	All	All	LM2	All
Chevrolet	Suburban	2023 - 2024	All	All	LM2	All
Chevrolet	Tahoe	2023 - 2024	All	All	LM2	All
GMC	Yukon	2023 - 2024	All	All	LM2	All
GMC	Yukon XL	2023 - 2024	All	All	LM2	All

Involved Region or Country:	North America
Condition:	Multiple electrical issues, including but not limited to no crank, stall, erratic operation of the engine and lights.
Cause:	You may find low clamp load on the negative battery ground cable at the engine block (NOT the nut over the engine mount), due to the nut bottoming out on the shoulder of the stud.





Version History

Version	1
Modified	10/20/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.